

Skoda Octavia

VIN code

TMBJG7NE2K0029855

Report generated: 2025-08-12 15:48

Valid: 155 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Skoda Octavia

 Gearbox
Manual

 First registration year
2018

 Fuel type
Diesel



Advertisements

 Sale ad records found for this vehicle



Mileage

 No inconsistencies found in mileage history



Thefts

 No records found



Traffic accidents / damages

 Vehicle damage records found



Photos

 Photos found

Technical data

(Original language)

Production date	2018-08-31
Model	OCT.COM AMB TD85/1.6 M5F
Series	OCT.COM
Type code	5E5354
Engine code	DGTE 4-cyl. turbo dies. eng. 1.6 l/85 kW 4V TDI common rail base engine is TJ1/TI7
Power	85
Fuel type	Diesel
Displacement	1.60
Drive type	FWD

Steering side	Left
Color	Brilliant Silver Metallic
Interior	Black
Transmission	manual
Transmission code	RTD

Equipment (Original language)

PKA0	Without camera systems/accident sensors
PKK3	Refrigerant R1234yf
PAV1	Driving on the right
PF0A	No special purpose vehicle, standard equipment
PQQ0	Without add. lights (interior lighting)
P5K7	Transport protection film (minimum protection) with additional transport protection measures
P2WA	Without additional tires
P0Y3	Cold zones
P3CA	Without partition
P3FA	Without roof insert (standard roof)
P4A3	Seat heater for front seats separately controlled
P3LD	Door and side trim panel
P4KC	Side and rear windows in heat-insulating glass
P0A2	4 doors
P1N3	Speed-related variable steering assist (Servotronic)
P0FA	Standard manufacturing sequence
P3L3	Manual height adjustment for front seats
P7W0	Without extended safety system
P5D1	Carrier frequency 433.92 MHz-434.42 MHz
P7X0	Without park distance control
P8WB	Front fog lights
P8Z5	Not hot country
P2JB	Standard bumpers
P3S2	Black roof rails
PG0C	5-speed manual transmission
PL04	Suspension range 04 installation control only, no requirement forecast
P2V1	Dust and pollen filter
P3H0	Without backrest release for front seats
P7Q0	Without navigation device
P1S1	Tool kit and jack
P8Y1	Two-tone horn

P8GU	Alternator 140 A
PQH0	Without voice control
PE0A	No special edition
PUG1	Hill hold control
PVF0	Standard pedal cluster
PVL0	Standard pedestrian protection measures
P1D0	Without trailer hitch
P0F5	Fuel system for diesel engine
P3W3	Special interior noise suppression
P1SA	Without additional front underbody guard
P0YF	Weight range 6 installation control only, no requirement forecast
P5J0	Without rear spoiler
P4P3	Rear floor panel module, type 4
P2W6	Fuel filler cap
P2B1	Additional exterior noise suppression
P7B2	12-volt socket in luggage boot
P8W1	Washer fluid level indicator
P6M0	Without tie down straps/net/pocket
P8N4	Windshield wiper intermittent control with potentiometer (four speeds)
P7M5	Without protective film for scuff plate
P8QL	Key for locking system with remote control
P9HA	Without additional malfunction display
P8RE	4 speakers (passive)
P6T0	Without interior light in footwell
P0N1	Standard rear axle
P0P0	Rear exhaust tailpipe (standard)
P1Q0	Without mass damper for steering wheel
P9U0	Without brake pad wear indicator
PJ0V	Battery 420 A (70 Ah)
PEL0	Without online service
PV1P	Tire suppliers for EU countries
P1Z2	Increase in initial standard fuel filling
P2A0	Without delivery equipment
P1W2	Glove compartment cooling system
P7QA	Without CD/DVD for navigation
P5C0	Without special body measures
P5TD	Decorative aluminum inserts
PHH7	Tires 205/55 R16 91V
PKD8	4-cyl. turbo dies. eng. 1.6 l/85 KW 4V TDI common rail base engine is TJ1/TI7

PND0	Without adapter
PEF0	Without ECO function
PFB0	Standard paint coating
PFM0	Basic equipment variant
PTJ1	4-cylinder diesel engine 1.6 l unit 04L.1
P7P4	Manually adjustable lumbar support in front seats
PA61	Category 1
PES0	Without vehicle inlet
PUH0	Parking brake
PUK1	Standard rear seat release
P9D0	Without preparation for two-way radio installation
P3D6	Center console
P0B3	Wheelbase
P3QM	3-point seat belts, front
P7G0	Without preparation for VTS (vehicle tracking system)
P7LM	Vehicle class differentiation -5E0-
PC28	Operating permit, alteration
P1PF	Standard wheel bolts
P9J0	Without supertone system and tone sequence control
P7CP	Emission standard EU6 AG/H/I
P0BA	Without rear stabilizer bar
P0EJ	Installation differentiation for transmission MQ 250 -- vehicle components --
P0KA	Without decals and emblems
P1EX	Special identification label for EC for M1 passenger vehicles
P1JA	Rear shock absorption, basic version 1
P1NL	Trims for alloy wheels
P3GA	Without luggage/load compartment floor
P4L2	Breakaway interior rearview mirror, dimming
P4X3	Side airbag in front with curtain airbag
P5RQ	Right exterior mirror, convex
P6XD	Exterior mirrors, power-adjustable/ heated
P7N2	Glasses storage
P8Q1	Headlight range control
P9M0	Without auxiliary heater/parking heater
PK8D	Wagon/Avant
PL0L	Left-hand drive
PQG1	LongLife Service Regime
PQV0	Without TV reception/digital radio reception
P6FF	Exterior mirror housings and various add-on parts in body color

P6PC	Hand brake lever handle in leather
P8X0	Without headlamp washer system
PA8C	Comfort equipment
PQ1A	Standard seats in front
P1G2	Steel spare wheel with original equipment tire
PPG0	Roof rails, black
PG01	Shock absorption in front
P1KD	Disc brakes in rear
P1X0	Front-wheel drive
P1ZF	Disc brakes in front (Geomet D)
P2H0	Without "drive select"
P3B4	Child seat anchors for child seat system ISOFIX
P3G0	Without child seat anchora in front (ISOFIX)
P3X0	Without load-through hatch
P3Y0	Without roll-up sunshade
P4K3	Remote central locking with 2 foldable keys (SAFE system)
P4R5	El. windows front
P8M1	Rear window wiper "AERO"
P9TC	Additional retro-reflectors (door area)
P0K0	Without alternative drive system
P0TD	Textile floor mats
P1AT	ESC
P1U8	Without folding table on front seat backrest
P1Y3	XDS+
P20A	Without electric motor (hybrid)
P3N2	Storage compartments with cover in trunkside panel
P3NU	Unsplit rear seat bench, split folding backrest, with center armrest
P3T2	Three rear head restraints
P4E2	Tailgate/trunk lid releaseckel hinten (electrically)
P4UP	Airbag on driver and front passenger side, knee airbag on driver/front pass. side, with front pass. airbag deactivat.
P5SJ	Left exterior mirror, convex
P5XB	Sun visors with mirror and airbag label on front passenger side
P5ZF	Front head restraints
P6E3	Front armrest "JUMBO BOX"
P6K0	Without forward collision warning/ autonomous emergency braking
P6N1	Rear mud flaps
P6Q2	Gearshift knob/handle in leather
P6SG	Luggage compartment floor covering "Comfort"

P7AS	Alarm with interior monitoring and towing protection, back up horn
P7E6	Additional el. heating
P7K1	Tire pressure monitoring system
P7L6	Green tec
P7Y0	Without lane change assist
P8G0	Without light control
P8S6	2 reading lights in front
P8T2	"CRUISE CONTROL"
P8TB	Rear fog lamp
P8ZH	Antenna for AM/FM reception, "diversity"
P9P5	Passenger seat-belt warning light (for all passengers)
P9S5	"MAXI DOT"
P9WC	Without "Multimedia" in vehicle
P9Z0	Operating voltage 12 V
P9ZV	Comfort telephony without exterior aerial
PCF3	Alloy wheels "ILIAS" 6,5J x 16" - 4 pcs.
PEM0	Without driver alert system
PER1	Regional code (Europe)
PGM1	Standard electronic engine sound
PKH6	Air conditioning
PQI6	Service indicator 30 000 km or 2 years (variable)
PQJ9	Chrome package
PQK0	Without multifunction camera
PQR8	Without dynamic road sign display
PU5A	Instrument cluster, km/h speedometer
P4GS	Heat-reflecting windshield
P9JA	Non-smoker's package
PB0A	Part set without country-specific prescriptive standard
P0AC	Front stabilizer bar
P3U2	Sliding luggage compartment cover
P8IE	H7 headlamps with LED separate daytime running lamps
P8SK	LED rear lights
P9T1	Heated winscreen washer nozzles
PN3C	Seat trim covers in fabric
PNZ0	Without call feature
PQE5	Storage compartment package 3
PUI5	External, USB type A, 1x USB socket
P8K1	Separate daytime running light
P1E9	Without activated carbon canister with SCR

PB72	Type approval country Lithuania
PX5G	Equipment options subset for Lithuania
P4ZC	Chrome package
P9E4	2 side lamps in luggage compartment (1 detachable)
P2SB	Labels in Polish, Estonian, Latvian, Lithuanian and Slovenian
PPJ1	Alloy wheels "ILIAS" 6,5J x 16" - 4 pcs
PI8C	Radio "SWING"
P2PV	3 spoke leather steering wheel
PPT2	BT comfort telephony
P0XR	Manual in Lithuanian
PPDA	Alarm with int. monitoring, back up horntowing protection +SAFE system

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2018



Service

2018-09 |  Lithuania

Performed tasks:

check_service



Service

2019-10 |  Lithuania | 11 044 km

Performed tasks:

oil_service



Service

2020-10 |  Lithuania | 23 308 km

Performed tasks:

oil_service

Filters



Service

2021-10 |  Lithuania | 32 745 km

Performed tasks:

oil_service

brake_service

check_service

unknown_service



Technical inspection

2021-10 |  Lithuania | 32 827 km

Technical inspection is valid until: 2023-10
Technical inspection type - periodic inspection:
Without faults.



Damage / repair assessment

2022-08 |  Lithuania

Damaged components:

Exterior body parts
Exterior lights



Damage / repair assessment

2023-01 |  Lithuania

Damaged components:

Exterior body parts
Structural elements of the body
Exterior lights



Technical inspection

2023-10 |  Lithuania | 46 132 km

Technical inspection is valid until: 2025-10
Technical inspection type - periodic inspection:
Without faults.



Sale or auction

2025-08 |  Lithuania | 56 090 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **2** records related to this vehicle:



Damage / repair assessment



Date

2022-08

Country:



Lithuania

Preliminary repair cost

€ 501 - € 1500 [i](#)

Damaged components:


Exterior body parts

Exterior lights

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage / repair assessment



Date

2023-01

Country:



Lithuania

Preliminary repair cost

€ 1501 - € 3000 

Damaged components:

Exterior body parts

Structural elements of the body

Exterior lights

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found **1** listings related to this vehicle:



ADVERTISEMENTS

The ad is inactive

Ad has been placed:

Country

Mileage

Seller:

Seller

2025-08

Lithuania

56 090 km


2025-08-12

private

identified

2025-08-12

Photos (21)





Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany