

Audi Q8

VIN code

WAUZZZF1XKD003773

Report generated: 2026-02-10 15:25

Valid: 357 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model

Audi Q8

 Gearbox

Automatic

 First registration year

2018

 Fuel type

Diesel



Mileage

 No inconsistencies found in mileage history, but not enough records found



Thefts

 No records found



Traffic accidents / damages

 Vehicle damage records found



Photos

 No photos found

Technical data

(Original language)

Production date

2018-07-13

Model

Q8 quat. TDI 3.0 V6210 A8

Series

Q8

Type code

4MN0L2

Engine code

DHXA 6-cyl. turbo diesel engine 3.0 l/210 kW V6 TDI common rail base engine is T7V/T2P

Power

210

Fuel type

Diesel

Displacement

3.00

Drive type

AWD

Steering side	Left
Color	Daytona Gray Pearlescent/Daytona Gray Pearlescent
Interior	Black-Black/Black-Black/Black/ Moon Silver
Transmission	automatic
Transmission code	SKV

Equipment

(Original language)

P3S2	Black roof rails
PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PE0A	No special edition
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PJ2D	Battery 380 A (68 Ah)
P0C0	Standard
PVF0	Standard pedal cluster
PS0C	Introductory volume
P0YJ	Weight range 9 installation control only, no requirement forecast
P0N1	Standard rear axle
P1S1	Tool kit and jack
P1T0	Without first aid kit and warning triangle
P1I0	Passenger presence detection
P0Y3	Cold zones
P1SA	Without additional front underbody guard
P3FA	Without roof insert (standard roof)
P1Z6	Increase in initial standard fuel filling
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 MHz
P7HA	Without leather
P8IT	LED headlamps
P8Z5	Not hot country
P7CP	Emission standard EU6 AG/H/I
P0FA	Standard manufacturing sequence
P2G5	Filler neck module 1 without insert
P5C0	Without special body measures

P6U0	Without additional seals outside
P6V1	Rear trim panel (ECE)
P6W6	Front license plate carrier
P0F3	Fuel system for diesel engine
P7A0	Without CD changer/CD player
PVL0	Standard pedestrian protection measures
P7G0	Without preparation for VTS (vehicle tracking system)
P8Y1	Two-tone horn
PA00	No self-collection
PIX2	Diesel engine
PKS0	Without head-up display
PNT0	Transit coating (type 1)
PNY0	Standard battery/alternator capacity
PVH2	48-V electric system
P0RZ	Without ignition/starter switch locking system, without steering lock
P04H	S line
PT7V	6-cylinder diesel engine 3.0 l unit 059.N
P0JL	Weight category front axle weight range 11
P1VH	Installation parts for six-cylinder engine
P3M3	Passenger car design
P5L0	Without front spoiler
PES0	Without vehicle inlet
PEV0	Without charging cable
PC34	Operating permit, alteration
P1P0	Standard suspension
P3CA	Without partition
P73A	Without charging cable (industrial connector)
PEH0	Without charging cable
P1D3	Trailer hitch
PK5A	Body style variant 1
PQT5	Without step
P0E2	Long wheelbase
P1Y6	Automatic slip-control differential
P3U7	Luggage compartment cover
P1TR	Vehicle class differentiation -4MF-
PDV8	6-cyl. turbo diesel engine 3.0 l/210 kW V6 TDI common rail base engine is T7V/T2P
P0K4	Mild hybrid
P0M5	Fuel tank with increased volume
P0NB	S line logo, exterior

P0TD	Floor mats in front and rear
P2C5	Safety steering column
P2D0	Without action
P2F0	Without locking and starting systems
P2KR	Labels in English and German
P2Z8	Model designation as per new engine power designation
P3B3	ISOFIX child seat anchors and top tether for the rear bench seat
P3G4	ISOFIX child seat anchors for front passenger seat
P3GD	Luggage compartment floor
P3NS	Rear bench seat Plus
P4D3	Seat ventilation in front
P4E7	Luggage compartment lid, electrically opening and closing
P4L6	Auto-dimming interior rearview mirror, frameless
P5J1	Roof spoiler including center high-mounted stop lamp
P5RU	Exterior mirror on the right (large field of view), convex
P5SL	Left exterior mirror, aspherical
P6F0	Without emblems
P6FA	Exterior mirror housings painted in body color
P6K8	Audi pre sense front
P6NQ	Headliner in Black fabric
P7AL	Anti-theft alarm system
P7E0	Without heat accumulator/auxiliary heater
P7K1	Tire pressure monitoring system
P7L8	Start/stop system
P7P1	4-way lumbar support for the front seats
P7TL	Decorative inserts in Gray Brown Natural Fine Grain Ash
P7W3	Audi pre sense rear
P8G5	HD Matrix LED headlamps with dynamic light design and dynamic turn signal
P8SQ	LED rear combination lamps with dynamic light design and dynamic turn signal
P8X1	Headlamp washer system
P9G8	Belt-driven integrated starter alternator 48 V 110 - 250 A
P9R0	Without night vision
P9WC	Without "Multimedia" in vehicle
PA8S	Standard equipment
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PFY2	Singleframe mask in Matte Platinum Gray
PFZ1	N.N.N. Type 1

PG1G	tiptronic
PGH1	quattro (with self-locking center differential)
PGJ0	Without combined lateral and longitudinal control
PGP0	Vehicles without special upgrade measures
PGZ2	Power latching for the doors
PH8N	Tires 285/45 R21 113Y XL
PJX1	Front cross traffic assist
PL0L	Left-hand drive
PNJ0	Without wall bracket
PPQD	"S line" exterior package
PQK1	With multifunction camera
PQV0	Without TV reception and without digital audio broadcasting
PQZ7	Electromechanical power steering
PU5A	Instrument housing assembly, indication in km/h
PUH2	Hold assist
PV0A	Tires without specification of tire brand
PVT5	Scuff plates with aluminum inserts in front and rear, illuminated, with "S" logo in front
P2V5	Automatic air recirculation
P4A3	Seat heaters in front
P4X3	Side airbags in front and curtain airbag system
P5K5	Adhesive film
P0P0	Tailpipes
P4KC	Heat-insulating glass
P7UG	MMI Navigation plus with MMI touch
P7X2	Parking aid Plus
PKA2	Rear view camera system
PQJ0	Without aluminum/chrome package
P1BK	adaptive air suspension
P3Y0	Without roll-up sunshade
P6Y2	Speed limiter
P8K1	Separate daytime running light
PN5D	Valcona leather
P3L4	Power front seats including memory feature for the driver seat
P8Q3	Headlight range control
P9JA	Non-smoker's package
P9S8	Audi virtual cockpit
PFK2	AdBlue tank (24 liters)
PIU0	Without Connect package
PIV0	Without Connect Plus

PIW0	Without emergency call service / roadside assistance call
PUF7	Audi music interface
P4GF	Windshield with heat-insulating glass
P9ZE	Audi phone box
PEL3	Audi connect Navigation & Infotainment
PFT0	Without parking assistance/garage parking assist
P2P2	Stainless steel loading edge protection
PGM0	Without electronic engine sound measures
PKN1	With trim panel
P1G1	Collapsible spare tire
P4F2	Comfort key with sensor-controlled luggage compartment release (with SAFELOCK)
P9AQ	Comfort automatic air conditioning system, four-zone
P9PA	Standard wiper arms/blades
PGS5	Operating buttons in Black glass look with haptic feedback including extended aluminum look
PI8T	MMI Radio plus with MMI touch response
P8T6	Cruise control system with speed limiter
P1PR	Anti-theft wheel bolts and loose wheel warning
P5ZC	Variable head restraints for front seats
P4ZD	Black Appearance package
PVC2	Garage door opener
P1EX	Special identification label (EU)
PER1	Regional code " ECE " for radio
PPNQ	MMI Navigation plus with MMI touch®
PQI6	Service indicator 30 000 km or 2 years (variable)
PQL5	Privacy glass (dark-tinted windows)
PQR9	Camera-based traffic sign recognition
PPS8	Individual contour seats in front
PQ2J	Individual contour seats in front
PPV3	Power seats in front including memory feature for the driver seat
P1KQ	Disc brakes in rear (18-inch ECE)
P1LN	Disc brakes in front (18-inch ECE)
P2H9	Audi drive select →with efficiency
P2K7	Body-colored S line bumpers (full paint finish)
P4UF	Deactivation switch for front passenger airbag
P6E6	Comfort center armrest in front
P6SS	Without luggage compartment mat
P6XL	Ext. mirrors, power-adjustable, heated, folding, both sides auto-dim.,mem. ft., front pass. ext. mirror lowering funct.

P7Y1	Audi side assist including Audi pre sense rear
P9VS	Premium sound system with 3D sound
PPCM	City assistance package
PQQ2	Contour/Ambient Lighting package (adjustable to different colors)
PY8W	Special control I/VP
P5XC	Sun visors with illuminated vanity mirrors on driver and front passenger side
P6I3	Lane departure warning
PPAH	Gloss package, black
PYCZ	Ramp-up scenario Z
P9M9	Parking heater and ventilation
PPIH	ISOFIX child seat anchors for front passenger seat
PCZ4	Cast alloy wheels, 5-arm star style, Contrast Gray, partly polished, 10J x 21
PPXC	HD Matrix LED headlamps
PGB1	LTE antenna amplifier country variant 1 for Audi phone box
PPG3	Comfort key in combination with anti-theft alarm system with towing protection
PX7Y	Equipment options subset for export (others)
PIT1	Audi connect Navigation & Infotainment
PB72	Type approval country Lithuania
PPK6	Parking heater/ventilation
PY8S	Special control
P2FJ	Leather-wrapped steering wheel, 3-spoke, with multi-function Plus
PWCK	Equipment package for the Baltic States
PWDA	Comfort package for the Baltic States
PI4M	With special labels safety certificates for Lithuania
PWCR	Technology package for the Baltic States
P0XR	Manual in Lithuanian
LZ7S/	Daytona Gray Pearlescent/Daytona Gray Pearlescent

History

Find different types of vehicle history records in the timeline.



2018



Technical inspection

2021-09 |  Lithuania | 48 254 km

Technical inspection is valid until: 2023-09

Technical inspection type - periodic inspection:

Without faults.



We found no history events from 2021-09 to 2023-10



Damage / repair assessment

2023-10 |  Lithuania

Damaged components:

Exterior body parts

Cooling and air conditioning system

Structural elements of the body


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **1** records related to this vehicle:



Damage / repair assessment



Date

2023-10

Country:

 Lithuania

Preliminary repair cost

€ 3001 - € 5000 

Damaged components:

Exterior body parts

Cooling and air conditioning system

Structural elements of the body

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 

389 €



CO₂ emission g/km

213 g/km



CO₂ emission class

F



Fuel type

Diesel

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany