



Audi A4

VIN code

WAUZZZF42RA015017

Report generated: 2025-12-23 11:44

Valid: 308 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Audi A4

 Gearbox
Automatic

 First registration year
2024



Advertisements

 Sale ad records found for this vehicle



Mileage

 No inconsistencies found in mileage history



Thefts

 No records found



Traffic accidents / damages

 Vehicle damage records found



Photos

 Photos found

Technical data

(Original language)

Production date	2023-09-15
Model	A4 Sedan 2.0 R4110 A7
Series	A4
Type code	8WCA7G
Engine code	DMSB 4-cylinder SI engine 2.0 l/110 kW (16V) turbo FSI, homogeneous base engine is T2J/T5H/T4X
Power	110
Fuel type	Petrol
Displacement	2.00
Drive type	FWD

Steering side	Left
Color	Brilliant Black/Brilliant Black
Interior	Cedar Brown-Cedar Brown-Granite Gray/ Black-Black/Black/Black
Transmission	automatic
Transmission code	VKK

Equipment

(Original language)

PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PE0A	No special edition
PFU0	Country group A
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PIX1	SI engine
PJ2D	Battery 380 A (68 Ah)
P0C0	Standard
PVF0	Standard pedal cluster
P0UA	Without special color trim
P1D0	Without trailer hitch
P1PA	Standard wheel bolts
P0YF	Weight range 6 installation control only, no requirement forecast
P0Y3	Cold zones
P1SA	Without additional front underbody guard
P3FA	Without roof insert (standard roof)
P1Z5	Increase in initial standard fuel filling
P3H0	Without backrest release for front seats
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P8Z5	Not hot country
P7Y1	Side Assist
P7P0	Without lumbar support in seat backrests
P8G1	High beam assistant
P0FA	Standard manufacturing sequence
P0G7	Tiptronic
P1A2	Fuel system for SI engine with direct injection (FSI)

P5C0	Without special body measures
P5J0	Without rear spoiler
P6V1	Rear trim panel (ECE)
P6W6	Front license plate carrier
P7G0	Without preparation for VTS (vehicle tracking system)
P8Y1	Two-tone horn
PA00	No self-collection
PGP1	Vehicles with special upgrade measures
PGW0	Without Car2X
PKS0	Without head-up display
PK8B	Notchback
PNM1	Engine cover
PM3I	4-cylinder SI ENGINE 2.0 l/110 kW (16V) turbo FSI, homogeneous base ENGINE IS T2J/T5H/T4X
PNT0	Transit coating (type 1)
PVH0	Standard electric
PNY0	Standard battery/alternator capacity
P04A	Basic
P0RZ	Without ignition/starter switch locking system, without steering lock
P0JG	Weight category front axle weight range 7
PS3Y	Control of special edition prices
P2G1	Insert for the filling up of unleaded fuel
P6JD	Body-colored door handles
P1VG	Installation parts for four-cylinder engine
P3M3	Passenger car design
P6EA	Without additional side body covers (stone guard)
P4D0	Without seat ventilation/massage seat
P5L0	Without front spoiler
P9TA	Without additional warning lights
PC26	Operating permit, alteration
PT2A	4-cylinder SI engine 2.0 l unit 06N.A 888evo4
P0K4	Mild hybrid
P0P0	Standard exhaust system
P2F0	Without locking and starting systems
P2KR	Labels in English and German
P5SL	Left exterior mirror, aspherical
P7E0	Without heat accumulator/auxiliary heater
P9B0	Without integrated toll system
P9P6	Seat belt reminder

P9S9	Audi virtual cockpit Plus
P9VD	Audi sound system
P9WC	Without "Multimedia" in vehicle
P9ZX	Bluetooth interface
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PGA0	Without preconditioning
PGB0	Without antenna amplifier
PIW3	Audi connect Emergency Call & Service with Audi connect Remote & Control
PL0L	Left-hand drive
PQK1	With multifunction camera
PQQ2	Ambient Lighting package plus
PQZ7	Electromechanical power steering
PV0A	Tires without specification of tire brand
PVC0	Without garage door opener
P1X0	Front-wheel drive
P4H5	Power-operated child safety lock
P5K5	Adhesive film
P6F0	Without decorative films/emoles
P7S0	Without wind deflector
P9K0	Without neck heating
P9M0	Without auxiliary heater/parking heater
PU5A	Instrument cluster, km/h speedometer
P5A8	Luggage compartment trim (design 2)
PYEA	Internal control code
PG1C	S tronic
P3GA	Without luggage/load compartment floor
P3Y0	Without roll-up sunshade
P7AL	Anti-theft alarm
P8K1	Separate daytime running light
P4E2	Luggage compartment lid, automatically opening
P6K8	Audi pre sense city
P7IA	Vehicle class differentiation -8W0/8WA-
PGH0	Without rear differential
P6SS	Luggage compartment mat
PVL1	Extended pedestrian protection
P3NT	Split-folding rear seat backrest
P6H0	Roof in body color

P9G9	Belt-driven integrated starter alternator 12 V, 130 - 200 A
PA9F	A4
P1BA	Standard suspension
P4GF	Windshield with heat-reflecting glass and acoustic glass
PYEB	Internal control code
P8X0	Without headlamp washer system
PUH1	Electromechanical parking brake
P6XD	Exterior mirrors, electrically adjustable and heated
P1EX	Special identification label (EU)
P6FA	Exterior mirror housings in body color
PER1	Regional code " ECE " for radio
PQI6	Service indicator 30 000 km or 2 years (variable)
PQV3	Digital audio broadcasting
PQE0	Without Storage package
PQR9	Camera-based traffic sign recognition
P7W3	Audi pre sense rear and basic
PYEG	Internal control code
P6Y6	Top speed limited to 210 km/h
P6I3	Lane departure warning
P2H0	Without Audi drive select
PA61	Top speed limited to 210 km/h
PPIH	Child Safety package
PIT6	Audi connect Navigation & Infotainment on demand
P2K1	Bumpers
PB72	Type approval country Lithuania
PWK8	Interior design selection
PIU1	Smartphone interface
PI4M	With special labels safety certificates for Lithuania
PGV0	Without alcohol interlock
PX79	Equipment options subset for ROW/Europe
P0XR	Manual in Lithuanian
P4WH	Emission standard, EU6 EA lambda = 1 WLTP3 M1, N1-I
PS18	Deviating installation
PNI0	SWIN management
P0TD	Floor mats, front and rear
P1G8	Tire repair kit
P1S2	Vehicle tool kit
P1T3	First-aid kit with warning triangle and high-visibility vests
P1KD	Disk brakes, rear, 16-inch (ECE)

P1LA	Disk brakes, front, 16-inch (ECE)
P1XW	Leather steering wheel, 3-spoke with multifunction plus
P0M1	Fuel tank with increased capacity
PQ1D	Sport seats, front
PQL1	Rear window, rear door and side windows in clear glass
P6E3	Comfort center armrest, front
P6NJ	Headlining in cloth in specific color
P2Z7	Omission of output/technology logo
P3G4	ISOFIX child seat mounting for the front passenger seat
P3B3	ISOFIX child seat mounting and top tether for the outer rear seats
P3PB	Driver seat, electrically adjustable
P5ZF	Head restraints, front
P7L8	Start-stop system
P9JA	Non-smoker version
P4A3	Seat heating, front
P4KC	Rear and side windows with heat-insulating glazing
P4X3	Side airbags, front and head airbag system
P7X2	Parking system plus
P8IT	LED headlights
P9AQ	3-zone deluxe automatic air conditioning
P4ZB	Gloss package
P4L6	Interior mirror, automatically dimming, frameless
P4UF	Airbags, front; front passenger airbag can be deactivated
P7K1	Tire pressure loss indicator
P8VM	LED rear lights plus
P5XK	Sun visors, front
P7HB	Interior elements in artificial leather
P8T6	Cruise control with speed limiter
P7TL	Inlays, Oak Natural, Gray
P7UZ	Preparation for activating navigation function
P4F2	Convenience key with Safelock
PFK0	Without AdBlue tank
PFP1	Preparation for functions on demand
PGT6	Accent surfaces, Gloss Black
PKA2	Reversing camera
PFZ1	Seat belts in Black
P3S0	Omission of roof rails
P5RU	Exterior mirrors on the right, (large field of view), convex
PJE3	Data module, Europe

PH3U	Tires with optimized rolling resistance 225/50 R17
PVT4	Door sill trims with aluminum inlays, front, illuminated
PPX2	LED headlights and LED rear lights with dynamic turn signal in rear
PPCM	Assist package City
PPKG	GSR equipment package
PC8F	Wheels, 10-spoke crystal, 7.5J x 17, 225/50 R17 tires
PPGD	Convenience key with sensor-controlled release of the luggage compartment lid including anti-theft alarm
PN3Q	Fine Nappa leather upholstery and trim
LY9B/	Brilliant Black/Brilliant Black

History

Find different types of vehicle history records in the timeline.



Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.



View original



2024



Service

2024-01 |  Lithuania | 9 km

Performed tasks:

Delivery inspection.



Technical inspection

2024-02 |  Lithuania | 1 km

Technical inspection is valid until: 2027-02

Technical inspection type - new vehicle inspection:

Without faults.



Sale or auction

2024-03 |  Lithuania | 300 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)



Damage / repair
assessment

2025-01 |  Lithuania

Damaged components:

Exterior body parts



Damage / repair assessment

2025-01 |  Lithuania

Damaged components:
Exterior body parts



Service

2025-04 |  Lithuania | 20 423 km

Performed tasks:

Flexible oil change service.



Service

2025-08 |  Lithuania | 28 746 km

Performed tasks:


Inspection.
Dust and pollen filter.
Brake fluid service.
Air cleaner element.



Sale or auction

2025-11 |  Lithuania | 31 303 km

An online ad has been placed for the sale of this vehicle.




[More information »](#)

Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:
Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **1** records related to this vehicle:



Damage / repair assessment



Date

2025-01

Country:



Lithuania

Preliminary repair cost

€ 0 - € 500

Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found 2 listings related to this vehicle:



ADVERTISEMENTS

The ad is inactive

Ad has been placed

Country

Mileage

Seller

Seller

2024-03

 Lithuania

300 km

2024-03-19

Private

Unidentified

2024-03-19

 Photos (21)





ADVERTISEMENTS

Ad has been placed

Country

Mileage

Seller

Seller

The ad is inactive

2025-11

 Lithuania

31 303 km




2025-11-12



Private

Identified

2025-11-12

 Photos (34)





Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany