



Porsche Panamera

VIN code

WP0ZZZ97ZJL188725

Report generated: 2025-05-19 12:01

Valid: 61 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

First registration year	2018
Transmission	Automatic
Engine	2894 cm³, 462 HP (340 kW)
Color	Gray
Fuel	Petrol + Electric
Wheel	Left hand drive
Bodytype	Touring
Doors	4/5
Drivetrain	Four wheel drive
Engine CO2 g/km	59



Advertisements



Sale ad records found for this vehicle



Mileage



No inconsistencies found in mileage history



Thefts



No records found



Traffic accidents / damages



Vehicle damage records found



Photos



Photos found

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2017



Service

2017-12 |  Slovakia | 5 km

Performed tasks:

serviced_service

unknown_service



Information

2018-04 |  United States

Manufacturer's recall to eliminate deficiencies
Program #WH32 REWORKING COOLING FAN HOUSING



Damage / repair
assessment

2018-10 |  Belgium | 15 000 km



Recall

2018-12 |  Belgium

Manufacturer's recall for safety reasons
NHTSA #18V898
Recall #AJ13 RE-PROGRAMMING ELECTRIC POWER STEERING CONTROL UNIT
Status: Remedy Available



Recall

2019-03 |  Belgium

Manufacturer's recall for safety reasons
NHTSA #19V115
Recall #AKA1 RE-PROGRAMING INSTRUMENT CLUSTER
Status: Remedy Available



Service

2020-06 |  Netherlands | 14 913 km

Performed tasks:

unknown_service



Service

2021-10 |  Lithuania | 17 465 km

Performed tasks:

unknown_service



Service

2021-10 |  Lithuania | 17 321 km

Performed tasks:

unknown_service



Technical inspection

2022-03 |  Lithuania | 27 202 km

Technical inspection is valid until: 2024-03
Technical inspection type - periodic inspection:
Without faults.



Service

2022-09 |  Lithuania | 47 966 km

Performed tasks:

unknown_service



Service

2022-10 |  Lithuania | 50 309 km

Performed tasks:

unknown_service



Damage / repair assessment

2023-09 |  Lithuania | 75 557 km

Damaged components:

Body parts



Sale or auction

2023-11 |  Lithuania | 76 416 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)



Technical inspection

2024-03 |  Lithuania | 77 849 km

Technical inspection is valid until: 2026-03

Technical inspection type - periodic inspection:

Without faults.



Damage / repair assessment

2024-09 |  Lithuania

Damaged components:

Body parts

Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.

Data error


2020-06

14 913 km

Data error

2021-10

17 321 km



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

! Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **3** records related to this vehicle:



Damage / repair assessment




 Undercarriage damage

Date	2018-10
Mileage	(15 000 km)
Country:	 Belgium
Preliminary repair cost	€113,000 - €114,000 



Damage / repair assessment



Date

2023-09

Mileage

(75 557 km)

Country:

 Lithuania

Preliminary repair cost

€250 - €500 


Damaged components:

Body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage / repair assessment



Date

2024-09

Country:



Lithuania

Preliminary repair cost

€500 - €750 [i](#)

Damaged components:

Body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.It insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 
0 €



CO₂ emission g/km
59 g/km



CO₂ emission class
A



Fuel type
Petrol + Electric

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found **1** listings related to this vehicle:



ADVERTISEMENTS

Ad has been placed: **2023-11-23**

The ad is inactive

 **Lithuania**

Mileage


76 416 km

2023-11-23

Seller: **business**

2023-11-23

[Photos \(40\) »](#)



Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany

 United States