

Mercedes-Benz GLC 350

VIN code

WDC2539541F279945

Report generated: 2026-03-09 11:27

Valid: 361 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Mercedes-Benz GLC 350

 Gearbox
Automatic

 First registration year
2017

 Fuel type
Petrol + Electric



Mileage

 No inconsistencies found in mileage history



Thefts

 No records found



Photos

 No photos found

Technical data (Original language)

| | |
|-----------------|---------------------------------|
| Production date | 2017-05-15 |
| Model | GLC 350 e 4MATIC |
| Series | GLC |
| Generation | 253 |
| Body type | Special version |
| Type code | 253 |
| Engine code | 4-CYLINDER GASOLINE ENGINE M274 |
| Displacement | 2.00 |
| Steering side | Left |
| Color | DIAMOND WHITE - METALLIC PAINT |
| Interior | LEATHER - BEIGE |
| Transmission | automatic |

Equipment (Original language)

| | |
|-----|------------------------|
| 057 | YOM 16/2 |
| 531 | COMAND APS NTG5/NTG5.5 |

| | |
|------|--|
| 807 | YOM 16/1 |
| 810 | PREMIUM SOUND SYSTEM |
| HA | REAR AXLE |
| L | LEFT-HAND STEERING |
| P44 | PARKING PACKAGE |
| U22 | LUMBAR SUPPORT ADJUSTMENT |
| 274 | TELEPHONE ANTENNA |
| 345 | RAIN SENSOR |
| JVG | PLANT CONTROL CODE |
| JVO | PLANT CONTROL CODE |
| M20 | DISPLACEMENT 2.0 LITER |
| P17 | KEYLESS-GO PACKAGE |
| U25 | ILLUMINATED DOOR SILL |
| 293 | Sidebag in rear left and right |
| 367 | Live Traffic capability |
| 2U8 | Alternative refrigerant |
| FX | Special version |
| K13 | Control code for service interval 25000 km |
| 720 | ROOF RAILING |
| P55 | NIGHT PACKAGE |
| 851 | ACOUSTIC GLAZING |
| 900 | EXTERIOR CHROME PACKAGE |
| F253 | MODEL SERIES 253 |
| 229L | GERMANY |
| 2XXL | FEDERAL REPUBLIC OF GERMANY |
| 70B | SAFETY VEST - DRIVER |
| P22 | INTERIOR LUXURY PACKAGE |
| 237 | ACTIVE BLIND SPOT ASSIST |
| 99R | AMG DOUBLE-SPOKE WHEELS 19" ALL-ROUND |
| JVX | PLANT CONTROL CODE |
| VR | FRONT AXLE HALF, RIGHT |
| VL | FRONT AXLE HALF, LEFT |
| 550 | TRAILER COUPLING |
| 890 | Automatic rear-end door |
| 351 | E-CALL EMERGENCY CALL SYSTEM |
| 8U8 | I-SIZE-MARKING (ISOFIX SUCCESSOR) |
| 8U7 | REAR SEAT BELT WITH BELT FORCE LIMITER AND SOFTST. |
| B59 | TRANSMISSION MODE SELECTOR LEVER (AGILITY SELECT) |
| 6P5 | STEUERCODE VERTRIEB FUER CODE 475 ANFORDERUNG |

| | |
|------|--|
| 270 | GPS ANTENNA |
| U01 | REAR BELT STATUS INDICATION |
| P49 | MIRRORS PACKAGE |
| 670 | RESIDUAL ENGINE HEAT UTILIZATION (MRA) |
| 235 | ACTIVE PARK ASSIST |
| 255B | MB MOBILO WITH DSB AND GGD |
| U10 | FRONT PASSENGER SEAT WITH WEIGHT SENSING |
| 299 | PRESAFE |
| 309 | CUP HOLDER |
| 475 | TIRE PRESSURE CONTROL |
| 500 | ELECTRIC FOLDING OUTSIDE MIRROR |
| 927 | EURO 6 TECHNOLOGY EXHAUST GAS CLEANING |
| K11 | ADAPTIVE STOP LIGHT FLASHING |
| U60 | PEDESTRIAN PROTECTION - ACTIVE ENGINE HOOD |
| 249 | INTERIOR AND EXTERIOR MIRROR,AUTOMATICALLY DIMMING |
| 3U1 | EUROPE/CIS COUNTRIES/MONGOLIA HEAD UNIT |
| 294 | KNEE AIRBAG |
| 893 | KEYLESS START |
| 736 | TRIM PIECES - WOOD ASH BLACK |
| U72 | DVD PLAYER WITH REGIONAL CODE 2, EUROPE, JAPAN |
| 253 | REAR-END COLLISION WARNING AND PROTECTION SYSTEM |
| 628 | AUTOMATIC HIGH BEAM SWITCH PLUS (IHC+) |
| 772 | AMG STYLING PACKAGE-FRONT SPOILER, SIDE SKIRT |
| 871 | SENSORS FOR TRUNK LID OPENING/CLOSING |
| 238 | ACTIVE LANE KEEPING ASSIST (FAP) |
| 23P | DRIVING PACKAGE |
| 840 | DARK TINTED GLASS |
| 266 | DISTRONIC PLUS CROSS SUPPORT (DTR+Q) |
| 268 | EXPANDED BRAKE ASSIST (BAS+) |
| 269 | BRAKE ASSIST PLUS CROSS TRAFFIC (BAS+Q) |
| 271 | AUTONOMOUS BRAKE INTERVENTION/WARN. FOR PED. PROT. |
| 300 | COLLISION MINIMIZATION BRAKE INTERV./WARNING (CMS) |
| 5P6 | CONTROL CODE MARKETING |
| P31 | AMG LINE EXTERIOR/AMG SPORTS PACKAGE EXTERIOR |
| 489 | AIRMATIC DUAL CONTROL / AIR SUSPENSION SEMI-ACTIVE |
| M274 | 4-CYLINDER GASOLINE ENGINE M274 |
| 233 | AUTONOMOUS INT. CRUISE CONT. PLUS (DISTRONIC PLUS) |
| 275 | MEMORY PACKAGE (DRIVER SEAT, STRG. COL., MIRROR) |
| 581 | Automatic climate control |

| | |
|------|--|
| 876 | INTERIOR LIGHT ASSEMBLY |
| 642 | Dynamic LED headlamps, right-hand traffic |
| 877 | AMBIENCE ILLUMINATION |
| 889 | KEYLESS - GO |
| 427 | AUTOMATIC TRANSMISSION 7-SPEED |
| J81 | JUNE RELEASE |
| 11U | MBCONNECT - REMOTE ONLINE (HERMES) |
| 02B | OPERATORS MANUAL AND SERVICE BOOKLET GERMAN |
| 360 | HERMES - COMMUNICATION MODULE UMTS |
| 332B | INSTRUMENT CLUSTER/HU LANGUAGE - GERMAN |
| 969 | COC PAPER EURO6 TECH. W/ REGISTRATION CERT. PART 2 |
| 875 | HEATED SCREEN WASH SYSTEM |
| U35 | 12 V - SOCKET IN LOAD SPACE |
| 55U | ROOF INTERIOR TRIM BEIGE FABRIC |
| 513 | TRAFFIC SIGN RECOGNITION |
| 448 | TOUCHPAD WITH ROTARY PUSHBUTTON |
| 502 | 3 YEARS OF MAP UPDATES FREE OF CHARGE |
| 401 | FRONT SEAT CLIMATE CONTROL |
| 413 | PANORAMIC SLIDING SUNROOF/GLASS SUNROOF |
| GH | HYBRID TRANSMISSION |
| 723 | TRUNK COVERING |
| U40 | CARGO NET BEHIND FRONT SEATS |
| 242 | ELECTRICALLY ADJUSTABLE RIGHT DRIVER SEAT W MEMORY |
| M005 | VEHICLES WITH 4-MATIC-/ALL WHEEL DRIVE |
| U09 | LEATHER-CLAD INST.PANEL + BELTLINE (ART. EMBOSSED) |
| A17 | DAS 4 |
| 611 | AMBIENT ILLUMINATION |
| 537 | DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.) |
| 815 | DVD SINGLE DRIVE |
| 220A | LEATHER |
| 225A | LEATHER - BEIGE |
| R05 | ROLLING RESISTANCE-OPTIMIZED SUMMER TIRE |
| 799U | DIAMOND WHITE - METALLIC PAINT |
| A121 | P VALVE BODY ASSEMBLY WITH VGS-500 |
| J9A | D724.2 VENTILATION B2 |
| 26A | EFTI ELECTRIC MOTOR 50-80 KW |
| 652 | SUMMER TIRES MOUNTED |
| ME05 | HYBRID DRIVE 85KW-94KW VARIANT (INCL. PLUG-IN) |
| 13U | MBCONNECT - EV FUNCTIONS (HERMES) |

| | |
|------|--|
| 0V2 | SPEED- + LOADINDEX 101V |
| B30 | CHAR.CABLE GROUNDING-CONTACT CEE 7/7 (TYPE E/F) 4M |
| 4R7 | COMPLETE WINTER WHEEL, L. ALLOY 5-SPOKE DESIGN 18" |
| B33 | CHARGING CABLE 7-PIN ICCA PER IEC 62196 16A 4M |
| G268 | TRANSMISSION CODE VERSION 69 |

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2017



Service

2018-06 |  Germany | 13 845 km

Performed tasks:

Engine oil and filter change
Cabin filter replacement



Service

2019-06 |  Germany | 24 297 km

Performed tasks:

Engine oil and filter change
Brake fluid changed
Cabin filter replacement



Service

2020-05 |  Germany | 30 944 km

Performed tasks:

Engine oil and filter change
Air filter element replacement
Spark plugs replaced
Starter replaced



Service

2021-05 |  Finland | 39 191 km

Performed tasks:

Engine oil and filter change
Cabin filter replacement



Service

2022-06 |  Finland | 70 132 km

Performed tasks:

Engine oil and filter change
Automatic transmission: oil and filter change / Oil change of transfer case
Brake fluid changed



Service

2023-11 |  Finland | 96 956 km

Performed tasks:

Engine oil and filter change
Air filter element replacement
Spark plugs replaced



Service

2024-09 |  Finland | 110 753 km

Performed tasks:

Engine oil and filter change
Brake fluid changed
Cabin filter replacement


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.It insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

Great! We did not find any official records of damage or traffic accidents in this report.

This is often a good sign, indicating that the vehicle may not have been involved in accidents or serious incidents and was used responsibly.



However, it is important to note that not all events are always recorded in official databases. Some incidents may be unrecorded or unavailable in our information sources. The data is provided based on third-party information, so its absence in the report does not guarantee that no incidents occurred.

Therefore, as with any used car, we recommend additionally assessing the condition of the vehicle, speaking with the seller, or consulting with a specialist.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.It insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 
0 €



CO₂ emission g/km
59 g/km



CO₂ emission class
A



Fuel type
Petrol + Electric

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany