

Nissan Qashqai

VIN code

SJNFEAJ11U1771635

Report generated: 2025-11-11 12:29

Valid: 242 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

First registration year	2016
Transmission	Automatic
Engine	1197 cm³, 116 HP (85 kW)
Color	White
Fuel	Petrol
Wheel	Left hand drive
Bodytype	Crossover
Doors	4/5
Drivetrain	Front wheel drive
Engine CO2 g/km	129



Mileage

✓ No inconsistencies found in mileage history



Thefts

✓ No records found



Traffic accidents / damages

! Vehicle damage records found



Photos

✗ No photos found

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2016



Technical inspection

2016-08 |  Lithuania | 1 km

Technical inspection is valid until: 2019-08
Technical inspection type - new vehicle inspection:
Without faults.



Service

2017-02 | 11 619 km

Performed tasks:

Workshop Repair.



Service

2017-07 | 20 032 km

Performed tasks:

Nissan Customer Maintenance Plan.



Damage / repair assessment

2018-05 |  Lithuania

Damaged components:

Exterior body parts



Service

2018-07 | 32 534 km

Performed tasks:

Nissan Customer Maintenance Plan.



Service

2018-08 | 33 895 km

Performed tasks:

Workshop Repair.



Damage / repair assessment

2018-09 |  Lithuania

Damaged components:

Exterior body parts



Damage / repair assessment

2018-12 |  Lithuania

Damaged components:

Exterior body parts



Service

2019-07 | 45 037 km

Performed tasks:

Nissan Customer Maintenance Plan.



Technical inspection

2019-08 |  Lithuania | 46 306 km

Technical inspection is valid until: 2021-08

Technical inspection type - periodic inspection:

Without faults.



Service

2020-01 | 51 703 km

Performed tasks:

Roadside Recovery.



Damage / repair assessment

2020-06 |  Lithuania

Damaged components:

Exterior body parts



Technical inspection

2021-08 |  Lithuania | 69 717 km

Technical inspection type - periodic inspection:

Major faults.



Technical inspection

2021-09 |  Lithuania | 70 056 km

Technical inspection is valid until: 2023-08

Technical inspection type - re-inspection:

Minor faults.



Technical inspection

2023-08 |  Lithuania | 92 887 km

Technical inspection is valid until: 2025-08

Technical inspection type - periodic inspection:

Minor faults.



Technical inspection

2025-08 |  Lithuania | 116 438 km

Technical inspection type - periodic inspection:

Major faults.



Technical inspection

2025-08 |  Lithuania | 116 476 km

Technical inspection is valid until: 2027-08

Technical inspection type - re-inspection:

Minor faults.


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **4** records related to this vehicle:



Damage / repair assessment



Date

2018-05

Country:



Lithuania

Preliminary repair cost

€ 501 - € 1500 [i](#)


Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage / repair assessment



Date

2018-09

Country:



Lithuania

Preliminary repair cost

€ 501 - € 1500 [i](#)


Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage / repair assessment



Date

2018-12

Country:



Lithuania

Preliminary repair cost

€ 0 - € 500 


Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage / repair assessment



Date

2020-06

Country:



Lithuania

Preliminary repair cost

€ 501 - € 1500 [i](#)

Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 
0 €



CO₂ emission g/km
129 g/km



CO₂ emission class
B



Fuel type
Petrol

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany