



## Tesla Model X

VIN code

**7SAXCCE62PF371860**

Report generated: 2025-07-16 18:08

Valid: 169 d.

# Information

Basic data of the inspected vehicle and summary of inquiries.

Transmission	Automatic
Engine	1020 HP (750 kW)
Color	White
Fuel	Electric
Wheel	Left hand drive
Bodytype	Crossover
Doors	4/5
Drivetrain	Four wheel drive



## Advertisements



Sale ad records found for this vehicle



## Mileage



No inconsistencies found in mileage history, but not enough records found



## Thefts



No records found



## Traffic accidents / damages



Vehicle damage records found



## Photos



Photos found

# History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2022



Registration

2022-12 | Germany



Accident

2023-07 | Germany



Service

2023-07 | Germany | 8 500 km



Sale or auction

2025-02 | Lithuania | 8 900 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)


# Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



# Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.

Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)


We found **1** records related to this vehicle:



## Damage registered

### ?

#### LOCATION OF THE DAMAGE IS UNKNOWN



Date 2023-07

Country:  Germany

Preliminary repair cost €90,000 - €91,000 



About this record:

*This record lacks detailed information to accurately identify its origin, but we provide all available data for your analysis. It is important to understand that this is a recorded financial assessment, which may indicate:*

- **Repairs or modifications:** a service estimate for planned maintenance, cosmetic bodywork, or the installation of additional equipment (e.g., rims);
- **Proportional value:** the cost of parts for new or luxury vehicles is high, so even minor repairs can appear as a significant amount;
- **Damage record:** a calculation performed by an insurance company after a potential traffic accident.

*We provide this information as an additional indicator to help buyers and sellers constructively discuss the vehicle's history and carry out a more focused physical inspection at a service center.*

# Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found **1** listings related to this vehicle:



## ADVERTISEMENTS

Ad has been placed	2025-02
Country	Lithuania
Mileage	<b>8 900 km</b>
Seller	2025-02-11
Seller	Business
	Identified

2025-02-11 | Photos (4)



# Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany



United States