



Audi e-tron

VIN code

WAUZZZGE8NB046414

Report generated: 2025-10-03 11:39

Valid: 248 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Audi e-tron

 Gearbox
Automatic

 First registration year
2022

 Fuel type
Electric



Advertisements

 Sale ad records found for this vehicle



Mileage

 No inconsistencies found in mileage history



Thefts

 No records found



Photos

 Photos found

Technical data

(Original language)

Production date	2022-06-27
Model	e-tron 300
Series	e-tron
Type code	GENCAE
Engine code	EASA Electric motor, system output 300 kW base motor is N02/T68/T83/T0B/T67/T3S
Power	300
Fuel type	Electric
Steering side	Left
Color	Mythos Black Metallic
Interior	Black-Black-Rock Gray/Black-Black/ Black/Lunar Silver

Transmission automatic

Transmission code UPV

Equipment

(Original language)

PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PE0A	No special edition
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PJ2D	Battery 380 A (68 Ah)
P0YQ	Weight range 15 installation control only, no requirement forecast
P1D0	Without trailer hitch
P0Y1	Standard climatic zones
P1SA	Without additional front underbody guard
P6F7	Emblems
P3FA	Without roof insert (standard roof)
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P5J1	Rear spoiler
PGZ0	Manually operated doors
P0FA	Standard manufacturing sequence
P5C0	Without special body measures
P7A0	Without CD changer/CD player
P7G0	Without preparation for VTS (vehicle tracking system)
P8Y1	Two-tone horn
PGW0	Without Car2X
PIU2	With Connect package 2
PKS0	Without head-up display
P04A	Basic
PS3Y	Control of special edition prices
P0JM	Weight category front axle weight range 12
P4D0	Without seat ventilation/massage seat
P9TA	Without additional warning lights
P8IY	LED headlamps with lens
PC19	Operating permit, alteration

P0K9	Drive system BEV
PT4K	Electric motor units 0EF.A and 0EF.B
P2C5	Safety steering column
P2F0	Without locking and starting systems
P4E7	Luggage compartment lid, electrically opening and closing
P4UF	Driver and front passenger airbag with front passenger airbag deactivation
P5SL	Left exterior mirror, aspherical
P5XC	Sun visor on driver and front passenger side
P6K8	Audi pre sense front
P7P1	4-way lumbar support for the front seats
P7UG	MMI navigation plus with MMI touch response
P9B0	Without integrated toll system
P9R0	Without night vision
P9VD	Audi sound system
P9WC	Without "Multimedia" in vehicle
P9ZX	Bluetooth interface
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PGB0	Without antenna amplifier
PGJ0	Without combined lateral and longitudinal control
PGP0	Vehicles without special upgrade measures
PIT3	Audi connect Navigation & Infotainment
PIW3	Audi connect Emergency Call & Service with Audi connect Remote & Control
PL0L	Left-hand drive
PQK1	With multifunction camera
PVC0	Without garage door opener
P5K5	Adhesive film
P7AA	Electronic immobilizer
P7Y0	Without lane change assist
P7W1	Audi pre sense basic
P1X1	quattro
P3Y0	Without roll-up sunshade
P9S8	Audi virtual cockpit
PQQ1	Ambient Lighting package
P6SS	Luggage compartment mat
PUF7	Audi music interface
PK4H	Box
PFT0	Without parking assistance/garage parking assist

PQZ7	Progressive steering
P2V5	Without air quality package
PA8Y	S line
P0GA	Without specific emission standard
PEH1	Vehicle charging cable
PKB3	On-board charger up to 11 kW (AC)
P1EX	Special identification label (EU)
P6FA	Exterior mirror housings in body color
PGM4	Acoustic vehicle alerting system
P0LW	With special labels safety certificates for Germany
PB01	Type approval country Germany
PER1	Regional code " ECE " for radio
PQV3	Digital audio broadcasting
PX0A	Equipment options subset for Germany
P0VC	Manual in German
P31K	License plate carrier in front and rear (ECE)
PYBS	Control code 8
PQE0	Without Storage package
P3L3	Front seats, manually adjustable
P1TX	Vehicle class differentiation -4KE/4KH-
P3U4	Manual luggage compartment cover
PG1Z	Transmission for electric drive (1-speed)
PQL5	Privacy glass (dark-tinted windows)
PQR9	Camera-based traffic sign recognition
PVI9	Service indicator 30 000 km or 2 years (fix) electric vehicle
PH6W	Tires 255/50 R20 109H xI
P2Z0	Without model and engine power/ technology nameplate
P6I3	Lane departure warning
PJX0	Without front cross traffic assist
P7HA	Upper part of dashboard in leatherette
PJ9T	High-voltage battery 95 kWh (gross)
PLX2	Cell module C
PY8X	Special control I/VP
P0TD	Floor mats, front and rear
P1I0	Seat occupancy sensor
P1PR	Wheel bolts with anti-theft protection and loose wheel detection
P1G8	Tire repair kit
P1S2	Vehicle tool kit
P1T3	First-aid kit with warning triangle and high-visibility vests

P1KQ	Disk brakes, rear, 18-inch
P1LP	Disk brakes, front, 18-inch
PNJ0	Without wall mount
PQ1D	Sport seats, front
PNW1	e-tron charging system compact
PN2R	Valcona leather with S embossing
P6NQ	Headlining in cloth, Black
P6E3	Comfort center armrest, front
P76H	Charging cable for public charging, mode 3, 22 kW (AC)
P2MB	adaptive air suspension sport
P2K7	Bumpers, S line
P3B3	ISOFIX child seat mounting and top tether for the rear seat bench
P3CX	Partition net
P3G4	ISOFIX child seat mounting for the front passenger seat
P70T	Domestic connector type E/F for the e-tron charging system
P73P	Industrial connector CEE 16A, 400V, long and straight, for the e-tron charging system
P7B3	12V socket
P7E1	Heating output, standard
P6XK	Exterior mirrors, electrically adjustable, heated and folding, automatically dimming on both sides
P2PF	Sport contour leather steering wheel, 3-spoke, flat bottom with multifunction and shift paddles
P4ZP	Black Styling package plus
P5ZF	Head restraints, front
P9JA	Non-smoker version
P9PA	Windshield wiper arms and blades, standard
P4A3	Seat heating, front
P4KC	Rear and side windows with heat-insulating glazing
P4X3	Side airbags, front and head airbag system
P8G4	Matrix LED headlights with dynamic light sequencing and dynamic turn signal
P4L6	Interior mirror, automatically dimming, frameless
P7K1	Tire pressure loss indicator
P9AK	2-zone deluxe automatic air conditioning
P8T6	Cruise control with speed limiter
P9X9	Parking system plus with 360° display
P4GF	Windshield with heat-insulating/ acoustic glazing
P5TG	Inlays, Matt Brushed Aluminum, Dark
PFP1	Preparation for functions on demand
PES7	Charging socket CCS type 2

PGA2	Comfort auxiliary air conditioning
PGS0	Control buttons, Matt Black
PKA2	Reversing camera
P8K4	Daytime running lights
P3S0	Omission of roof rails
P4I7	Remote control key, without Safelock
P5RU	Exterior mirrors on the right, (large field of view), convex
PJE3	Data module, Europe
PJS0	Without second charging port
PVT5	Door sill trims with aluminum inlays, front and rear, illuminated, front with S logo
PWQS	Interior S line
PF08	Wheels, 5-arm dynamic, Graphite Gray, gloss turned finish, 9.0J x 20, 255/50 R20 tires
PPX6	Matrix LED headlights and LED rear lights
PM1J	Electric motor, system output 300 kW base motor is N02/T68/T83/T0B/T67/T3S

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

☐ View original



2022



Service

2022-08 | Germany

Performed tasks:

Delivery inspection.



We found no history events from 2022-08 to 2024-08



Service

2024-08 | Lithuania | 11 269 km

Performed tasks:

Inspection
Dust and pollen filter.
Brake fluid service.
Collection tank.



Service

2025-06 | Lithuania | 28 242 km



Technical inspection

2025-08 | Lithuania | 31 874 km

Technical inspection is valid until: 2027-08
Technical inspection type - periodic inspection:
Without faults.



Sale or auction

2025-08 |  Lithuania | 34 400 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

Great! We did not find any official records of damage or traffic accidents in this report.

This is often a good sign, indicating that the vehicle may not have been involved in accidents or serious incidents and was used responsibly.



However, it is important to note that not all events are always recorded in official databases. Some incidents may be unrecorded or unavailable in our information sources. The data is provided based on third-party information, so its absence in the report does not guarantee that no incidents occurred.

Therefore, as with any used car, we recommend additionally assessing the condition of the vehicle, speaking with the seller, or consulting with a specialist.

Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found **1** listings related to this vehicle:



ADVERTISEMENTS

The ad is inactive

Ad has been placed

Country

Mileage

Seller

Seller

2025-08

 Lithuania

34 400 km



2025-08-27



Private

Identified

2025-08-27

 Photos (31)







Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany