

## Toyota Corolla

VIN code

**NMTBE3BE70R012971**

Report generated: 2026-02-19 10:37

Valid: 361 d.

# Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model  
**Toyota Corolla**

 Gearbox  
**Automatic**

 First registration year  
**2019**

 Fuel type  
**Petrol**



## Mileage

 No inconsistencies found in mileage history



## Thefts

 No records found



## Traffic accidents / damages

 Vehicle damage records found



## Photos

 No photos found

## Technical data

(Original language)

Model	Corolla
Body type	Sedan
Type code	ZRE210
Engine code	1ZR-FAE
Transmission	automatic

## Equipment

(Original language)

ISOL28	Immobilizer anti-theft system
FRGRA19	Fr2, rr2 assist grip

ECVECBK32	Ebd brake cont valve- edb control
WRDHO20	With cooler rear duct
BBMCO23	Black door belt moulding
WBLHE26	With emergency brake lights
RALCAIN38	Rh aiming (for lhd car) headlamp aiming
WACHC36	With (hac3) hill assist control (hac)
WRLHG21	With luggage room lamp
WCHARHP28	With cup holder rear arm rest
WLCAB31	Wvta label regulation compliancy
WOBPHS37	With (passenger only) seat back pocket
WOMTSLHT38	With outer mirror side turn signal lamp
WAWHL21	With asl speed warning
FRRA17	Fr & rr stabilizer
EMFFAL29	Ethanol min. fill washer fluid
WFLWHS30	With washer fluid level warning
FRHRC19	Fr:2 rr:2 cup holder
EERCL1E30	E5, e10 reg. fuel caution label
WFLHA17	With rear fog lamp
WDLSHO33	With d (power) seat lumbar support
PFAFLF29	Pollen filter clean air filter
WDLHR22	With wireless door lock
CASAPDE31	Cold area spec cold area package
WTRLSHD43	With (led type) daytime running light system
NSMF16	Normal front seat
WBLHO18	With glove box lamp
DNRVMNH34	Day & night inside rear view mirror
EBPK16	Epb parking brake
WWTWDHA43	With (heavy with timer) rear window defogger
LWOL29	3-spoke leather steering wheel
STUT24	Sequential switch tronics
NPDCMDP37	Needle punch trunk & deck carpet & mat
ETPCI30	Electric type accelerator pedal
WDOPHA36	With (rear door only) child protector
PIHTG25	Plating door inside handle
FPRO16	Fr&rr door pocket
VXHTA26	Vertical x2 front headrests
MLUH24	Manual headlamp levelling
WRWHT34	With (autocut) light remind warning
WDLHW19	With power door lock

PTLSA22	Personal type room lamp
WKTH30	Without (repair kit) spare tyre
AMOA19	Auto (dual mode) a/c
WHS7	With abs
CBCSE37	Console box accessory connector (n0 1)
PSWIBMOSAI45	P seat with indicator air bag manual on-off sw
WJHD14	With audio jack
AMIE18	Audio + meter clock
WHHA13	With coat hook
RBIO16	Resin console box
FARRD19	Fabric door arm rest
RSPTOIA39	Resin + satin plating door trim ornament
SWDTPDGW51	Single without diffuser exhaust tail pipe & diffuser
WPLHL30	With (bulb) front personal lamp
DMSSMP32	260mm d&p manual front seat slide
GSGE025	Green 70% front side glass
SPBCCIL43	Satin plating/piano black i/p center cluster
WMLESHO46	With (room + map lamp) illuminated entry system
SWSPTT38	Soft w/ stitch (p-pad) instrument panel
AFPCSF340	Alc + fmh 3 position light control system
FROTUHWRN43	Fr & rr 4 one touch up/down hi power windows
SFSPT23	6:4 split fold rear seat
TS2F16	Tss2 safety sense
FRLBWRZ40	Fr & rr (buzzer + lamp) seat belt warning
FBMMRB25	Fabric b mid seat material
WSPPLBHT48	With satin plating + p-blk bezel shift lever boot
WPIHT36	With (meter) shift position indicator
KSSI23	Km/h + satin speedometer
DSHCKANH40	D&p snl hi+sd (fr) + csa + kn srs airbag
TTCTL32	Tilt & telescopic steering column
DTVAAALWSPE71	Disp (h) + tel + voice + audio + acc + asl + lda steering wheel switches
COACTO36	Centre ornament (for alumi) wheel cap
LGAGIT38	Laminated green 70% ac windshield glass
ESPE17	Eps power steering
RSAM34	Rotary (mechanical) starting system
CBCSE38	Console box1 accessory connector (n0 2)
RWSIO23	Rr window + sfin antenna
GGE019	Green 70% back glass
RSIPSOIO38	Radiator sp + id plate + sash black out

PCOU15	Pp colour bumper
ITRSZO42	Isize + top tether*2 child restraint system
WRACHL35	With (full range acc) cruise control
WECMHA36	With e-call data communication module
BDWKPOHYL45	Bodycolour d: w/ key p:w/o door outside handle
WSPHO20	With door scuff plate
FHWNFTRR33	Fr&rr: hard with nv felt door trim
PWFTG24	Plating door window frame
WAMUCPHT58	With (without acoustic mat) engine under cover & protection
ETWOECOT44	Euro6d temp with obd exhaust emission control
FSRLIS35	Fr (with silencer) & rr fender liner
DHPFCAMOW48	Dilour (with heel pad) front floor carpet and mat
DPFSBEP37	D,p: 3elr + pt + f/l*2 front seat belt
DMSVAAA42	D: 2way manual front seat vertical adjuster
DWBIB30	15" disc (b) front wheel brake
BTWLBTE26	Bin type w/o lock glove box
BPHAEA29	Bi pes halogen + ahb headlamps
ADSCPOA37	Auto dual + satin heater control panel
WTMSLHD41	With (led type/cabin) high mount stop lamp
WPUCHI26	With (d, p) i/p under cover
APMCSFPPIA66	Audio panel & meter cluster satin (plating) instrument finish panel
WBABDGHA46	With (plating) lower back and back door garnish
CELABDRLL46	Cable + elec lock luggage and back door release
WTHG16	With luggage tray
WMAHC25	With (ohc) mike & mike amp
WIDHM27	With 4.2" multi info display
EOA8	Euro ncap
EHRVMCI40	Electric, heater outside rear view mirror
WSSWHCHT50	With (with sos sw, without holder) overhead console
GFWFLTTTCSI57	Glass fiber with felt lo package tray trim & tonneau cover
WWTPWHA39	With wrap type paint protection wax/film
BPPGCA36	Black paint + plating radiator grille
MBLGEA35	Material black radiator lower grille
PPCBAT25	Pp paint color rear bumper
LBCLTL50	Led (tail/stop) + bulb (turn) rear combination lamp
VFHTA34	Vertical*2 + fixed*1 rear headrests
SBRF33	3elr-pt-fl*2 3elr*1 rear seat belt
GSGE024	Green 70% rear side glass
FRSRT22	Fr & rr: satin register

PMVDI26	Pvc (d/p: mirror) sun visor
ADW5131	205/55r16 al-1 tire & disc wheel
WCSRHM35	With camera traffic sign recognition
WDIPWH351	With (433mhz) direct tyre inflation pressure warning
IAWCTE45	Int (time adjustment) windshield wiper control
JMPAE28	Jk master (w/-tr) 2 key plate
PHHHT34	Ptc heater (600w) additional heater
BMBOT40	10" booster (-b) brake m/cylind & booster
TFCLMF229	Tex fm 520g conv lhd floor mat
SFRFRDTET58	Side (without felt) + rr + 1con fk luggage room & deck trim
BOEC20	Base package option 3
FWSWSPCBWT46	Fab w/o stitch w/o slide p-blk rear console box
WBHC15	With (vsc b) vsc
SMMRO20	Sport mode drive mode
L4H15	Ln2 48ah battery
CTB18	Cd/bt/usb 6sp audio
WBFLHT37	Without (material blk) front fog lamps
WKAHA32	With (lta) lane keep assist (lka)
LLKTR31	Leather (cvt) shift lever & knob

# History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.



View original



2019



Technical inspection

2019-06 |  Lithuania | 5 km

Technical inspection is valid until: 2022-06

Technical inspection type - new vehicle inspection:

**Without faults.**



Service

2019-11 | 17 173 km

**Performed tasks:**

serviced\_service



Service

2020-07 | 31 270 km

**Performed tasks:**

serviced\_service



Service

2021-01 | 44 924 km

**Performed tasks:**

serviced\_service



Service

2021-08 | 61 194 km

**Performed tasks:**

serviced\_service



## Service

2022-01 | 75 857 km

### Performed tasks:

serviced\_service



## Technical inspection

2022-06 | 87 459 km

Technical inspection is valid until: 2024-06

Technical inspection type - periodic inspection:

**Without faults.**



## Service

2022-07 | 91 982 km

### Performed tasks:

serviced\_service



## Damage / repair assessment

2022-08

### Damaged components:

Exterior lights

Structural elements of the body

Exterior body parts



## Service

2023-08 | 110 478 km

### Performed tasks:

serviced\_service



## Damage / repair assessment

2023-12

### Damaged components:

Exterior lights

Exterior body parts  
Structural elements of the body



### Technical inspection

2024-07 | 129 123 km

Technical inspection type - periodic inspection:  
**Major faults.**



### Technical inspection

2024-07 | 129 171 km

Technical inspection is valid until: 2026-07  
Technical inspection type - re-inspection:  
**Without faults.**



### Service

2024-08 | 130 870 km

**Performed tasks:**

serviced\_service



### Damage / repair assessment

2025-05 |  Lithuania

**Damaged components:**

Exterior body parts  
Structural elements of the body


# Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



# Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

## ! Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **3** records related to this vehicle:



## Damage / repair assessment



Date

2022-08

Preliminary repair cost

€ 1501 - € 3000

Damaged components:

Exterior lights


Structural elements of the body

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



## Damage / repair assessment



Date

2023-12

Preliminary repair cost

€ 501 - € 1500 

Damaged components:

Exterior lights


Exterior body parts

Structural elements of the body

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



## Damage / repair assessment



Date

2025-05

Country:



Lithuania

Preliminary repair cost

€ 1501 - € 3000 [i](#)

Damaged components:

Exterior body parts

Structural elements of the body

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

# O<sub>2</sub> emission

How much CO<sub>2</sub> emissions do vehicles of this model / year emit?



Autoistorija.It insight:

Each vehicle is assigned a CO<sub>2</sub> emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax   
22 €



CO<sub>2</sub> emission g/km  
133 g/km



CO<sub>2</sub> emission class  
B



Fuel type  
Petrol

CO<sub>2</sub> emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

# Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany