

# Land Rover Range Rover Sport

VIN code

**SALWA2BK8LA708053**

Report generated: 2025-09-01 14:25

Valid: 216 d.

# Information

Basic data of the inspected vehicle and summary of inquiries.

First registration year	<b>2020</b>
Transmission	<b>Automatic</b>
Engine	<b>2993 cm<sup>3</sup>, 249 HP (183 kW)</b>
Color	<b>White</b>
Fuel	<b>Diesel</b>
Wheel	<b>Left hand drive</b>
Bodytype	<b>Crossover</b>
Doors	<b>4/5</b>
Drivetrain	<b>Four wheel drive</b>
Engine CO2 g/km	<b>199</b>



## Mileage



No inconsistencies found in mileage history



## Thefts



No records found



## Traffic accidents / damages



Vehicle damage records found



## Photos



No photos found

# History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2019



Service

2019-12 | Lithuania | 13 km

**Performed tasks:**

Pre-Delivery Inspection.



Technical inspection

2020-02 | Lithuania | 1 km

Technical inspection is valid until: 2023-02

Technical inspection type - new vehicle inspection:

**Without faults.**



Service

2020-11 | Lithuania | 23 958 km

**Performed tasks:**

26000 km / 12 months service.

Renewal of Oil and Oil Filter.

Renewal of Pollen Filter.

Renewal of Engine Air Filter.

Electronic Vehicle Health Check (eVHC).



Service

2021-10 | Lithuania | 49 251 km

**Performed tasks:**

52000 km / 24 months service.

Renewal of Oil and Oil Filter.

Renewal of Pollen Filter.

Renewal of Engine Air Filter.  
Renewal of Fuel Filter.  
Electronic Vehicle Health Check (eVHC).  
AdBlue Top-up (Diesel exhaust fluid).



## Accident

2022-04 |  Lithuania

### Damaged components:

Exterior lights  
Exterior body parts  
Cooling and air conditioning system



## Accident

2022-04 |  Lithuania

### Damaged components:

Glass



## Service

2022-04 |  Lithuania | 63 504 km

### Performed tasks:

Not Applicable.  
Renewal of Oil and Oil Filter.  
Renewal of Pollen Filter.  
Electronic Vehicle Health Check (eVHC).  
AdBlue Top-up (Diesel exhaust fluid).



## Accident

2022-04 |  Lithuania

### Damaged components:

Exterior body parts  
Exterior lights  
Cooling and air conditioning system



## Service

2022-11 |  Lithuania | 74 255 km

### Performed tasks:

78000 km / 36 months service.  
Renewal of Oil and Oil Filter.  
Renewal of Brake Fluid.  
Renewal of Pollen Filter.

Renewal of Engine Air Filter.  
Electronic Vehicle Health Check (eVHC).

## Technical inspection

2023-02 |  Lithuania | 80 133 km

Technical inspection is valid until: 2025-02  
Technical inspection type - periodic inspection:  
**Minor faults.**

## Service

2023-11 |  Lithuania | 98 095 km

### Performed tasks:

104000 km / 48 months service.  
Renewal of Oil and Oil Filter.  
Renewal of Pollen Filter.  
Renewal of Engine Air Filter.  
Renewal of Fuel Filter.  
Renewal of Transfer Case Fluid.  
Renewal of Alarm Handset Batteries.  
Renewal of Rear Differential Fluid.  
Electronic Vehicle Health Check (eVHC).

## Service

2024-12 |  Lithuania | 122 414 km

### Performed tasks:

130000 km / 60 months service.  
Renewal of Oil and Oil Filter.  
Renewal of Pollen Filter.  
Electronic Vehicle Health Check (eVHC).

## Technical inspection

2025-02 |  Lithuania | 126 048 km

Technical inspection is valid until: 2027-02  
Technical inspection type - periodic inspection:  
**Minor faults.**

# Mileage

Data on the fixed mileage and its changes was collected from various sources




Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.

**Data error** 

2020-02

**1 km**



# Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **3** records related to this vehicle:



## Damage registered



Date 2022-04

Country:  Lithuania

Preliminary repair cost € 10001 - € 15000 (i)


Damaged components:

Exterior lights Exterior body parts Cooling and air conditioning system

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



## Damage registered



Date

2022-04

Country:

 Lithuania

Preliminary repair cost

€ 1501 - € 3000 


Damaged components:

Glass

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



## Damage registered






Date **2022-04**

Country:  **Lithuania**

Preliminary repair cost **€ 15001 - € 20000** 

Damaged components:

   **Exterior body parts** **Exterior lights** **Cooling and air conditioning system**

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

# O<sub>2</sub> emission

How much CO<sub>2</sub> emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO<sub>2</sub> emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 

303 €



CO<sub>2</sub> emission g/km

199 g/km



CO<sub>2</sub> emission class

F



Fuel type

Diesel

CO<sub>2</sub> emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

# Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany