

## Mercedes-Benz E 300

VIN code


W1K2132531A929986


Report generated: 2025-12-02 13:16


Valid: 308 d.


# Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model  
**Mercedes-Benz E 300**

 Gearbox  
**Automatic**

 First registration year  
**2021**

 Fuel type  
**Petrol + Electric**



## Mileage



No inconsistencies  
found in mileage history



## Thefts



No records found



## Photos



No photos found

## Technical data

(Original language)

Production date	2021-01-14
Model	E 300 e Wagon
Series	E
Generation	213
Body type	CREWBUS
Type code	213
Engine code	INLINE 4-CYLINDER SPARK IGNITION ENGINE M274
Power	85
Fuel type	Petrol
Displacement	2.00
Steering side	Left
Color	Obsidian black - metallic finish
Interior	FABRIC - BLACK / ANTHRACITE
Transmission	automatic

## Equipment

(Original language)

16U	APPLE CARPLAY SMARTPHONE INTEGRATION
17U	ANDROID AUTO SMARTPHONE INTEGRATION
235	ACTIVE PARKING ASSIST
249	AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS
294	KNEEBAG
351	ECALL EMERGENCY CALL SYSTEM
362	HERMES COMMUNICATIONS MODULE LTE
475	TIRE PRESSURE MONITOR (TPM)
500	ELECTRICALLY FOLDING EXTERIOR MIRRORS
B59	DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
P44	PARKING PACKAGE
P49	MIRROR PACKAGE
U12	VELOUR FLOOR MATS
VL	LEFT FRONT AXLE HALF
VR	RIGHT FRONT AXLE HALF
287	THROUGH-LOADING FEATURE
875	HEATED WINDSCREEN WASHER SYSTEM
M20	DISPLACEMENT 2.0 LITER
M274	INLINE 4-CYLINDER SPARK IGNITION ENGINE M274
R01	SUMMER TYRES
218	Rear view camera
30P	Stowage facility package
421	9-speed automatic transmission
8U6	Assistance system steering wheel control changeover
255B	MB-Mobilo with DSB and GGD
2U8	Alternative refrigerant
725	Roof rails in chrome look
927	Exhaust treatment, Euro 6 technology
K13	Control code for service interval 25000 km
PZB	Control code for Sales
U60	Pedestrian protection - Active hood
2U1	Radiator shutter
891	PREMIUM AMBIANCE ILLUMINATION
897	FRONT WIRELESS TELEPHONE CHARGING
LS2	BODY-IN-WHITE LOAD STAGE 2
20U	KEYLESS RENTAL
365	HARD DRIVE NAVIGATION

3U6	HU COUNTRY SET FOR ECE/ROW
485	COMFORT SUSPENSION
51B	RATING, COUNTRY GROUP EURO-NCAP
8U8	I-SIZE MARKING (ISOFIX SUCCESSOR)
B51	TIREFIT
K31	NOISE REGULATIONS AS PER ECE R51-03
549	CONNECT 20 HIGH (NTG6)
8U7	REAR PASSENGER COMPARTMENT SEAT BELT WITH BELT FORCE LIMITER AND SOFTST.
B53	EXTERNAL NOISE SOUND GENERATOR FOR HYBRIDS AND EV
P65	ERGONOMICS PACKAGE
U19	AUGMENTED REALITY VIDEO
229L	GERMANY
2XXL	FEDERAL REPUBLIC OF GERMANY
332B	LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN
70B	SAFETY VEST - DRIVER
F213	MODEL SERIES 213
728	CENTER CONSOLE IN PMMA VERSION (9051)
300A	FABRIC
301A	FABRIC - BLACK / ANTHRACITE
FS	CREWBUS
L2B	LEATHER LUXURY STEERING WHEEL
469	DIFFERENT TIRE INFLATION PRESSURE
ME05	HYBRID DRIVE 85 KW-94 KW VARIANT (INCL. PLUG-IN)
O16	SOFTWARE FRESH-UP 3
H41	Trim elements - Aluminum Shine (2B51)
K37	Deactivation of locking feedback via horn
88U	Headliner, gray fabric
999	Exhaust system with OPF, generation 3.0
PVA	Control code for Sales
085	World manufacturer conversion to Mercedes-Benz AG
0B3	Vehicle production location Sindelfingen
1B3	Communication module ECE version
270	GPS aerial
299	PRE-SAFE®
580	Air-conditioning system
7B4	WIPPS countries WEU+COC
868	Central display size L
890	Automatic rear-end door

K11	Adaptive brake light, flashing
309	CUP HOLDER
14U	Smartphone integration package
197U	Obsidian black - metallic finish
355	Preinstallation for retrofitting navigation system
414	Electric sunroof, glass version
513	Road sign recognition system
U10	Front passenger seat with weight sensor
642	Dynamic LED headlamps, right-hand traffic
GH	HYBRID TRANSMISSION
76B	AC charging function single-phase/multiphase Mid (6 kW-7.7 kW)
446	Touchpad only
873	Seat heaters for driver and front passenger
234	Blind Spot Monitoring
537	DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)
N2C	Plant control code
367	Pre-installation for Live Traffic Information
876	Interior lighting package
P35	Light Package
U01	Rear seat belt status indicator
PBF	MBUX Navigation Plus
L	LEFT-HAND DRIVE
051	YoM X0/2
13U	Mercedes-Benz Connect - EV functions
38U	Services for remote access and charging plus
63B	Vehicle socket XEV Combo 2/Type 2
B30	Charging cable Schuko CEE 7/7 (Type E/F) 4M/5M
B33	Charging cable 7-pin ICCA as per IEC 62196 16A 4M/5M
431	Steering wheel gearshift buttons/steering wheel shift paddles - Electroplated
B10	Fuel tank packages for Euro-6D standard
01U	Mercedes-Benz Connect - Services for navigation
998	Control code for conversion to WLTP with RDE
258	Collision warning system with FCW-Stop active brake application
628	Automatic high beam control plus (IHC+)
801	YoM X0/1
U35	12 V socket in load compartment
R32	Light-alloy wheel 5-spoke-design 18" "mixed tires"
7U0	Alternative hood
02J	Invalid changeover of world manufacturer to Mercedes-Benz AG (ASF)

22V	Speed/load index 100Y XL + 103Y XL
502	Multi-year free map updates
02B	Operating instructions and service booklet-German
969	Euro 6 technology COC document - with motor vehicle registration certificate, part 2
P14	Equipment line/package – AVANTGARDE – Interior
P15	Equipment line/package – AVANTGARDE – Exterior
6P5	Control code for Sales
79B	Pre-installation for digital radio standard DAB/DMB
U22	Front lumbar support adjustment

# History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

☐ View original



2021



Service

2021-10 |  Germany | 24 107 km



Service

2022-10 |  Lithuania | 36 962 km



Service

2023-09 |  Lithuania | 46 552 km



Technical inspection

2024-01 |  Lithuania | 48 162 km

Technical inspection is valid until: 2026-01

Technical inspection type - periodic inspection:

**Without faults.**


# Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.





# Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

Great! We did not find any official records of damage or traffic accidents in this report.

This is often a good sign, indicating that the vehicle may not have been involved in accidents or serious incidents and was used responsibly.



However, it is important to note that not all events are always recorded in official databases. Some incidents may be unrecorded or unavailable in our information sources. The data is provided based on third-party information, so its absence in the report does not guarantee that no incidents occurred.

Therefore, as with any used car, we recommend additionally assessing the condition of the vehicle, speaking with the seller, or consulting with a specialist.

# O<sub>2</sub> emission


How much CO<sub>2</sub> emissions do vehicles of this model / year emit?



Autoistorija.It insight:

Each vehicle is assigned a CO<sub>2</sub> emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax   
0 €



CO<sub>2</sub> emission g/km  
38 g/km



CO<sub>2</sub> emission class  
A



Fuel type  
Petrol + Electric

CO<sub>2</sub> emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

# Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany