



## Mercedes-Benz E 220

VIN code

**WDD2130041A152306**

Report generated: 2025-11-24 13:18

Valid: 257 d.

# Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model  
**Mercedes-Benz E 220**

 Gearbox  
**Automatic**

 First registration year  
**2016**

 Fuel type  
**Diesel**



## Advertisements

 Sale ad records found for this vehicle



## Mileage

 No inconsistencies found in mileage history



## Thefts

 No records found



## Traffic accidents / damages

 Vehicle damage records found



## Photos

 Photos found

## Technical data (Original language)

Production date	2016-10-27
Model	E 220 d
Series	E
Generation	213
Body type	LIMOUSINE
Type code	213
Engine code	R4 DIESEL ENGINE OM654
Fuel type	Diesel
Displacement	2.00
Steering side	Left

Color	BLACK
Interior	FABRIC - BLACK/ANTHRACITE
Transmission	automatic

## Equipment

(Original language)

807	YOM 16/1
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
L	LEFT-HAND STEERING
U22	LUMBAR SUPPORT ADJUSTMENT
287	THROUGH-LOADING FEATURE
M20	DISPLACEMENT 2.0 LITER
421	9-speed automatic transmission
2U8	Alternative refrigerant
474	Diesel particulate filter
5XXL	Europe
K13	Control code for service interval 25000 km
B51	TIREFIT
P65	ERGONOMICS PACKAGE
F213	MODEL SERIES 213
300A	FABRIC
527L	Lithuania
873	SEAT HEATER FOR LEFT AND RIGHT FRONT SEATS
VR	FRONT AXLE HALF, RIGHT
VL	FRONT AXLE HALF, LEFT
FW	LIMOUSINE
21A	EHS GENERATION
5A1	ELECTROHYDRAULIC CONTROLLER UNIT-CONVERTER
6A2	JOINT FLANGE W/ GW 110 / 3, 3-ARM X 110
7A5	REAR BRACKET MADE OF PLASTIC
A104	NOISE-OPTIMIZED TOOTHING
G011	TRANSMISSION CODE VERSION 11
GA7	AUTOMATIC TRANSMISSION
U79	DIESEL EXHAUST TREATMENT BLUETEC SCR GENERATION 3
U85	LARGE SCR TANK RESERVOIR
K27	SOFTWARE CONTROL FOR FORCE-FREE IN POSITION "D"
A020	OIL OFFSET QUANTITY +200GR OIL
8U8	I-SIZE-MARKING (ISOFIX SUCCESSOR)

8U7	REAR SEAT BELT WITH BELT FORCE LIMITER AND SOFTST.
B59	TRANSMISSION MODE SELECTOR LEVER (AGILITY SELECT)
6P5	STEUERCODE VERTRIEB FUER CODE 475 ANFORDERUNG
1V2	SPEED- + LOADINDEX 97 Y
270	GPS ANTENNA
040U	BLACK
58U	ROOF INTERIOR TRIM GRAY FABRIC
824	AIR CONDITIONING SCOPES FOR COLD COUNTRIES
U01	REAR BELT STATUS INDICATION
M654	R4 DIESEL ENGINE OM654
3A1	ASSEMBLY, ACTUATORS (THREE WHEELS)
670	RESIDUAL ENGINE HEAT UTILIZATION (MRA)
968	COC PAPER EURO6 TECH. W/O REGISTRATION CERT.PART 2
258	COLLIS.WARN. SYS. W/ ACTIVE BRAKE INTERV. FCW STOP
739	TRIM PIECES - ALUMINUM
235	ACTIVE PARK ASSIST
2A8	CONVERTER VERSION 9
1A6	4-CYL. DIESEL CONVERTER
255B	MB MOBILO WITH DSB AND GGD
U10	FRONT PASSENGER SEAT WITH WEIGHT SENSING
357	SD CARD NAVIGATION
LS1	BODYSHELL LOAD STAGE 1 / 1.5
218	REAR-VIEW CAMERA
299	PRESAFE
428	STEER.WHEEL GEARSHIFT BUTTONS/SHIFT PADDLE PAINTED
475	TIRE PRESSURE CONTROL
485	(COMFORT RUNNING GEAR)
927	EURO 6 TECHNOLOGY EXHAUST GAS CLEANING
K11	ADAPTIVE STOP LIGHT FLASHING
U60	PEDESTRIAN PROTECTION - ACTIVE ENGINE HOOD
R01	SUMMER TIRES
355	PREINSTALLATION FOR NAVIGATION RETROFITTING
3U1	EUROPE/CIS COUNTRIES/MONGOLIA HEAD UNIT
294	KNEE AIRBAG
246	ANALOG CLOCK
628	AUTOMATIC HIGH BEAM SWITCH PLUS (IHC+)
840	DARK TINTED GLASS
581	Automatic climate control
876	INTERIOR LIGHT ASSEMBLY

642	Dynamic LED headlamps, right-hand traffic
877	AMBIENCE ILLUMINATION
724	ROOF RACK PREINSTALLATION
02R	17" LIGHT ALLOY WHEEL 5-SPOKE DESIGN ALL-ROUND
L3C	SPORT STEERING WHEEL - LEATHER DEEP EMBOSSED
301A	FABRIC - BLACK/ANTHRACITE
P14	AVANTGARDE PACKAGE INTERIOR
P15	AVANTGARDE PACKAGE EXTERIOR
522	AUDIO 20 RADIO NAVIGATION CAPABLE NTG5
N6A	STEUERCODE W50 FUER PPS-INT. VERWENDUNG
448	TOUCHPAD WITH ROTARY PUSHBUTTON
U12	FLOOR MATS - VELOUR
413	PANORAMIC SLIDING SUNROOF/GLASS SUNROOF
551	BASIC ANTITHEFT ALARM SYSTEM (ATA)
882	SENSOR SYSTEM AND ANTITHEFT ALARM SYSTEM
P54	THEFT PROTECTION PACKAGE
P35	LIGHT PACKAGE (FFO)
333B	INSTRUMENT CLUSTER/HU LANGUAGE - RUSSIAN
87N	STEUERCODE WERK SINDELFINGEN/GRAZ
36B	LITHUANIAN OPERATORS MANUAL AND SERVICE BOOKLET

# History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2016



We found no history events from 2016-01 to 2018-02



Service

2018-02 |  Lithuania | 19 329 km

**Performed tasks:**

Engine oil and filter change  
AdBlue® refilled  
Air filter element replacement  
Cabin filter replacement



Service

2019-03 |  Lithuania | 35 841 km

**Performed tasks:**

Engine oil and filter change  
Air filter element replacement  
Brake fluid changed  
Cabin filter replacement



Damage / repair  
assessment

2020-01 |  Lithuania

**Damaged components:**

Body parts



## Service

2020-05 |  Lithuania | 61 851 km

### Performed tasks:

Engine oil and filter change  
AdBlue® refilled  
Air filter element replacement  
Rear brake pads replacement  
Cabin filter replacement  
Fuel filter replacement



## Service

2021-05 |  Lithuania | 75 707 km

### Performed tasks:

Engine oil and filter change  
Air filter element replacement  
Brake fluid changed  
Front brake pads replacement  
Cabin filter replacement



## Technical inspection

2021-09 |  Lithuania | 83 776 km

Technical inspection is valid until: 2023-09  
Technical inspection type - periodic inspection:

**Minor faults.**



## Damage / repair assessment

2021-09 |  Lithuania

### Damaged components:

Exterior body parts



## Damage / repair assessment

2023-02 |  Lithuania

### Damaged components:

Exterior body parts



## Technical inspection

2023-09 |  Lithuania | 126 208 km

Technical inspection is valid until: 2025-09  
Technical inspection type - periodic inspection:  
**Without faults.**



We found no history events from 2023-09 to 2025-09



## Technical inspection

2025-09 |  Lithuania | 164 470 km

Technical inspection is valid until: 2027-09  
Technical inspection type - periodic inspection:  
**Minor faults.**



## Sale or auction

2025-10 |  Lithuania | 165 000 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)


# Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.It insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



# Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **3** records related to this vehicle:



## Damage / repair assessment



Date

2020-01

Country:

 Lithuania

Preliminary repair cost

€250 - €500 


Damaged components:

Body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



## Damage / repair assessment



Date

2021-09

Country:



Lithuania

Preliminary repair cost

€ 501 - € 1500 [i](#)


Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



## Damage / repair assessment



Date

2023-02

Country:



Lithuania

Preliminary repair cost

€ 1501 - € 3000 [i](#)

Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

# O<sub>2</sub> emission

How much CO<sub>2</sub> emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO<sub>2</sub> emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax   
43 €



CO<sub>2</sub> emission g/km  
137 g/km



CO<sub>2</sub> emission class  
B



Fuel type  
Diesel

CO<sub>2</sub> emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

# Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found **1** listings related to this vehicle:



## ADVERTISEMENTS

The ad is inactive

Ad has been placed:

Country

Mileage

Seller:

Seller

2025-10

 Lithuania

**165 000 km**

2025-10-17

private

identified

2025-10-17

 Photos (18)





# Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany

 United States