

Citroen C5 Aircross

VIN code

VR7ARHNSSNL054841

Report generated: 2025-12-17 14:36

Valid: 302 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

First registration year	2023
Transmission	Automatic
Engine	1199 cm³, 131 HP (96 kW)
Color	Blue
Fuel	Petrol
Wheel	Left hand drive
Bodytype	Crossover
Doors	4/5
Drivetrain	Front wheel drive
Engine CO2 g/km	147



Mileage



No inconsistencies found in mileage history, but not enough records found



Thefts



No records found



Photos



No photos found

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2023



Technical inspection

2023-09 | Lithuania | 3 km

Technical inspection is valid until: 2026-03

Technical inspection type - new vehicle inspection:

Without faults.



Service

2024-04 | Lithuania | 9 840 km

Performed tasks:

RESSORT ARRIÈRE.

INTERVEH. TIME RESPECT ASSISTANCE UNIT


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

Great! We did not find any official records of damage or traffic accidents in this report.

This is often a good sign, indicating that the vehicle may not have been involved in accidents or serious incidents and was used responsibly.



However, it is important to note that not all events are always recorded in official databases. Some incidents may be unrecorded or unavailable in our information sources. The data is provided based on third-party information, so its absence in the report does not guarantee that no incidents occurred.

Therefore, as with any used car, we recommend additionally assessing the condition of the vehicle, speaking with the seller, or consulting with a specialist.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax

43 €



CO₂ emission g/km

147 g/km



CO₂ emission class

C



Fuel type

Petrol

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany