

Toyota Corolla

VIN code

NMTBZ3BE80R064811

Report generated: 2026-01-09 11:59

Valid: 346 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Toyota Corolla

 Gearbox
Automatic

 First registration year
2020

 Fuel type
Petrol + Electric



Mileage

 No inconsistencies found in mileage history



Thefts

 No records found



Traffic accidents / damages

 Vehicle damage records found



Photos

 No photos found

Technical data

(Original language)

Production date	2020-10-12
Model	Corolla
Body type	Sedan
Type code	ZWE211
Engine code	1.8L (HEV special) (2ZR-FXE)
Displacement	1.80
Color	6X1
Transmission	Automatic
Transmission code	P610

Equipment

(Original language)

ISOL28	Immobilizer anti-theft system
FRGRA19	Fr2, rr2 assist grip
ECVECBK32	Ebd brake cont valve- edb control
WRDHO20	With cooler rear duct
BBMCO23	Black door belt moulding
WBLHE26	With emergency brake lights
RALCAIN38	Rh aiming (for lhd car) headlamp aiming
WACHC36	With (hac3) hill assist control (hac)
WRLHG21	With luggage room lamp
WIDHU27	With (7") multi info display
WCHARHP28	With cup holder rear arm rest
WLCAB31	Wvta label regulation compliancy
WOBPHS37	With (passenger only) seat back pocket
WOMTSLHT38	With outer mirror side turn signal lamp
WAWHL21	With asl speed warning
FRRA17	Fr & rr stabilizer
EMFFAL29	Ethanol min. fill washer fluid
WFLWHS30	With washer fluid level warning
FSBSNA38	Front+back sonar clearance & back sonar
FRHRC19	Fr:2 rr:2 cup holder
HMNN13	Hv engine mark
EERCL1E30	E5, e10 reg. fuel caution label
SPRA23	Smart-master 2 key plate
WFLHA17	With rear fog lamp
WDLSHO33	With d (power) seat lumbar support
PFAFLF29	Pollen filter clean air filter
WHB15	With (ahb-r) vsc
CASAPDE31	Cold area spec cold area package
WTRLSHD43	With (led type) daytime running light system
NSMF16	Normal front seat
WBLHO18	With glove box lamp
EBPK16	Epb parking brake
WWTWDHA43	With (heavy with timer) rear window defogger
NPDCMDP37	Needle punch trunk & deck carpet & mat
ETPCI30	Electric type accelerator pedal
CWMEW24	Camera + w/h back monitor
WDOPHA36	With (rear door only) child protector

PIHTG25	Plating door inside handle
FPRO16	Fr&rr door pocket
VXHTA26	Vertical x2 front headrests
MLUH24	Manual headlamp levelling
EMRVMIO32	Ec mirror inside rear view mirror
WRWHT34	With (autocut) light remind warning
WDLHW19	With power door lock
PTLSA22	Personal type room lamp
WKTHT30	Without (repair kit) spare tyre
PSSHT32	Push (with smart) starting system
PMLVDI33	Pvc (d&p mirror + light) sun visor
AMOA19	Auto (dual mode) a/c
WHS7	With abs
CBCSE37	Console box accessory connector (n0 1)
PSWIBMOSAI45	P seat with indicator air bag manual on-off sw
TDD620	T1 (8") dab 6sp audio
AMIE18	Audio + meter clock
WHHA13	With coat hook
RBIO16	Resin console box
FARRD19	Fabric door arm rest
RSPTOIA39	Resin + satin plating door trim ornament
SWDTPDGW51	Single without diffuser exhaust tail pipe & diffuser
WPLHL30	With (bulb) front personal lamp
DMSSMP32	260mm d&p manual front seat slide
GSGE025	Green 70% front side glass
SPBCCIL43	Satin plating/piano black i/p center cluster
WMLESHO46	With (room + map lamp) illuminated entry system
SWSPTT38	Soft w/ stitch (p-pad) instrument panel
AFPCSF340	Alc + fmh 3 position light control system
FROTUHWRN43	Fr & rr 4 one touch up/down hi power windows
FWSWSPCBWT45	Fab w/o stitch w/ slide p-blk rear console box
SFSPT23	6:4 split fold rear seat
PSGVY26	Privacy 20% rear side glass
TS2F16	Tss2 safety sense
FRLBWRZ40	Fr & rr (buzzer + lamp) seat belt warning
WCBHHC36	With (d+p cushion & back) seat heater
FBMMRB25	Fabric b mid seat material
WSPPBLBHT48	With satin plating + p-blk bezel shift lever boot
WPIHT36	With (meter) shift position indicator

DSHCKANH40	D&p sngl hi+sd (fr) + csa + kn srs airbag
TTCTL32	Tilt & telescopic steering column
WOL36	3-spoke,leather,heater steering wheel
DTVAAALWSPE71	Disp (h) + tel + voice + audio + acc + asl + lda steering wheel switches
COACTO36	Centre ornament (for alum) wheel cap
LGAGIT38	Laminated green 70% ac windshield glass
ESPE17	Eps power steering
CBCSE38	Console box1 accessory connector (n0 2)
RWSIO23	Rr window + sfin antenna
WUJBD16	W/ usb audio jack
L3H15	Ln1 36ah battery
RSIPSOIO38	Radiator sp + id plate + sash black out
AMBRA29	Ahb-r brake m/cylind & booster
PCOU15	Pp colour bumper
ITTRSZO42	Isize + top tether*2 child restraint system
WRACHL35	With (full range acc) cruise control
WECMHA36	With e-call data communication module
BDWKPOHYL45	Bodycolour d: w/ key p:w/o door outside handle
WSPHO20	With door scuff plate
FHWNFTRR33	Fr&rr: hard with nv felt door trim
PWFTG24	Plating door window frame
TDMGD22	Toggle dms 3 drive mode
WAMUCPHT58	With (without acoustic mat) engine under cover & protection
ETWOECOT44	Euro6d temp with obd exhaust emission control
FSRLIS35	Fr (with silencer) & rr fender liner
TFHMF227	Tex fm 520g hybrid floor mat
DHPFCAMOW48	Dilour (with heel pad) front floor carpet and mat
WMBSFLHD44	With (led + mat blk + silver) front fog lamps
DPFSBEP37	D,p: 3elr + pt + f/l*2 front seat belt
DMSVAAA42	D: 2way manual front seat vertical adjuster
DWBIB30	15" disc (b) front wheel brake
BTWLBT26	Bin type w/o lock glove box
ADSCPOA37	Auto dual + satin heater control panel
WPUCHI26	With (d, p) i/p under cover
APMCSFPIA66	Audio panel & meter cluster satin (plating) instrument finish panel
WBABDGHA46	With (plating) lower back and back door garnish
CELABDRLL46	Cable + elec lock luggage and back door release
SFRFRDTET55	Side (with felt) + rr + 1con fk luggage room & deck trim
WTHG16	With luggage tray

WMAHC25	With (ohc) mike & mike amp
EOA8	Euro ncap
WSSWHCHT50	With (with sos sw, without holder) overhead console
MOPK19	Mid package option 3
GFWFLTTCSI57	Glass fiber with felt lo package tray trim & tonneau cover
WWTPWHA39	With wrap type paint protection wax/film
BPPGCA36	Black paint + plating radiator grille
MBLGEA35	Material black radiator lower grille
PPCBAT25	Pp paint color rear bumper
VFHTA34	Vertical*2 + fixed*1 rear headrests
SBRF33	3elr-pt-fl*2 3elr*1 rear seat belt
FRSRT22	Fr & rr: satin register
SWPTAH33	Straight w/o paddle switch tronics
ADW5131	205/55r16 al-1 tire & disc wheel
WCSRHM35	With camera traffic sign recognition
WDIPWH351	With (433mhz) direct tyre inflation pressure warning
SELDLRN34	Smart entry less wireless door lock
AFEHRVMOL47	Auto fold, elec, heater outside rear view mirror
PHHHT34	Ptc heater (600w) additional heater
ASWCOI42	Auto (rain sensor) windshield wiper control
PGVY21	Privacy 20% back glass
BPLAEE25	Bi pes led + ahb headlamps
WPMSLHD45	With (led/cabin), privacy high mount stop lamp
LMLCLSP55	Led (stop/turn) + multi led (tail) rear combination lamp
KRRI23	Km/h + resin speedometer
SURPC034	Spec 1 (20mm up) rough road package
WKAHA32	With (Ita) lane keep assist (Ika)
LLKTR31	Leather (cvt) shift lever & knob

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2020



Accident

2020-12 |  Lithuania

Damaged components:

Exterior body parts



Service

2021-12 | 12 902 km

Performed tasks:

HHC.



Accident

2022-01

Damaged components:

Exterior body parts



Service

2022-12 | 23 065 km

Performed tasks:

HHC.



Service

2023-12 | 31 199 km

Performed tasks:

HHC.

Accident

2024-06 |  Lithuania

Damaged components:

Structural elements of the body
Exterior body parts
Exterior lights


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **3** records related to this vehicle:



Damage registered



Date **2020-12**

Country:  **Lithuania**

Preliminary repair cost **€ 501 - € 1500** 


Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage registered



Date

2022-01

Preliminary repair cost

€ 501 - € 1500 i


Damaged components:

Exterior body parts

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.



Damage registered



Date

2024-06



Country:

 Lithuania

Preliminary repair cost

€ 5001 - € 10000 

Damaged components:

 Structural elements of the body  Exterior body parts  Exterior lights

Minor damage usually does not affect the safety of the vehicle and does not cause structural damage.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax

0 €



CO₂ emission g/km

77 g/km



CO₂ emission class

A



Fuel type

Petrol + Electric

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany