

BMW M5

VIN code

WBSJF01050G966054

Report generated: 2025-11-06 11:40

Valid: 261 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model

BMW M5

 Gearbox

Automatic

 First registration year

2018

 Fuel type

Petrol



Mileage

 No inconsistencies found in mileage history



Thefts

 No records found



Photos

 No photos found

Technical data

(Original language)

Production date 2018-04-06

Model M5

Series M5

Generation F90

Type code JF01

Engine code S63M

Power 441

Drive type awd

Steering side Left

Color Blue-stone metallic

Interior Full leather Merino/black

Transmission automatic

Equipment

(Original language)

S06NW Telephony with wireless charging

S0654 DAB tuner

S0609	Navigation system Professional
S06AP	Remote Services
S06AN	Concierge Services
S06AC	Intelligent Emergency Call
S06AE	Teleservices
S0801	German version
S0851	Language version German
S0319	Integrated universal remote control
S0302	Alarm system
S05AC	High-beam assistant
S05AT	Driving Assistant Plus
S05AL	Active Protection
S0465	Through-loading system
S0420	Sun protection glazing
S01CA	Selection of COP-relevant vehicles
S0230	Extra package, EU-speciifc
S0248	Steering wheel heater
S02PA	Locking wheel bolt
S02VB	Tyre pressure display
S0316	automatic trunk lid mechanism
S03AC	Trailer coupling
S0428	Warning triangle and first aid kit
S0548	Kilometre speedo
S08KA	Oil service interval 24 mths / 30,000 km
S08TF	Active pedestrian protection
S09AA	Outer skin protection
S0688	Harman/Kardon surround sound system
S06AK	Connected Drive Services
S06AM	Real-Time Traffic Information
S0322	Comfort access
S08R9	Refrigerant R1234yf
S0403	Glass roof, electrical
S0879	On-board literature, German
S0552	Adaptive LED headlight
S06WD	WLAN Hotspot
S0453	Climate-controlled seats, front
S05DN	Parking assistance system Plus
S07XP	Navigation package Connected Drive
S06UK	Night Vision with person recognition

S0323	Soft-Close-Automatic doors
S02VC	Tyre repair set
S04NB	Autom. climate control with 4-zone ctrl
S04NM	Ambient Air Paket
S04T7	Massage function f.driver & fr.passenger
S04U1	Ceramic application, control elements
S04MA	M multifunction seat
S04WM	Interior trim finish.Al carb.struct.dark
S022B	BMW LA wheel double spoke styling 706M
S06CP	Smartphone Integration
S0650	CD player
SX3SW	Full leather Merino/black
S0C2Y	blue-stone metallic

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2018



Key fob mileage recording

2018-06 | Germany | 2 509 km



Service

2018-06 | Germany | 2 509 km

Performed tasks:

Service - running in check



Service

2020-02 | Germany | 29 135 km

Performed tasks:

Engine oil
Micro-filter



Service

2021-03 | Germany | 42 969 km

Performed tasks:

Brake fluid



Key fob mileage recording

2021-03 | Germany | 42 971 km

Technical inspection

2021-08 |  Lithuania | 44 851 km

Technical inspection is valid until: 2023-08

Technical inspection type - periodic inspection:

Without faults.

Key fob mileage recording

2022-02 |  Lithuania | 52 529 km

Service

2022-02 |  Lithuania | 52 644 km

Performed tasks:

- Engine oil
- Air filter element
- Vehicle inspection
- Spark plugs
- Micro-filter

Service

2023-05 |  Lithuania | 67 463 km

Performed tasks:

- Brake fluid
- Bonnet gas struts check

Technical inspection

2023-08 |  Lithuania | 70 555 km

Technical inspection is valid until: 2025-08

Technical inspection type - periodic inspection:

Without faults.

Service

2023-08 |  Lithuania | 70 839 km

Performed tasks:

- Engine oil
- Micro-filter



Key fob mileage recording

2023-09 | Lithuania | 72 473 km



Key fob mileage recording

2024-12 | Lithuania | 84 685 km



Service

2025-01 | Lithuania | 85 251 km

Performed tasks:

- Bonnet gas struts check
- Brake fluid
- Rear brakes



Service

2025-07 | Lithuania | 92 406 km

Performed tasks:

- Spark plugs
- Micro-filter
- Engine oil
- Vehicle inspection
- Air filter element



Technical inspection

2025-08 | Lithuania | 92 703 km

Technical inspection is valid until: 2027-08

Technical inspection type - periodic inspection:

Without faults.


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

Great! We did not find any official records of damage or traffic accidents in this report.

This is often a good sign, indicating that the vehicle may not have been involved in accidents or serious incidents and was used responsibly.



However, it is important to note that not all events are always recorded in official databases. Some incidents may be unrecorded or unavailable in our information sources. The data is provided based on third-party information, so its absence in the report does not guarantee that no incidents occurred.

Therefore, as with any used car, we recommend additionally assessing the condition of the vehicle, speaking with the seller, or consulting with a specialist.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.lt insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 

260 €



CO₂ emission g/km

241 g/km



CO₂ emission class

G



Fuel type

Petrol

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:



Lithuania



Slovenia



Slovakia



Czech Republic



Hungary



Italy



Romania



Germany