

Volkswagen Arteon

VIN code


WVWZZZ3HZJE501783


Report generated: 2026-01-15 11:57


Valid: 352 d.


Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Volkswagen Arteon

 Gearbox
Automatic

 First registration year
2017

 Fuel type
Diesel



Mileage



No inconsistencies
found in mileage history



Thefts



No records found



Photos



No photos found

Technical data

(Original language)

Production date	2017-06-20
Model	Arteon RLine 176 TDID7A
Series	Arteon
Type code	3H749T
Engine code	CUAA 4-cylinder diesel engine 2.0 l TDI, 176 kW
Power	176
Fuel type	Diesel
Displacement	2.00
Steering side	Left
Color	Oryx White Mother-of-Pearl Effect/Oryx White Mother-of-Pearl Effect
Interior	Black-Titanium Black/Titanium Black/ Titanium Black
Transmission	automatic
Transmission code	RWU

Equipment

(Original language)

PE0A	No special edition
P0F5	Fuel system for diesel engine
P1SA	Without additional front underbody guard
P0Y3	Cold zones
P2JX	Comfort bumpers
PKK3	Refrigerant R1234yf
P3LJ	Door and side trim panel in foam film, insert in leatherette
PKS0	Without head-up display
PFN7	Variant
P3FA	Without roof insert (standard roof)
P3W6	Additional interior noise suppression
P4D0	Without seat ventilation/massage seat
P5C0	Without special body measures
P7ZS	Vehicle class differentiation -3H0-
P7MM	Emission standard EU6 plus
P8FC	Installation of SLI battery in rear, without second battery
PQH0	Without voice control
PEF1	ECO function
PFC1	Customized installation
PF0A	No special purpose vehicle, standard equipment
PS0C	Introductory volume
PQA0	Without child seat
P0FA	Standard manufacturing sequence
P5K7	Transport protection film (minimum protection) with additional transport protection measures
P1S1	Tool kit and jack
P2WA	Without additional tires
P7G0	Without preparation for VTS (vehicle tracking system)
P8GV	Alternator 180 A
P3H0	Without backrest release for front seats
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
PL47	Suspension range 47 installation control only, no requirement forecast
P6A0	Without fire extinguisher
P0YG	Weight range 7 installation control only, no requirement forecast
P1JP	Rear shock absorption
P0VV	Information kit in Swedish
P0P0	Rear exhaust tailpipe (standard)
P8Y1	Two-tone horn
PC01	Operating permit, alteration

PEV0	Without charging cable
PAV1	Driving on the right
PSV3	Control (in-plant)
PNY0	Standard battery/alternator capacity
PES0	Without vehicle inlet
P1Z2	Increase in initial standard fuel filling
P2A0	Without delivery equipment
P7U0	Standard engine starter
P9D0	Without preparation for two-way radio installation
P1Q2	Mass damper for steering wheel, 36 Hz
PA62	Category 2
P0M4	Fuel tank
PPW9	Parking heater and ventilation with radio remote control and timer
P0B5	Wheelbase
PTS3	4-cylinder diesel engine 2.0 l
P1X1	Four-wheel drive
P4ZB	Chrome moldings on the side windows
P7L6	Start-stop system with generative braking
P8G0	Without light control
P8RM	8 speakers
P8X1	Headlamp washer system
PA8F	Sports equipment
PEM1	Driver alert system
PG1D	7-speed automatic or DSG for four-wheel drive note: family EDF
PL0L	Left-hand drive
PQG1	LongLife Service Regime
PQI6	Service indicator 30 000 km or 2 years (variable)
PQV0	Without TV reception/digital radio reception
P6Q2	Gearshift knob in leather
P7K1	Tire pressure monitoring system
P0K0	Without alternative drive system
P0NB	Elimination of nameplate for engine designation on luggage compartment lid
P1AT	Electronic Stability Control w/ driver steering recommendation, ABS, ASR, EDL, EDTC and trailer stabilization
P1E9	Without activated carbon canister with SCR
P1NL	Trims for alloy wheels
P1PE	Wheel locks with extended theft protection
P20A	Without electric motor (hybrid)
P31K	License plate carrier in front and rear (ECE)

P3QT	3-point seat belts in front with height adjustment and seat belt pretensioners
P3T2	3 head restraints in rear
P4A4	Heated front and outer rear seats
P4L6	Auto-dimming interior rearview mirror
P4X3	Curtain airbag system for front and rear passengers incl. side airbags in front
P5RQ	Right exterior mirror, convex
P5SL	Aspherical exterior mirror on driver side
P5XJ	Illuminated vanity mirrors in sun visors
P7X5	Park Assist with Park Distance Control
P8N6	Rain sensor
P8T8	Adaptive Cruise Control ACC stop & go incl. speed limiter
P8TB	Rear fog lamp
P9T1	Automatically-heated washer nozzles in front
PQK1	Multifunction camera
PUH2	Electromechanical parking brake with Auto Hold function
P0SC	Labels in English
P0TE	Carpet mats in front and rear with decorative stitching
P1G8	Tire Mobility Set: 12-volt compressor and tire sealant
P1N7	Progressive steering
P1Y3	Electronic differential lock XDS
P2I0	Adaptive Chassis Control DCC
P3D3	Decorative inserts "Piano Black" for center console
P3GA	Luggage compartment floor
P3KB	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest and load-through hatch
P3U1	Luggage compartment cover
P3Y0	Without roll-up sunshade
P4B4	Lower side trims in chrome
P4GF	Heat-insulating windshield
P4UN	Driver and front passenger airbag with front passenger airbag deactivation, including knee airbag on driver side
P4V0	Without front passenger seat control
P5I6	Easy Open - sensor controlled luggage compartment opening and delayed electric closing, with remote unlocking
P6SE	Textile luggage compartment trim
P6T1	2 LED light units in front footwell
P7B6	12-V outlet in center console in rear
P7E0	Without heat accumulator/auxiliary heater
P8IU	LED headlamps for low beam and high beam, with LED separate daytime running light and dynamic cornering light

P8K3	Aut. headlight control w/ separate daytime running light, Leaving Home and manual Coming Home feature
P8Q5	Dynamic headlight range control, with dynamic cornering light
P8S7	Interior lights with switch-off delay and dimmer, 2 LED reading lights each in front and rear
P8SH	LED rear combination lamps, with dynamic turn signal
P8WM	Cornering light and poor weather light
P9P9	Warning signal and warning light for front and rear seat belts not fastened
P9S8	Multi-color Active Info Display, selection of different info profiles possible
P9TJ	LED entry/warning lights in front doors
PGM1	Standard electronic engine sound
PGP0	Vehicles without special upgrade measures
PI8F	Radio "Composition Media"
PK8C	Coupe
PPA6	Ambient lighting
PQJ3	Chrome elements on door pulls, on the rotary light switch and on the front vents
PQQ9	Ambient lighting (three-color)
PUG6	Hill Start Assist
PUP0	Analog clock in dashboard
PVC0	Without garage door opener
PVF1	Pedals in brushed stainless steel
PVL4	Pedestrian monitoring and re-active hood
PWLH	LED headlamps
P5ZF	Safety-optimized front head restraints
PKA2	Rear view camera system
P7P7	Lumbar supports in front, power-adjustable on driver side
PV0A	Tires without specification of tire brand
P7W2	Proactive passenger protection system in combination with Front Assist
P7UF	Navigation system "Discover Media" with TFT touch screen
PUQ2	2 USB interfaces, also for iPod/iPhone, 1 USB charging socket and AUX-IN jack
PU5A	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
P0EX	Dual-clutch transmission DSG DQ500
P3ZU	3-point seat belts in rear incl. seat belt pretensioner for the outer seats
PQ4H	Top comfort seats, in front
PSX8	Model update, week 22
P9JA	Non-smoker's package: 12-V outlet in front
P3A0	ISOFIX anchorage points for mounting 2 child seats on rear seats, also for i-Size child seats
P9WX	App-Connect and "Volkswagen Media Control"
PJ0B	Battery 520 A (92 Ah)

PQ48	AirStop® tires 245/40 R19
PKH7	Air Care Climatronic 3 zone automatic climate control with allergen filter and controls in the rear
PG12	Shock absorption in front
P4F2	Keyless locking and starting system Keyless Access with SAFELOCK
P7AL	Anti-theft alarm system with interior monitoring, backup horn, and towing protection
P1EX	Special identification label for EC for M1 passenger vehicles
PER1	Regional code " ECE " for radio
P1T3	First aid kit and warning triangle
P1LA	Disc brakes in front
P2PK	R-Line leather-wrapped multi-function sports steering wheel, with shifting paddles
P1KZ	Disc brakes in rear
P5TE	Decorative inserts in aluminum "Silver Rise" for dashboard and door trim panels
P6NW	Titanium Black headliner
P6K4	Forward Collision Warning Front Assist Autonomous Emergency Braking (for Adapt.Cruise Control ACC up to 210 km/h)
P7RE	Navigation data for Western Europe on SD card
PPND	Navigation feature "Discover Media" (for "Composition Media")
P1M6	Folding trailer hitch, with electric release
P3PW	Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment
P8ZQ	Diversity antenna for FM reception
P9ZE	Mobile phone interface "Comfort"
P6XI	Ext. mirror w/ surround lighting a. fr. passenger ext. mirror lowering funct., folding/heated, auto-dimming on dr. side
PPEL	Easy Open package incl. SAFELOCK
PQR9	Dynamic Road Sign Display
PEL5	Online service, with OCU, with head unit coding, without engine immobilizer interconnection
P45T	4 alloy wheels "Montevideo" 8J x 19, black, diamond-turned surface
P6E3	Front center armrest with storage compartment, 2 rear vents
P7M9	Scuff plates w/ stainless steel inserts and "R-Line" logo
PPJW	Montevideo 8J x 19, Black, diamond-turned surface, Volkswagen R, AirStop® tires 245/40 R19
PW12	VE: NCAP package
PW17	VE: Lights & Vision package, LED High without high-beam control Light Assist
PWD5	Anti-theft alarm system
PWQ3	Dynamic Road Sign Display in combination with driver assistance package or "Business Premium" package
PNZ4	Emergency call service, contract dur. 10 years; no registration required, service is activated upon delivery
PPAP	Acoustics package

P9M9	Parking heater and ventilation with radio remote control and timer
PB07	Type approval country Sweden
PX1D	Equipment options subset for Sweden
P8D5	Non-hot country plus auxiliary radiator
P9Z3	230-V outlet in center console in rear
P79D	Emergency Assist, Traffic Jam Assist, Rear Traffic Alert, Side Assist Plus incl. Lane Assist
PN7N	Inserts in Alcantara, inner sides of bolsters in leather "Vienna"
PYOZ	Guide & Inform and Security & Service Plus, contr.dur.:3 years incl. Security & Service Basic,contr. dur. 10 years
PPTO	Mobile phone interface "Comfort"
PPW3	Winter package for leather package
PB0H	Part set, complying with vehicle type for Sweden, various parts
PDK9	4-cylinder diesel engine 2.0 l TDI, 176 kW
PVW5	Sound-insulating windows in laminated safety glass, 65% light-absorbing glass in rear window and rear side windows
PW50	SE: Load package forces 1M6, KA2
PW52	SE: Executive package Elegance forces WLH,WL6,PA6 2ZD,PEL,5MD R-Line forces WLH,PA6,PEL,5TE
L0K1/	Oryx White Mother-of-Pearl Effect/Oryx White Mother-of-Pearl Effect

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

☐ View original



2017



Pre-registration check

2017-08 |  Sweden



Change of ownership

2017-08 |  Sweden



Change of ownership

2017-09 |  Sweden



First registration

2017-09 |  Sweden



Change of ownership

2018-10 |  Sweden



Service

2019-01 |  Sweden | 24 942 km



Service

2019-01 |  Sweden | 27 454 km

Performed tasks:

Inspection with Oil change (flexible).



Change of ownership

2019-05 |  Sweden



Service

2020-03 |  Sweden | 55 385 km



Technical inspection

2020-08 |  Sweden | 63 997 km



Technical inspection

2020-08 |  Sweden | 64 235 km



Technical inspection

2022-06 |  Sweden | 95 994 km



Change of ownership

2022-12 |  Sweden



Change of ownership

2023-04 |  Sweden



**Deregistration
(temporary or
permanent)**

2023-08 |  Sweden



Service

2024-07 |  Lithuania | 134 620 km

Performed tasks:

Inspection with Oil change (flexible).

Brake fluid service.

Gearbox oil.

Diesel fuel filter.

Dust and pollen filter.

Air cleaner element.

Oil for all-wheel drive coupling.

Additional Inspection scope.


Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages

Great! We did not find any official records of damage or traffic accidents in this report.

This is often a good sign, indicating that the vehicle may not have been involved in accidents or serious incidents and was used responsibly.



However, it is important to note that not all events are always recorded in official databases. Some incidents may be unrecorded or unavailable in our information sources. The data is provided based on third-party information, so its absence in the report does not guarantee that no incidents occurred.

Therefore, as with any used car, we recommend additionally assessing the condition of the vehicle, speaking with the seller, or consulting with a specialist.

O₂ emission

How much CO₂ emissions do vehicles of this model / year emit?



Autoistorija.It insight:

Each vehicle is assigned a CO₂ emission class (from "A" to "G") based on the amount of emissions it produces.



Pollution tax 
130 €



CO₂ emission g/km
152 g/km



CO₂ emission class
C



Fuel type
Diesel

CO₂ emission (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany