

Moller Auto



Coming soon

Audi e-tron

VIN code

WAUZZZGE3LB026293

Report generated: 2025-04-15 10:58

Valid: 22 d.

Information

Basic data of the inspected vehicle and summary of inquiries.

 Make, model
Audi e-tron

 Gearbox
Automatic

 First registration year
2021

 Fuel type
Electric



Advertisements

 Sale ad records found for this vehicle



Mileage

 Inconsistencies found in mileage history



Thefts

 No records found



Traffic accidents / damages

 Vehicle damage records found



Photos

 Photos found

Technical data

(Original language)

Production date	2020-02-14
Model	e-tron Spb 300
Series	e-tron
Type code	GEACAE
Engine code	EASA Electric motor, total system output 300 kW base motor is N02/T68/T83/T0B/T67
Power	300
Fuel type	Electric
Steering side	Left
Color	Myth Black Metallic

Interior	Black-Black-Rock Gray/Black-Black/ Black/Moon Silver
Transmission	automatic
Transmission code	UDE

Equipment (Original language)

PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PE0A	No special edition
PC08	Operating permit, alteration
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PJ2D	Battery 380 A (68 Ah)
P1D0	Without trailer hitch
P0YR	Weight range 16 installation control only, no requirement forecast
P1S1	Tool kit and jack
P1I0	Passenger presence detection
P0Y3	Cold zones
P1SA	Without additional front underbody guard
P6F7	Emblems
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
PGZ0	Manually operated doors
P0FA	Standard manufacturing sequence
P5C0	Without special body measures
P7A0	Without CD changer/CD player
P7G0	Without preparation for VTS (vehicle tracking system)
P8Y1	Two-tone horn
PKS1	Head-up display
P0JM	Weight category front axle weight range 12
P4D0	Without seat ventilation/massage seat
P8IY	LED headlamps with lens
PGS5	Operating buttons in Black glass look with haptic feedback and extended aluminum look
P3CA	Without partition
P5J4	Body-colored rear spoiler
PKB3	Battery charger (type 3)

P0K9	Drive system BEV
PK5B	Body style variant 2
P3BA	Without left exterior mirror
PT4K	Electric motor units 0EF.A and 0EF.B
P0TD	Floor mats in front and rear
P2Z8	Model designation as per new engine power designation
P3B3	ISOFIX child seat anchors and top tether for the rear bench seat
P3G4	ISOFIX child seat anchors for front passenger seat
P4E7	Luggage compartment lid, electrically opening and closing
P4L6	Auto-dimming interior rearview mirror, frameless
P4UF	Driver and front passenger airbag with front passenger airbag deactivation
P5XC	Sun visor on driver and front passenger side
P5ZF	Head restraints in front
P6FA	Exterior mirror housings painted in body color
P6K8	Audi pre sense front
P6NQ	Headliner in Black fabric
P6SS	Luggage compartment floor mat
P7AL	Anti-theft alarm system
P7P1	4-way lumbar support for the front seats
P7UG	MMI navigation plus with MMI touch response
P7W3	Audi pre sense rear
P7Y1	Lane change assistant with exit warning system and rear cross traffic alert
P8T5	Adaptive cruise control with speed limiter, efficiency assist, swerve assist and turn assist
P9B0	Without integrated toll system
P9PA	Standard wiper arms and blades
P9R0	Without night vision
P9S9	Audi virtual cockpit Plus
P9WC	Without "Multimedia" in vehicle
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PGJ0	Without combined lateral and longitudinal control
PGM0	Without acoustic vehicle alerting system
PGP0	Vehicles without special upgrade measures
PIU1	Audi smartphone interface
PIW3	Audi connect Emergency Call & Service with Audi connect Remote & Control
PJX1	Front cross traffic assist
PKA6	360-degree cameras
PL0L	Left-hand drive

PQK1	With multifunction camera
PVC0	Without garage door opener
PVT5	Scuff plates with aluminum inserts in front and rear, illuminated, with "S" logo in front
PVW0	Acoustic glass for door and side windows
P3S0	Elimination of roof rails
P4A3	Seat heaters in front
P5K5	Adhesive film
PQE1	Storage and luggage compartment package
PS9T	Special vehicle for launch
P1X1	quattro
P2C7	Electric steering wheel adjustment
P3Y0	Without roll-up sunshade
P8K1	Separate daytime running light
P4GF	Windshield with acoustic glass
P6E3	Comfort center armrest in front
PQ4Q	S sports seats in front
P2K7	S line bumpers
P3L4	Power front seats with memory feature for the driver seat
P9AQ	4-zone climate control system
P9X0	Parking aid Plus with 360° display
P9ZE	Audi phone box
PEL3	Audi connect Navigation & Infotainment
PFT0	Without parking assistance/garage parking assist
PQZ7	Progressive steering
PQQ2	Contour/Ambient Lighting package, multi-color
P2V5	Without air quality package
PA8Y	S line
P3F1	Collapsible spare tire
PUF8	Audi music interface in the rear seat area
PI8T	MMI Radio plus with MMI touch response
P6XL	Exterior mirrors, power-adjustable, heated and power-folding, auto-dimming on both sides, with memory feature
P8G4	Matrix LED headlamps with dynamic light design and dynamic turn signal
P1PR	Anti-theft wheel bolts and loose wheel warning
P7K3	Direct tire pressure monitoring system
P0GA	Without specific emission standard
P70T	Household plug Type E/F for the e-tron charging system
P9VS	Bang & Olufsen premium sound system with 3D sound
PEH1	Vehicle charging cable

PGA2	Comfort stationary air conditioning
PJS1	Second charging access
PNW1	e-tron charging system "compact"
P1EX	Special identification label (EU)
PER1	Regional code " ECE " for radio
P31K	License plate carrier in front and rear (ECE)
P9JA	Non-smoker package
PGB1	LTE support for Audi phone box
PWQS	"S line" interior
P1TX	Vehicle class differentiation -4KE/4KH-
P1ZT	Disc brakes in front, 18-inch, brake calipers painted in Orange with "e-tron" lettering
P2EJ	Disc brakes in rear, 18-inch, brake calipers painted in Orange
P2MB	adaptive air suspension - sport
P2ZQ	Leather-wrapped multi-function steering wheel, double-spoke, with shift paddles
P3AA	Virtual exterior mirrors
P3U4	Manual luggage compartment cover
P4X9	pre sense package for rear compartment
P5TG	Decorative inserts in Matte Brushed Aluminum, dark
P6I6	Adaptive cruise assist with emergency assist
P76H	Mode 3 charging cable for public charging 22 kW
P7B3	12-volt outlet
P7HD	Upper part of dashboard and lower interior elements in leather
P9TF	Door entrance LED projector lights in front and rear
PES7	Vehicle inlet CCS type 2
PFP1	Preparation for features on demand
PG1Z	Transmission for electric drive (1-speed)
PH9Q	Tires 265/45 R21 108H xl
PJE3	Data module for Europe
PN2R	Valcona leather with embossed "S"
PNJ2	Wall bracket
PPAF	Virtual exterior mirrors
PPCC	Tour assistance package
PPCM	City assist package
PPCZ	360-degree cameras
PPX6	Matrix LED headlamps, LED rear combination lamps and headlamp washer system
PQL5	Privacy glass (dark-tinted windows)
PQR9	Camera-based traffic sign recognition
PVI9	Service indicator 30 000 km or 2 years (fix) electric vehicle
P73P	Industrial plug CEE 16 A, 400 V, long and straight, for the e-tron charging system

PPV3	Power seats in front including memory feature for the driver seat
PQ0D	Preparation for digital radio reception for function-on-demand feature
P1T3	First aid kit with warning triangle and safety vests
P4ZD	Black Styling package
P7E4	Increased heat output
PPC2	Brake calipers painted in Orange (18-inch)
P4F2	Comfort key with SAFELOCK
PPG3	Comfort key in combination with anti-theft alarm system with towing protection
PX7Y	Equipment options subset for export (others)
PPIH	Child Safety package
P2F1	Audi connect key
PIT1	Audi connect Navigation & Infotainment
P3FU	Panoramic glass roof
PYCL	Ramp-up scenario L
PB72	Type approval country Lithuania
P47B	Forged alloy wheels, 5-arm turbine style, Glossy Black, partly polished, 9.5J x 21, 265/45 R21 tires
PI4M	With special labels safety certificates for Lithuania
PM1J	Electric motor, total system output 300 kW base motor is N02/T68/T83/T0B/T67
P0XR	Manual in Lithuanian

History

Find different types of vehicle history records in the timeline.

Please note: Information texts written in other languages have been translated. You can choose to view them in the original language.

View original



2020



Service

2020-08 |  Lithuania | 43 km

Performed tasks:

unknown_service



Service

2020-11 |  Lithuania | 278 km

Performed tasks:

unknown_service



Service

2021-02 |  Lithuania | 43 km

Performed tasks:

check_service



Technical inspection

2021-02 |  Lithuania | 5 km

Technical inspection is valid until: 2024-02

Technical inspection type - new vehicle inspection:

Without faults.



Sale or auction

2021-03 |  Lithuania | 27 832 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)



Service

2021-08 |  Lithuania | 12 660 km

Performed tasks:

unknown_service



Service

2021-11 |  Lithuania | 20 290 km

Performed tasks:

unknown_service



Service

2022-03 |  Lithuania | 27 782 km

Performed tasks:

unknown_service



Service

2022-03 |  Lithuania | 28 751 km

Performed tasks:

check_service

Filters

unknown_service



Damage / repair assessment

2023-01 |  Lithuania



Sale or auction

2023-01 |  Lithuania | 49 000 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)



Sale or auction

2023-07 |  Lithuania | 59 000 km

An online ad has been placed for the sale of this vehicle.



[More information »](#)



Technical inspection

2023-09 |  Lithuania | 48 580 km

Technical inspection is valid until: 2025-09

Technical inspection type - periodic inspection:

Without faults.

Mileage

Data on the fixed mileage and its changes was collected from various sources



Autoistorija.lt insight:

Our data is sourced from various official data sources, but we still recommend performing a professional car inspection with specialists.

Mileage decrease


2021-08

12 660 km

Mileage decrease

2023-09

48 580 km



Traffic accidents/damages

Data collected from various sources on fixed traffic incidents/damages



Important before assessing damage:

Not all records in the report indicate an actual consequence of damage or a traffic accident.


Some records may appear not due to the damage itself, but as a result of damage assessments, residual value calculations, insurance company processes, costly repair works, inspections, diagnostics, pre-sale evaluations, or other formal procedures.

[Read more »](#)

We found **1** records related to this vehicle:



Damage / repair assessment



Date

2023-01

Country:



Lithuania

Preliminary repair cost

€0 - €500

Sales information

Information on vehicle ads found. Sale time, price change, information about the seller.

We found **3** listings related to this vehicle:



ADVERTISEMENTS

Ad has been placed: **2021-03-28**

The ad is inactive



Lithuania

Mileage

27 832 km

2021-03-28

Seller: **business**

2021-03-28

[Photos \(2\) »](#)

Moller Auto

Keturi žiedai



Moller Auto

Keturi žiedai



ADVERTISEMENTS

Ad has been placed: **2023-01-18**

The ad is inactive



Lithuania

Mileage

49 000 km


2023-01-18

Seller: **business**

 Seller identified

2023-01-18

Photos (32) »



ADVERTISEMENTS

Ad has been placed: **2023-07-26**

The ad is inactive

 **Lithuania**

Mileage

59 000 km

2023-07-26

Seller: **business**

2023-07-26

Photos (2) »

Moller Auto

Coming soon



**Atli Audi automobiliai
antija iš oficialaus atstovo**

Įvairius naudotų Audi bei kitų gamintojų naudotų
automobilių pasirinkimas

Įsigysite geras sąlygas dabartinio jūsų
automobilio atpikimui ir įsigyto automobilio
naudimui.

Įsi mūsų automobiliai yra patikrinti oficialiame
įrvisse su gilia serise istorija. Garantuojame tiera
automobilio rida.

2 mėnesių arba 20 000 km garantija Audi
audotiem automobiliams iki 5 metų arba iki
50 000 km rida.



Mantas Petkevicius
Naudotų automobilių
pardavimo vadybininkas
+370 616 70238
mantas.petkevicius@moller.lt



Artūras Sobolia
Naudotų automobilių
pardavimo vadybininkas
+370 614 29762
arturas.sobolia@moller.lt



Mažvydas Bernikis
Naudotų automobi
pardavimo vadybi
+370 651 16927
mazvydas.bernikis



Theft check

Information from police and other databases about whether the car is wanted.



No records were found indicating that the vehicle has been stolen.

Searches for potential vehicle thefts were conducted in the databases of the following countries:

 Lithuania

 Slovenia

 Slovakia

 Czech Republic

 Hungary

 Italy

 Romania

 Germany