



Audi A4

VIN kodas

WAUZZZF42RA015017

Sugeneruota: 2025-12-23 11:44

Galioja: 308 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Audi A4

 Pavarų dėžė
Automatinė

 Pirmos registracijos metai
2024



Skelbimas



Rasta įrašų apie automobilio pardavimą



Rida



Nerasta neatitikimų ridos istorijoje



Vagystės



Įrašų nerasta



Žalų / remontų vertinimas



Rasta informacijos apie automobilio pažeidimus



Nuotraukos



Rastos istorinės automobilio nuotraukos

Automobilio techninė informacija

(Originalo kalba)

Production date	2023-09-15
Model	A4 Sedan 2.0 R4110 A7
Series	A4
Type code	8WCA7G
Engine code	DMSB 4-cylinder SI engine 2.0 l/110 kW (16V) turbo FSI, homogeneous base engine is T2J/T5H/T4X
Power	110
Fuel type	Petrol
Displacement	2.00
Drive type	FWD

Steering side	Left
Color	Brilliant Black/Brilliant Black
Interior	Cedar Brown-Cedar Brown-Granite Gray/ Black-Black/Black/Black
Transmission	automatic
Transmission code	VKK

Automobilio komplektacija (Originalo kalba)

PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PE0A	No special edition
PFU0	Country group A
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PIX1	SI engine
PJ2D	Battery 380 A (68 Ah)
P0C0	Standard
PVF0	Standard pedal cluster
P0UA	Without special color trim
P1D0	Without trailer hitch
P1PA	Standard wheel bolts
P0YF	Weight range 6 installation control only, no requirement forecast
P0Y3	Cold zones
P1SA	Without additional front underbody guard
P3FA	Without roof insert (standard roof)
P1Z5	Increase in initial standard fuel filling
P3H0	Without backrest release for front seats
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P8Z5	Not hot country
P7Y1	Side Assist
P7P0	Without lumbar support in seat backrests
P8G1	High beam assistant
P0FA	Standard manufacturing sequence
P0G7	Tiptronic
P1A2	Fuel system for SI engine with direct injection (FSI)

P5C0	Without special body measures
P5J0	Without rear spoiler
P6V1	Rear trim panel (ECE)
P6W6	Front license plate carrier
P7G0	Without preparation for VTS (vehicle tracking system)
P8Y1	Two-tone horn
PA00	No self-collection
PGP1	Vehicles with special upgrade measures
PGW0	Without Car2X
PKS0	Without head-up display
PK8B	Notchback
PNM1	Engine cover
PM3I	4-cylinder SI ENGINE 2.0 l/110 kW (16V) turbo FSI, homogeneous base ENGINE IS T2J/T5H/T4X
PNT0	Transit coating (type 1)
PVH0	Standard electric
PNY0	Standard battery/alternator capacity
P04A	Basic
P0RZ	Without ignition/starter switch locking system, without steering lock
P0JG	Weight category front axle weight range 7
PS3Y	Control of special edition prices
P2G1	Insert for the filling up of unleaded fuel
P6JD	Body-colored door handles
P1VG	Installation parts for four-cylinder engine
P3M3	Passenger car design
P6EA	Without additional side body covers (stone guard)
P4D0	Without seat ventilation/massage seat
P5L0	Without front spoiler
P9TA	Without additional warning lights
PC26	Operating permit, alteration
PT2A	4-cylinder SI engine 2.0 l unit 06N.A 888evo4
P0K4	Mild hybrid
P0P0	Standard exhaust system
P2F0	Without locking and starting systems
P2KR	Labels in English and German
P5SL	Left exterior mirror, aspherical
P7E0	Without heat accumulator/auxiliary heater
P9B0	Without integrated toll system
P9P6	Seat belt reminder

P9S9	Audi virtual cockpit Plus
P9VD	Audi sound system
P9WC	Without "Multimedia" in vehicle
P9ZX	Bluetooth interface
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PGA0	Without preconditioning
PGB0	Without antenna amplifier
PIW3	Audi connect Emergency Call & Service with Audi connect Remote & Control
PL0L	Left-hand drive
PQK1	With multifunction camera
PQQ2	Ambient Lighting package plus
PQZ7	Electromechanical power steering
PV0A	Tires without specification of tire brand
PVC0	Without garage door opener
P1X0	Front-wheel drive
P4H5	Power-operated child safety lock
P5K5	Adhesive film
P6F0	Without decorative films/emoles
P7S0	Without wind deflector
P9K0	Without neck heating
P9M0	Without auxiliary heater/parking heater
PU5A	Instrument cluster, km/h speedometer
P5A8	Luggage compartment trim (design 2)
PYEA	Internal control code
PG1C	S tronic
P3GA	Without luggage/load compartment floor
P3Y0	Without roll-up sunshade
P7AL	Anti-theft alarm
P8K1	Separate daytime running light
P4E2	Luggage compartment lid, automatically opening
P6K8	Audi pre sense city
P7IA	Vehicle class differentiation -8W0/8WA-
PGH0	Without rear differential
P6SS	Luggage compartment mat
PVL1	Extended pedestrian protection
P3NT	Split-folding rear seat backrest
P6H0	Roof in body color

P9G9	Belt-driven integrated starter alternator 12 V, 130 - 200 A
PA9F	A4
P1BA	Standard suspension
P4GF	Windshield with heat-reflecting glass and acoustic glass
PYEB	Internal control code
P8X0	Without headlamp washer system
PUH1	Electromechanical parking brake
P6XD	Exterior mirrors, electrically adjustable and heated
P1EX	Special identification label (EU)
P6FA	Exterior mirror housings in body color
PER1	Regional code " ECE " for radio
PQI6	Service indicator 30 000 km or 2 years (variable)
PQV3	Digital audio broadcasting
PQE0	Without Storage package
PQR9	Camera-based traffic sign recognition
P7W3	Audi pre sense rear and basic
PYEG	Internal control code
P6Y6	Top speed limited to 210 km/h
P6I3	Lane departure warning
P2H0	Without Audi drive select
PA61	Top speed limited to 210 km/h
PPIH	Child Safety package
PIT6	Audi connect Navigation & Infotainment on demand
P2K1	Bumpers
PB72	Type approval country Lithuania
PWK8	Interior design selection
PIU1	Smartphone interface
PI4M	With special labels safety certificates for Lithuania
PGV0	Without alcohol interlock
PX79	Equipment options subset for ROW/Europe
P0XR	Manual in Lithuanian
P4WH	Emission standard, EU6 EA lambda = 1 WLTP3 M1, N1-I
PS18	Deviating installation
PNI0	SWIN management
P0TD	Floor mats, front and rear
P1G8	Tire repair kit
P1S2	Vehicle tool kit
P1T3	First-aid kit with warning triangle and high-visibility vests
P1KD	Disk brakes, rear, 16-inch (ECE)

P1LA	Disk brakes, front, 16-inch (ECE)
P1XW	Leather steering wheel, 3-spoke with multifunction plus
P0M1	Fuel tank with increased capacity
PQ1D	Sport seats, front
PQL1	Rear window, rear door and side windows in clear glass
P6E3	Comfort center armrest, front
P6NJ	Headlining in cloth in specific color
P2Z7	Omission of output/technology logo
P3G4	ISOFIX child seat mounting for the front passenger seat
P3B3	ISOFIX child seat mounting and top tether for the outer rear seats
P3PB	Driver seat, electrically adjustable
P5ZF	Head restraints, front
P7L8	Start-stop system
P9JA	Non-smoker version
P4A3	Seat heating, front
P4KC	Rear and side windows with heat-insulating glazing
P4X3	Side airbags, front and head airbag system
P7X2	Parking system plus
P8IT	LED headlights
P9AQ	3-zone deluxe automatic air conditioning
P4ZB	Gloss package
P4L6	Interior mirror, automatically dimming, frameless
P4UF	Airbags, front; front passenger airbag can be deactivated
P7K1	Tire pressure loss indicator
P8VM	LED rear lights plus
P5XK	Sun visors, front
P7HB	Interior elements in artificial leather
P8T6	Cruise control with speed limiter
P7TL	Inlays, Oak Natural, Gray
P7UZ	Preparation for activating navigation function
P4F2	Convenience key with Safelock
PFK0	Without AdBlue tank
PPF1	Preparation for functions on demand
PGT6	Accent surfaces, Gloss Black
PKA2	Reversing camera
PFZ1	Seat belts in Black
P3S0	Omission of roof rails
P5RU	Exterior mirrors on the right, (large field of view), convex
PJE3	Data module, Europe

PH3U	Tires with optimized rolling resistance 225/50 R17
PVT4	Door sill trims with aluminum inlays, front, illuminated
PPX2	LED headlights and LED rear lights with dynamic turn signal in rear
PPCM	Assist package City
PPKG	GSR equipment package
PC8F	Wheels, 10-spoke crystal, 7.5J x 17, 225/50 R17 tires
PPGD	Convenience key with sensor-controlled release of the luggage compartment lid including anti-theft alarm
PN3Q	Fine Nappa leather upholstery and trim
LY9B/	Brilliant Black/Brilliant Black

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2024



Aptarnavimas

2024-01 |  Lietuva | 9 km

Atlikti darbai:

Perdavimo patikra.



Techninė apžiūra

2024-02 |  Lietuva | 1 km

Apžiūros galiojimas iki: 2027-02

Atlikta techninė apžiūra - naujam automobiliui:

Be trūkumų.



Įkeltas / atnaujintas skelbimas

2024-03 |  Lietuva | 300 km

Patalpintas skelbimas internete apie šio automobilio pardavimą.



[Daugiau informacijos »](#)



Žalos / remonto vertinimas

2025-01 |  Lietuva

Pažeisti komponentai:

Išorinės kėbulo dalys



Žalos / remonto vertinimas

2025-01 |  Lietuva

Pažeisti komponentai:
Išorinės kėbulo dalys



Aptarnavimas

2025-04 |  Lietuva | 20 423 km

Atlikti darbai:

Lanksti alyvos keitimo paslauga.



Aptarnavimas

2025-08 |  Lietuva | 28 746 km

Atlikti darbai:

Apžiūra.

Dulkių ir žiedadulkių filtras.

Stabdžių skysčio keitimas.

Oro filtro elementas.



Įkeltas / atnaujintas skelbimas

2025-11 |  Lietuva | 31 303 km

Patalpintas skelbimas internete apie šio automobilio pardavimą.



[Daugiau informacijos »](#)


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalias ar transporto priemonės defektus



Svarbu prieš vertinant žalą:

Ne visi ataskaitoje esantys įrašai reiškia realią žalos ar eismo įvykio pasekmę.


Kai kurie įrašai gali atsirasti ne dėl pačios žalos, o dėl žalos vertinimo, likutinės vertės apskaičiavimo, draudimo bendrovių procesų, brangesnių remonto darbų, apžiūrų, diagnostikos, vertinimų prieš pardavimą ar kitų formalių procedūrų.

[Skaityti daugiau »](#)

Aptikome **1** su šia transporto priemone susijusius įrašus:



Žalos / remonto vertinimas



Data

2025-01

Fiksavimo šalis:



Lietuva

Preliminari remonto kaina

€ 0 - € 500

Pažeisti komponentai:

Išorinės kėbulo dalys

Nedideli apgadinimai paprastai neturi įtakos transporto priemonės saugumui ir nesukelia struktūrinių pažeidimų.

Informacija apie pardavimą

Rasta informacija apie automobilio skelbimus internete. Pardavimo laikas, kainos kitimas, informacija apie pardavėją.

Aptikome **2** su šia transporto priemone susijusius įrašus:



SKELBIMAS

Skelbimas neaktyvus

Skelbimas patalpintas

Šalis

Rida

Pardavėjo tipas

Pardavėjo tapatybė

2024-03

 Lietuva

300 km

2024-03-19

Privatus asmuo

Nepatvirtinta

2024-03-19 |  Nuotraukos (21)





SKELBIMAS

Skelbimas patalpintas

Šalis

Rida

Pardavėjo tipas

Pardavėjo tapatybė

Skelbimas neaktyvus

2025-11

 Lietuva




31 303 km

2025-11-12

Privatus asmuo

Patvirtinta


2025-11-12 |  Nuotraukos (34)






Papildoma įranga	
Papildoma gamybinė įranga	
M4202(M4201) Interjero šviesos šaltinis:	
1.000 Oro apšvietimas 3-jų spalvių multimedžiama apšvietimo sistema „Audi“	462 €
2.27 Be varžiklio identifikavimo aktyvių automobilių gale	
3.97 Nupjaukite vieną gale odinį, padidins 13-jų dalių nulenkinimo galios odinio atšildymo vėdinimo rankena	431 €
3.98 Elektro nustatoma naktinio važiavimo	433 €
4.43 Priekinių šviesų šildymas	431 €
4.18 Automatinis kambario šildymo vėdinimo rankena vėdinimo	108 €
4.28 Šviesų dalis, įmontuota	225 €
4.63 Konformiška priekinio vėdinimo rankena	

C87 Lietiškoji (priešais 10 stiprių „Crystal“ dizaino ratlankiai, 7,50 x 17, su 225/50 R17 padangomis		566 €
C75 Judo stiklo optikos akcentiniai paneliai		204 €
M41 Saugumo sertifikatas 1:		
R17 Audi spauda išmaniam telefonui		348 €
M42 „Fine Nappa“ odas odinių apšvietimų su kontrastine spalvos odine ir apšvietimu		1.279 €
PCM Asistavimo paketas „City“		
Išėjimo iš parko		
Saugumo ir apšvietimo sistemos gale		
Galios vairo kamera		1.433 €
Audi „Audi“ spauda išmaniam telefonui		
Parkavimo sistema „Audi“		
Cable „Audi“ prietaisų sistema (įmontuoti „Audi“ prietaisų) sistemoje		
PCD Konformiška sistema su sensorių dūko valdymo bagažinėje dūko atšildymo, įmontuoti signalizaciją		668 €
F42 Priekiniai liksos dydį šilumos ir galiniai liksos dydį šilumos su šildymo rankena naktinio važiavimo		1.121 €



Mileage	260 420 km
Order number	535547
Performed by	
Moller Auto Keturi Ziedai	
Ukmergės g. 1, 6786130 Vilnius	

Mileage	260 746 km
Order number	536277
Additional services performed	
Dust and pollen filter	
Brake fluid service	



Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija