

Mercedes-Benz CLA 220

VIN kodas

WDD1183441N009724

Sugeneruota: 2026-02-04 13:11

Galioja: 351 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Mercedes-Benz CLA 220

 Pavarų dėžė
Automatinė

 Pirmos registracijos metai
2019

 Kuro tipas
Benzinas



Rida



Nerasta neatitikimų
ridos istorijoje



Vagystės



Įrašų nerasta



Žalų / remontų vertinimas



Rasta informacijos apie
automobilio pažeidimus



Nuotraukos



Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2019-04-29
Model	CLA 220 Coupe
Series	CLA
Generation	118
Body type	COUPE
Type code	118
Engine code	INLINE 4-CYLINDER SPARK IGNITION ENGINE M260
Fuel type	Petrol
Displacement	2.00
Steering side	Left

Color	POLAR WHITE - STANDARD FINISH
Interior	Fabric/ imitation leather/ microfiber - Black/ anthracite
Transmission	automatic

Automobilio komplektacija (Originalo kalba)

149U	POLAR WHITE - STANDARD FINISH
16U	APPLE CARPLAY SMARTPHONE INTEGRATION
17U	ANDROID AUTO SMARTPHONE INTEGRATION
235	ACTIVE PARKING ASSIST
249	AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS
294	KNEEBAG
351	ECALL EMERGENCY CALL SYSTEM
362	HERMES COMMUNICATIONS MODULE LTE
475	TIRE PRESSURE MONITOR (TPM)
500	ELECTRICALLY FOLDING EXTERIOR MIRRORS
543	SUN VISOR WITH ADDITIONAL FUNCTION
810	PREMIUM SOUND SYSTEM
840	GLAS DUNKEL GETÖNT
889	KEYLESS-GO
B09	REFRIGERANT COMPRESSOR WITH MAGNETIC CLUTCH
B59	DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
P44	PARKING PACKAGE
P49	MIRROR PACKAGE
VL	LEFT FRONT AXLE HALF
VR	RIGHT FRONT AXLE HALF
287	THROUGH-LOADING FEATURE
345	RAIN SENSOR
51U	HEADLINER, BLACK FABRIC
772	AMG STYLING - FRONT SPOILER, SIDE SKIRTS
875	HEATED WINDSCREEN WASHER SYSTEM
877	AMBIENT LIGHTING
916	FUEL TANK WITH LARGE CAPACITY - VOLUME 1
B63	ENGINE SOUND VIA SPEAKERS
FC	COUPE
M20	DISPLACEMENT 2.0 LITER
U25	ILLUMINATED DOOR SILL

U26	FLOOR MATS - AMG
08U	Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)
09U	Mercedes-Benz Connect - Vehicle Monitoring (HERMES)
15U	Pre-installation for MB-Link smartphone integration
218	Rear view camera
233	Adaptive cruise control Plus (DISTRONIC PLUS)
273	Exit warning assistant
546	Automatic speed control
8U6	Assistance system steering wheel control changeover
K32	Active Lane Change Assist
K34	Route-based speed adaptation
255B	MB-Mobilo with DSB and GGD
2U8	Alternative refrigerant
429	7-speed automatic dual-clutch transmission
650A	Fabric/imitation leather/microfiber
927	Exhaust treatment, Euro 6 technology
942	Load compartment/trunk package
K13	Control code for service interval 25000 km
M013	Derated engine
U60	Pedestrian protection - Active hood
2U1	Radiator shutter
310	DOUBLE CUP HOLDER
99B	ACTIVE ADJUSTMENT DAMPING "NORMALLY OPEN"
365	HARD DRIVE NAVIGATION
3U6	HU COUNTRY SET FOR ECE/ROW
51B	RATING, COUNTRY GROUP EURO-NCAP
73B	ROLLER BLIND COMPARTMENT CLOSED
8U8	I-SIZE MARKING (ISOFIX SUCCESSOR)
98B	UPPER RADIATOR SHUTTERS
B51	TIREFIT
K31	NOISE REGULATIONS AS PER ECE R51-03
P55	NIGHT PACKAGE
U55	MULTI-LINK AXLE
1U5	RUBBER-SPRUNG STEERING GEAR
549	CONNECT 20 HIGH (NTG6)
K33	EXTENDED RESTART IN STOP-AND-GO TRAFFIC
L5C	SUPERSPORT STEERING WHEEL - LEATHER DEEP-EMBOSSSED
U19	AUGMENTED REALITY VIDEO
229L	GERMANY

2XXL	FEDERAL REPUBLIC OF GERMANY
332B	LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN
70B	SAFETY VEST - DRIVER
7U3	SEAT MODEL VARIANT 3
F118	MODEL SERIES 118
M260	INLINE 4-CYLINDER SPARK IGNITION ENGINE M260
PAC	VALUE PACKAGE
H44	TRIM ELEMENTS - LONGITUDINAL GRAIN ALUMINUM (2B45)
598	GASOLINE PARTICULATE FILTER (OPF) WITH SENSOR SYSTEM
586	LOGO PROJECTION VIA DOOR ILLUMINATION
002	CONTROL CODE FOR CHANGEOVER OF OPF FROM CORNING
JXS	PLANT CONTROL CODE
O16	SOFTWARE FRESH-UP 3
PAD	Engineering package
V76	Speed/load index 93H XI
260	Model badge on trunk lid - Omission
270	GPS aerial
299	PRE-SAFE®
580	Air-conditioning system
458	Instrument cluster display S
859	Central display size M
950	AMG line
U62	Exterior light and sight package
14U	Smartphone integration package
355	Preinstallation for retrofitting navigation system
513	Road sign recognition system
U10	Front passenger seat with weight sensor
23P	DRIVING PACKAGE
642	Dynamic LED headlamps, right-hand traffic
446	Touchpad only
873	Seat heaters for driver and front passenger
413	Automatic panoramic sliding sunroof
U59	Seat comfort package
645	M+S winter tyres, set of 4
367	Pre-installation for Live Traffic Information
459	Steel suspension with adjustable damping
U29	SPORT BRAKE SYSTEM
U01	Rear seat belt status indicator
PBF	MBUX Navigation Plus

L	LEFT-HAND DRIVE
266	DISTRONIC PLUS transverse support (DTR+Q)
RVG	AMG multi-spoke wheels 19" "all-round"
AA5	Standard power variant
059	YoM X8/2
431	Steering wheel gearshift buttons/steering wheel shift paddles - Electroplated
B10	Fuel tank packages for Euro-6D standard
01U	Mercedes-Benz Connect - Services for navigation
809	YoM X8/1
998	Control code for conversion to WLTP with RDE
628	Automatic high beam control plus (IHC+)
213	Speed-sensitive power steering / Vario steering
U35	12 V socket in load compartment
651A	Fabric/ imitation leather/ microfiber - Black/ anthracite
286	Luggage nets to left and right driver seat backrests
502	Multi-year free map updates
02B	Operating instructions and service booklet-German
969	Euro 6 technology COC document - with motor vehicle registration certificate, part 2
6P5	Control code for Sales
79B	Pre-installation for digital radio standard DAB/DMB
U22	Front lumbar support adjustment
B18	On-board xEV charging socket, NACS

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2019



Aptarnavimas

2020-08 |  Vokietija | 12 868 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas



Aptarnavimas

2021-09 |  Vokietija | 31 511 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Stabdžių skysčio keitimas



Aptarnavimas

2022-10 |  Lietuva | 43 773 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Pakeistas oro filtro elementas

Spark plugs replaced



**Žalos / remonto
vertinimas**

2023-10 |  Lietuva

Pažeisti komponentai:

Išorinės kėbulo dalys


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus



Svarbu prieš vertinant žalą:

Ne visi ataskaitoje esantys įrašai reiškia realią žalos ar eismo įvykio pasekmę.


Kai kurie įrašai gali atsirasti ne dėl pačios žalos, o dėl žalos vertinimo, likutinės vertės apskaičiavimo, draudimo bendrovių procesų, brangesnių remonto darbų, apžiūrų, diagnostikos, vertinimų prieš pardavimą ar kitų formalių procedūrų.

[Skaityti daugiau »](#)

Aptikome **1** su šia transporto priemone susijusius įrašus:



Žalos / remonto vertinimas



Data

2023-10

Fiksavimo šalis:



Lietuva

Preliminari remonto kaina

€ 501 - € 1500

Pažeisti komponentai:

Išorinės kėbulo dalys

Nedideli apgadinimai paprastai neturi įtakos transporto priemonės saugumui ir nesukelia struktūrinių pažeidimų.

CO₂ emisija

Kiek CO₂ emisijų išskiria šio modelio / metų transporto priemonės?



Autoistorija.lt įžvalga:

Kiekvienai transporto priemonei priskiriama CO₂ emisijos klasė (nuo "A" iki "G") pagal tai, kokį emisijos kiekį ji išskiria.



Taršos mokestis 
43 €



CO₂ emisija g/km
143 g/km



CO₂ emisijos klasė
C



Kuro tipas
Benzinas

CO₂ emisija (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija