

Moller Auto

Keturi žiedai



Audi Q2

VIN kodas

WAUZZZGAXKA080580

Sugeneruota: 2026-01-07 15:53

Galioja: 344 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Audi Q2
 Pavarų dėžė
Automatinė

 Pirmos registracijos metai
2019
 Kuro tipas
Benzinas



Skelbimas

 Rasta įrašų apie automobilio pardavimą



Rida

 Nerasta neatitikimų ridos istorijoje



Vagystės

 Įrašų nerasta



Žalų / remontų vertinimas

 Rasta informacijos apie automobilio pažeidimus



Nuotraukos

 Rastos istorinės automobilio nuotraukos

Automobilio techninė informacija

(Originalo kalba)

Production date	2019-06-14
Model	Q2 1.5 R4110 DSG
Series	Q2
Type code	GABBZG
Engine code	DADA 4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57
Power	110
Fuel type	Petrol
Displacement	1.50
Drive type	FWD

Steering side	Left
Color	Brilliant Black/Brilliant Black
Interior	Black-Black-Rock Gray/Black-Black/ Black/Titanium Gray
Transmission	automatic
Transmission code	TSM

Automobilio komplektacija

(Originalo kalba)

PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PC13	Operating permit, alteration
PE0A	No special edition
PEF0	Without ECO function
PF0A	No special purpose vehicle, standard equipment
PFC0	Without customized installation
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PIX1	SI engine
PL04	Suspension range 04 installation control only, no requirement forecast
P0C0	Standard
PVF0	Standard pedal cluster
PVL3	Extended and proactive pedestrian protection
P0UA	Without special color trim
P1D0	Without trailer hitch
P0N1	Standard rear axle
P1S2	Tool kit
P1E1	Activated carbon canister
P0YX	Weight range 22 installation control only, no requirement forecast
P0Y3	Cold zones
P1W0	Without refrigerator/glove compartment cooling system
P1SA	Without additional front underbody guard
P3FA	Without roof insert (standard roof)
P1Z5	Increase in initial standard fuel filling
P3H0	Without backrest release for front seats
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P7HA	Without leather

P8IT	LED headlamps
P7W0	Without extended safety system
P8W1	Washer fluid level indicator
P8M1	Rear window wiper and washer system with intermittent control
P7L6	Start/stop system with regenerative braking
P8Z5	Not hot country
P7CP	Emission standard EU6 AG/H/I
P7P0	Without lumbar support in seat backrests
P8GU	Alternator 140 A
P0FA	Standard manufacturing sequence
P1T1	First aid kit
P5C0	Without special body measures
P6V1	Rear trim panel (ECE)
P6W6	Front license plate carrier
P7G0	Without preparation for VTS (vehicle tracking system)
P0B2	Wheelbase
P8Y1	Two-tone horn
P9U1	Brake pad wear indicator
PA00	No self-collection
PKS0	Without head-up display
PNT0	Transit coating (type 1)
P0NA	Without nameplate set (without model designation)
PES0	Without vehicle inlet
PEV0	Without charging cable
P3CA	Without partition
PUK1	Standard rear seat release
PHI2	Tires 215/55 R17 94V
P4P6	Rear floor panel module, type 7
P0MG	Vehicle class differentiation -GA0-
PTJ7	4-cylinder SI engine 1.5 l unit 05E.A
PDS9	4-cylinder SI engine 1.5 l/110 kW TSI base engine is TJ7/N09/T9F/T57
P0TD	Floor mats in front and rear
P1G8	Tire mobility system
P20A	Without electric motor (hybrid)
P2KR	Labels in English and German
P4E7	Luggage compartment lid, electrically opening and closing
P4L6	Auto-dimming interior rearview mirror, frameless
P5RU	Exterior mirror on the right (large field of view), convex
P5SL	Left exterior mirror, aspherical

P6SS	Luggage compartment floor mat
P7AL	Anti-theft alarm system
P7E0	Without heat accumulator/auxiliary heater
P7K1	Tire pressure monitoring system
P8X1	Headlamp washer system
P9VD	Audi sound system
P9ZX	Bluetooth interface
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PGB0	Without antenna amplifier
PGP0	Vehicles without special upgrade measures
PL0L	Left-hand drive
PQV0	Without TV reception and without digital audio broadcasting
PUH2	Hold assist
PV0A	Tires without specification of tire brand
P0A2	5 doors
P0K0	Without alternative drive system
P1KE	Disc brakes in rear
P1U8	Without folding table on front seat backrest
P1X0	Front-wheel drive
P1ZE	Disc brakes in front (Geomet D)
P3G4	Child seat anchors in front
P3NZ	Folding rear seat backrest
P3S0	Elimination of roof rails
P3T2	Three rear head restraints
P4A3	Seat heaters in front
P4GH	Windshield with gray tinted sunshield
P4H5	Power-operated child safety lock
P4R4	Power windows
P4X3	Side airbags in front and curtain airbag system
P5K5	Adhesive film
P5ZF	Front head restraints
P6E3	Center armrest in front
P6F0	Without decorative films/emoles
P6FA	Body-colored exterior mirror housings
P7F9	Gearshift/selector lever knob
P7S0	Without wind deflector
P7Y0	Without lane change assist

P8TB	Rear fog lamps
P9AK	Comfort automatic air conditioning system
P9K0	Without neck heating
P9M0	Without auxiliary heater/parking heater
PQG1	LongLife Service Regime
PU5A	Instrument cluster, km/h speedometer
P0BA	Without rear stabilizer bar
P0EG	Installation differentiation for transmission DQ200 -- vehicle components --
P2H0	Without "drive select"
P9S5	Driver information system
PQK0	Without multifunction camera
P1A5	Fuel system for fuel-injected SI engine
P1AS	Electronic Stability Control ESC
P4KC	Heat-insulating glass
PJ0T	Battery 360 A (69 Ah)
PNZ0	Without call feature
P1XW	Leather-wrapped steering wheel, 3-spoke, with multi-function Plus
P7X2	Parking aid Plus
PG1C	S tronic
PKA2	Rear view camera system
P8G1	High-beam control
P8K1	Separate daytime running light
P8Q3	Headlight range control
P8SP	LED rear combination lamps with dynamic turn signal
P8T6	Cruise control system
P9JA	Non-smoker's package
PIT0	Without Audi connect Navigation & Infotainment
P0AE	Front stabilizer bar
P0P1	Tailpipes
P1JA	Standard suspension system
P1N7	Progressive steering
P4ZE	Standard decorative trims
P6K2	Audi pre sense front
P7M3	Aluminum scuff plates
P9P9	Seat belt reminder
PK4H	Box
PQ4H	Sports seats in front
PEL3	Audi connect Navigation & Infotainment
PQQ1	Lighting package

P5TG	Decorative inserts in Matte Brushed Aluminum
PG03	Shock absorption in front
PQJ0	Without aluminum look in the interior
P1EX	Special identification label (EU)
P3B4	ISOFIX child seat anchors and top tether for outer rear seats
PER1	Regional code " ECE " for radio
PQI6	Service indicator 30 000 km or 2 years (variable)
P6XD	Exterior mirrors, power-adjustable and heated
P1PE	Anti-theft wheel bolts
PQE0	Without Storage package
P4UF	Deactivation switch for front passenger airbag
PY8W	Special control I/VP
P2Z7	Without engine power/technology nameplate
P2JG	Full paint finish
P6H5	Blade in Ice Silver Metallic
P6NJ	Headliner in Titanium Gray fabric
P7UF	MMI navigation
PI8S	MMI navigation/navigation preparation
PN5G	Fabric "Index"
PU39	Cast alloy wheels, 5-arm star style, 7J x 17 with 215/55 R17 tires
PPNU	MMI Navigation
PUE4	Electrical interface for external usage, AUX-IN and USB
PPX2	LED headlamps with LED rear combination lamps and dynamic turn signal in rear
PPU7	Auto-dimming interior rearview mirror, with light and rain sensor
P3L3	Front passenger seat with height adjustment
PPG3	Comfort key in combination with anti-theft alarm system with towing protection
PA9D	Q2 sport
PX7Y	Equipment options subset for export (others)
P4F2	Comfort key (with SAFELOCK)
PB72	Type approval country Lithuania
PWCK	Equipment package for the Baltic States
PWDA	Comfort package for the Baltic States
PI4M	With special labels safety certificates for Lithuania
P0XR	Manual in Lithuanian
PWC8	Equipment package for the Baltic States
LY9B/	Brilliant Black/Brilliant Black

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2019



Techninė apžiūra

2019-12 |  Lietuva | 5 km

Apžiūros galiojimas iki: 2022-12

Atlikta techninė apžiūra - naujam automobiliui:

Be trūkumų.



Aptarnavimas

2019-12 |  Lietuva | 7 km

Atlikti darbai:

Patikra prieš pristatymą



Žalos / remonto vertinimas

2019-12 |  Lietuva

Pažeisti komponentai:

Žibintai

Išorinės kėbulo dalys



Aptarnavimas

2020-05 |  Lietuva | 6 057 km

Atlikti darbai:

Dirbtuvės pastaba.



Įkeltas / atnaujintas skelbimas

2021-02 |  Lietuva | 18 000 km

Patalpintas skelbimas internete apie šio automobilio pardavimą.



[Daugiau informacijos »](#)



Žalos / remonto vertinimas

2021-03 |  Lietuva

Pažeisti komponentai:

Stiklas

Išorinės kėbulo dalys



Aptarnavimas

2021-11 |  Lietuva | 21 374 km

Atlikti darbai:

Patikra su alyvos keitimu (lanksti).

Dulkių ir žiedadulkių filtras.

Stabdžių skysčio keitimas.

Oro filtro elementas.



Techninė apžiūra

2022-12 |  Lietuva | 30 472 km

Apžiūros galiojimas iki: 2024-12

Atlikta techninė apžiūra - pirminė apžiūra:

Nedideli trūkumai.



Aptarnavimas

2023-12 |  Lietuva | 38 873 km

Atlikti darbai:

Patikra su alyvos keitimu (lanksti).

Dulkių ir žiedadulkių filtras.

Stabdžių skysčio keitimas.



Žalos / remonto vertinimas

2024-11 |  Lietuva

Pažeisti komponentai:
Išorinės kėbulo dalys



Aptarnavimas

2025-12 |  Lietuva | 50 057 km

Atlikti darbai:

Patikra su alyvos keitimu (lanksti).
Dulkių ir žiedadulkių filtras.
Stabdžių skysčio keitimas.
Spark plug.
Oro filtro elementas.


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus



Svarbu prieš vertinant žalą:

Ne visi ataskaitoje esantys įrašai reiškia realią žalos ar eismo įvykio pasekmę.


Kai kurie įrašai gali atsirasti ne dėl pačios žalos, o dėl žalos vertinimo, likutinės vertės apskaičiavimo, draudimo bendrovių procesų, brangesnių remonto darbų, apžiūrų, diagnostikos, vertinimų prieš pardavimą ar kitų formalių procedūrų.

[Skaityti daugiau »](#)

Aptikome **3** su šia transporto priemone susijusius įrašus:



Žalos / remonto vertinimas



Data

2019-12

Fiksavimo šalis:



Lietuva

Preliminari remonto kaina

€ 501 - € 1500 

Pažeisti komponentai:


Žibintai

Išorinės kėbulo dalys

Nedideli apgadinimai paprastai neturi įtakos transporto priemonės saugumui ir nesukelia struktūrinių pažeidimų.



Žalos / remonto vertinimas



Data

2021-03

Fiksavimo šalis:



Lietuva

Preliminari remonto kaina

€ 501 - € 1500 

Pažeisti komponentai:


Stiklas

Išorinės kėbulo dalys

Nedideli apgadinimai paprastai neturi įtakos transporto priemonės saugumui ir nesukelia struktūrinių pažeidimų.



Žalos / remonto vertinimas



Data

2024-11

Fiksavimo šalis:



Lietuva

Preliminari remonto kaina

€ 501 - € 1500 

Pažeisti komponentai:

Išorinės kėbulo dalys

Nedideli apgadinimai paprastai neturi įtakos transporto priemonės saugumui ir nesukelia struktūrinių pažeidimų.

Informacija apie pardavimą

Rasta informacija apie automobilio skelbimus internete. Pardavimo laikas, kainos kitimas, informacija apie pardavėją.

Aptikome **1** su šia transporto priemone susijusius įrašus:



SKELBIMAS

Skelbimas neaktyvus

Skelbimas patalpintas

Šalis

Rida

Pardavėjo tipas

2021-02

 Lietuva

18 000 km

2021-02-06

Verslas

2021-02-06

 Nuotraukos (19)

Moller Auto
Keturi žiedai



Moller Auto
Keturi žiedai





Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija