

Audi A3

VIN kodas

WAUZZZGY8MA113284

Sugeneruota: 2025-04-22 21:17

Galioja: 35 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Audi A3

 Kuro tipas
Benzinas / Elektra



Rida



Nerasta neatitikimų
ridos istorijoje



Vagystės



Įrašų nerasta



Nuotraukos



Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2021-04-29
Model	A3 PHEV 1.4 R4150 DSG
Series	A3
Type code	8YAAPX
Engine code	DGEA 4-cylinder SI engine 1.4 l/110 kW hybrid electric vehicle, TSI, 150 KW system output; base engine is TH8/T9D
Power	110
Fuel type	Electric
Displacement	1.40
Drive type	FWD
Steering side	Left
Color	Myth Black Metallic
Interior	Black Silver-Black/Black-Black/Black/ Steel Gray
Transmission	automatic
Transmission code	TTT

Automobilio komplektacija

(Originalo kalba)

PAV1

Driving on the right

PA51	Audi AG
PAQ0	Standard-production quality
PC14	Operating permit, alteration
PE0A	No special edition
PG1A	6-speed automatic transmission
PEF1	ECO function
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
PK8R	Sportsback
PI8Y	MMI Radio plus
PIX1	SI engine
P0B1	Wheelbase
PVF0	Standard pedal cluster
P1D0	Without trailer hitch
P1S1	Tool kit and jack
P0YC	Weight range 3 installation control only, no requirement forecast
P0Y1	Standard climatic zones
P1SA	Without additional front underbody guard
P1Z0	Initial standard fuel filling
P4A0	Without seat heater
P3FA	Without roof insert (standard roof)
P4BI	Emission standard EU6 AP
P3H0	Without backrest release for front seats
P2WA	Without additional tires
P6A0	Without fire extinguisher
P8IT	LED headlamps
P7W0	Without extended safety system
P8M1	Rear window wiper and washer system with intermittent control
P8Z5	Not hot country
P8RL	6 speakers (passive)
P8FC	Installation of SLI battery in rear, without second battery
PL71	Suspension range 71 installation control only, no requirement forecast
P5C0	Without special body measures
P4P4	Rear floor panel module, type 5
P0K3	Hybrid propulsion system PHEV
P8Y1	Two-tone horn
PA00	No self-collection
PKS0	Without head-up display

PNM1	Engine cover
PNT1	Transit coating (type 2)
P5L0	Without front spoiler
PNJ0	Without charging dock
PQR7	Without camera-based traffic sign recognition
P31B	Rear license plate carrier (ECE)
PTH8	4-cylinder SI engine 1.4 l unit 04E.C
P0P0	Standard exhaust system
P0TD	Floor mats in front and rear
P1G8	Tire mobility system
P2F0	Without locking and starting systems
P2Z8	Model designation as per new engine power designation
P4L6	Auto-dimming interior rearview mirror, frameless
P4UF	Driver and front passenger airbag with front passenger airbag deactivation
P4ZB	High-Gloss styling package
P6SS	Luggage compartment floor mat
P7E0	Without heat accumulator/auxiliary heater
P7K1	Tire pressure monitoring system
P7P1	4-way lumbar support for the front seats
P7X5	Park assist with parking aid plus
P8K4	Separate daytime running light
P9ZX	Bluetooth interface
PB0A	Part set without country-specific prescriptive standard
PFA0	Control of series production
PFQ0	Production wheels
PFZ1	N.N.N. Type 1
PGB0	Without antenna amplifier
PGP0	Vehicles without special upgrade measures
PIU1	Audi smartphone interface
PIW3	Audi connect Emergency Call & Service with Audi connect Remote & Control
PL0L	Left-hand drive
PQ1A	Standard seats in front
PQI4	Service indicator 15 000 km or 1 year (fix)
PQK1	With multifunction camera
PQL1	Rear window, rear door windows and side windows in clear glass
PUH2	Hold assist
PV0A	Tires without specification of tire brand
PVC0	Without garage door opener
P0AD	Front stabilizer bar

P1N3	Electromechanical power steering
P1X0	Front-wheel drive
P2JB	Bumpers
P3NZ	Folding rear seat backrest
P3S0	Elimination of roof rails
P3T2	Three rear head restraints
P5K5	Adhesive film
P5ZF	Front head restraints
P6E3	Center armrest in front
P6F0	Without decorative films/emoles
P6FA	Body-colored exterior mirror housings
P6NJ	Headliner in fabric
P7AA	Electronic immobilizer
P7F9	Gearshift/selector lever knob
P7L6	Start/stop system
P7Y0	Without lane change assist
P8G0	Without light control
P8N6	Light/rain sensor
P9M0	Without auxiliary heater/parking heater
PQJ1	Interior in aluminum look
PU5A	Instrument cluster, km/h speedometer
PA9F	Equipment 1
P5J3	Roof spoiler
P1A5	Fuel system for fuel-injected SI engine
P7UG	MMI Navigation plus with MMI touch
P2H6	Audi drive select
PKA2	Rear view camera system
PQQ0	Interior lighting
P6Y2	Speed limiter
P8T6	Cruise control system
P1JA	Standard suspension system
P4E0	Manual luggage compartment lid
P4H5	Child safety lock, electrically actuated
P0SS	Labels in English and French
P8VM	LED rear combination lamps with dynamic turn signal
P7HA	Without leather wrapping
P9AK	2-zone climate control system
PIT3	Audi connect Navigation & Infotainment Plus
PNW1	e-tron charging system "compact"

P0LJ	With special labels safety certificates for France
P1EX	Special identification label (EU)
PB08	Type approval country France
PX3A	Equipment options subset for France
PGM4	Acoustic vehicle alerting system
PER1	Regional code " ECE " for radio
PQV3	Digital audio broadcasting
P1E5	Activated carbon canister (Evaporative Emission Control System (EVAP))
P1T3	First-aid kit with warning triangle
P9JA	Non-smoker package
P9S1	Audi virtual cockpit
PJ0S	Battery 320 A (59 Ah)
PPX2	LED headlamps and LED rear combination lamps with dynamic turn signal in rear
P1PE	Anti-theft wheel bolts
PQE0	Without Storage package
P3L3	Front seats, manually adjustable
P73N	Industrial plug CEE 32 A, 230 V, long and straight, for the e-tron charging system
PFP1	Preparation for features on demand
PJE3	Data module for Europe
P6I3	Lane departure warning
PN5G	Fabric "Index"
P1AE	Brake control system for vehicles with electric drive (ESC and electromechanical brake booster)
P1I0	Seat belt reminder with passenger presence detection in rear
P1KE	Disc brakes in rear, 15-inch (ECE)
P1XX	Leather-wrapped steering wheel, 3-spoke, with multi-function Plus and shift paddles
P1ZK	Disc brakes in front, 16-inch (ECE)
P2CH	Vehicle class differentiation -8Y0/8YF-
P4G3	Swerve support and turn assist
P5F1	UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
P5JA	Exterior mirrors: aspherical on driver side, convex on front passenger side
P5MA	Platinum Gray decorative inserts in silk effect paint
P7M5	Without scuff plates
P8J3	Audi pre sense front
P8X7	Without headlamp washer system, with washer fluid level indicator
PCL9	Alloy wheels, 5-parallel-spoke style, 8.0J x 17, 225/45 R17 tires
PNZ2	Legal emergency call
P0N4	Four-link rear suspension
P4GH	Windshield with acoustic glass

P6XI	Exterior mirrors, power-adjustable, heated and power-folding, auto-dimming on both sides
P7B3	12-V outlet in rear seat area
P8GJ	DC-DC converter 3.0 kW
P0BT	Rear stabilizer bar
P0IC	Installation differentiation for transmission DQ400 -- vehicle components --
P20B	Electric motor (hybrid electric vehicle), total system output 150 kW, unit 0EC.A / 0EK.A
P0VB	Manual in French
P4I7	Remote control key without SAFELOCK
PYED	Internal control code
P70I	Household plug type E/F, 8 A, straight, for the e-tron charging system
P76C	Mode 3 charging cable for public charging 11 kW
PES3	Vehicle inlet AC type 2
P3A0	i-Size and top tether for outer rear seats
P6C2	Side airbag in front with curtain airbag and interaction airbag in front
PG11	Shock absorption in front
PHS3	Low-rolling-resistance tires, 225/45 R17
PWBL	Equipment package for France
PML7	4-cylinder SI engine 1.4 l/110 kW hybrid electric vehicle, TSI, 150 KW system output; base engine is TH8/T9D

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.

Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.

Žiūrėti originalo kalba



2021



Aptarnavimas

2021-05 |  Prancūzija

Atlikti darbai:

Serviso patikrinimas



Aptarnavimas

2022-04 |  Prancūzija | 13 713 km

Atlikti darbai:

Tepalų servisas



Aptarnavimas

2023-03 |  Prancūzija | 26 042 km

Atlikti darbai:

Tepalų servisas

Filtrai

Stabžių aptarnavimas



Aptarnavimas

2024-02 |  Prancūzija | 42 477 km

Atlikti darbai:

Tepalų servisas



Techninė apžiūra

2025-07 |  Lietuva | 45 233 km

Atlikta tehninė apžiūra - pirminė apžiūra:
Dideli trūkumai.



Techninė apžiūra

2025-07 |  Lietuva | 45 243 km

Apžiūros galiojimas iki: 2027-07

Atlikta techninė apžiūra - pakartotinė apžiūra:

Be trūkumų.


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija