

Mercedes-Benz GLC 350

VIN kodas

WDC2539541F279945

Sugeneruota: 2026-03-09 11:27

Galioja: 361 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Mercedes-Benz GLC 350

 Pavarų dėžė
Automatinė

 Pirmos registracijos metai
2017

 Kuro tipas
Benzinas / Elektra



Rida



Nerasta neatitikimų
ridos istorijoje



Vagystės



Įrašų nerasta



Nuotraukos



Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2017-05-15
Model	GLC 350 e 4MATIC
Series	GLC
Generation	253
Body type	Special version
Type code	253
Engine code	4-CYLINDER GASOLINE ENGINE M274
Displacement	2.00
Steering side	Left
Color	DIAMOND WHITE - METALLIC PAINT
Interior	LEATHER - BEIGE
Transmission	automatic

Automobilio komplektacija

(Originalo kalba)

057 YOM 16/2

531 COMAND APS NTG5/NTG5.5

807	YOM 16/1
810	PREMIUM SOUND SYSTEM
HA	REAR AXLE
L	LEFT-HAND STEERING
P44	PARKING PACKAGE
U22	LUMBAR SUPPORT ADJUSTMENT
274	TELEPHONE ANTENNA
345	RAIN SENSOR
JVG	PLANT CONTROL CODE
JVO	PLANT CONTROL CODE
M20	DISPLACEMENT 2.0 LITER
P17	KEYLESS-GO PACKAGE
U25	ILLUMINATED DOOR SILL
293	Sidebag in rear left and right
367	Live Traffic capability
2U8	Alternative refrigerant
FX	Special version
K13	Control code for service interval 25000 km
720	ROOF RAILING
P55	NIGHT PACKAGE
851	ACOUSTIC GLAZING
900	EXTERIOR CHROME PACKAGE
F253	MODEL SERIES 253
229L	GERMANY
2XXL	FEDERAL REPUBLIC OF GERMANY
70B	SAFETY VEST - DRIVER
P22	INTERIOR LUXURY PACKAGE
237	ACTIVE BLIND SPOT ASSIST
99R	AMG DOUBLE-SPOKE WHEELS 19" ALL-ROUND
JVX	PLANT CONTROL CODE
VR	FRONT AXLE HALF, RIGHT
VL	FRONT AXLE HALF, LEFT
550	TRAILER COUPLING
890	Automatic rear-end door
351	E-CALL EMERGENCY CALL SYSTEM
8U8	I-SIZE-MARKING (ISOFIX SUCCESSOR)
8U7	REAR SEAT BELT WITH BELT FORCE LIMITER AND SOFTST.
B59	TRANSMISSION MODE SELECTOR LEVER (AGILITY SELECT)
6P5	STEUERCODE VERTRIEB FUER CODE 475 ANFORDERUNG

270	GPS ANTENNA
U01	REAR BELT STATUS INDICATION
P49	MIRRORS PACKAGE
670	RESIDUAL ENGINE HEAT UTILIZATION (MRA)
235	ACTIVE PARK ASSIST
255B	MB MOBILO WITH DSB AND GGD
U10	FRONT PASSENGER SEAT WITH WEIGHT SENSING
299	PRESAFE
309	CUP HOLDER
475	TIRE PRESSURE CONTROL
500	ELECTRIC FOLDING OUTSIDE MIRROR
927	EURO 6 TECHNOLOGY EXHAUST GAS CLEANING
K11	ADAPTIVE STOP LIGHT FLASHING
U60	PEDESTRIAN PROTECTION - ACTIVE ENGINE HOOD
249	INTERIOR AND EXTERIOR MIRROR,AUTOMATICALLY DIMMING
3U1	EUROPE/CIS COUNTRIES/MONGOLIA HEAD UNIT
294	KNEE AIRBAG
893	KEYLESS START
736	TRIM PIECES - WOOD ASH BLACK
U72	DVD PLAYER WITH REGIONAL CODE 2, EUROPE, JAPAN
253	REAR-END COLLISION WARNING AND PROTECTION SYSTEM
628	AUTOMATIC HIGH BEAM SWITCH PLUS (IHC+)
772	AMG STYLING PACKAGE-FRONT SPOILER, SIDE SKIRT
871	SENSORS FOR TRUNK LID OPENING/CLOSING
238	ACTIVE LANE KEEPING ASSIST (FAP)
23P	DRIVING PACKAGE
840	DARK TINTED GLASS
266	DISTRONIC PLUS CROSS SUPPORT (DTR+Q)
268	EXPANDED BRAKE ASSIST (BAS+)
269	BRAKE ASSIST PLUS CROSS TRAFFIC (BAS+Q)
271	AUTONOMOUS BRAKE INTERVENTION/WARN. FOR PED. PROT.
300	COLLISION MINIMIZATION BRAKE INTERV./WARNING (CMS)
5P6	CONTROL CODE MARKETING
P31	AMG LINE EXTERIOR/AMG SPORTS PACKAGE EXTERIOR
489	AIRMATIC DUAL CONTROL / AIR SUSPENSION SEMI-ACTIVE
M274	4-CYLINDER GASOLINE ENGINE M274
233	AUTONOMOUS INT. CRUISE CONT. PLUS (DISTRONIC PLUS)
275	MEMORY PACKAGE (DRIVER SEAT, STRG. COL., MIRROR)
581	Automatic climate control

876	INTERIOR LIGHT ASSEMBLY
642	Dynamic LED headlamps, right-hand traffic
877	AMBIENCE ILLUMINATION
889	KEYLESS - GO
427	AUTOMATIC TRANSMISSION 7-SPEED
J81	JUNE RELEASE
11U	MBCONNECT - REMOTE ONLINE (HERMES)
02B	OPERATORS MANUAL AND SERVICE BOOKLET GERMAN
360	HERMES - COMMUNICATION MODULE UMTS
332B	INSTRUMENT CLUSTER/HU LANGUAGE - GERMAN
969	COC PAPER EURO6 TECH. W/ REGISTRATION CERT. PART 2
875	HEATED SCREEN WASH SYSTEM
U35	12 V - SOCKET IN LOAD SPACE
55U	ROOF INTERIOR TRIM BEIGE FABRIC
513	TRAFFIC SIGN RECOGNITION
448	TOUCHPAD WITH ROTARY PUSHBUTTON
502	3 YEARS OF MAP UPDATES FREE OF CHARGE
401	FRONT SEAT CLIMATE CONTROL
413	PANORAMIC SLIDING SUNROOF/GLASS SUNROOF
GH	HYBRID TRANSMISSION
723	TRUNK COVERING
U40	CARGO NET BEHIND FRONT SEATS
242	ELECTRICALLY ADJUSTABLE RIGHT DRIVER SEAT W MEMORY
M005	VEHICLES WITH 4-MATIC-/ALL WHEEL DRIVE
U09	LEATHER-CLAD INST.PANEL + BELTLINE (ART. EMBOSSED)
A17	DAS 4
611	AMBIENT ILLUMINATION
537	DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)
815	DVD SINGLE DRIVE
220A	LEATHER
225A	LEATHER - BEIGE
R05	ROLLING RESISTANCE-OPTIMIZED SUMMER TIRE
799U	DIAMOND WHITE - METALLIC PAINT
A121	P VALVE BODY ASSEMBLY WITH VGS-500
J9A	D724.2 VENTILATION B2
26A	EFTI ELECTRIC MOTOR 50-80 KW
652	SUMMER TIRES MOUNTED
ME05	HYBRID DRIVE 85KW-94KW VARIANT (INCL. PLUG-IN)
13U	MBCONNECT - EV FUNCTIONS (HERMES)

0V2	SPEED- + LOADINDEX 101V
B30	CHAR.CABLE GROUNDING-CONTACT CEE 7/7 (TYPE E/F) 4M
4R7	COMPLETE WINTER WHEEL, L. ALLOY 5-SPOKE DESIGN 18"
B33	CHARGING CABLE 7-PIN ICCA PER IEC 62196 16A 4M
G268	TRANSMISSION CODE VERSION 69

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2017



Aptarnavimas

2018-06 |  Vokietija | 13 845 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Salono filtro keitimas



Aptarnavimas

2019-06 |  Vokietija | 24 297 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Stabdžių skysčio keitimas
Salono filtro keitimas



Aptarnavimas

2020-05 |  Vokietija | 30 944 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Pakeistas oro filtro elementas
Spark plugs replaced
Starter replaced



Aptarnavimas

2021-05 |  Suomija | 39 191 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Salono filtro keitimas



Aptarnavimas

2022-06 |  Suomija | 70 132 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Automatinė pavarų dėžė: tepalo ir filtro keitimas / Paskirstymo dėžės tepalo keitimas
Stabdžių skysčio keitimas



Aptarnavimas

2023-11 |  Suomija | 96 956 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Pakeistas oro filtro elementas
Spark plugs replaced



Aptarnavimas

2024-09 |  Suomija | 110 753 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas
Stabdžių skysčio keitimas
Salono filtro keitimas


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

CO₂ emisija

Kiek CO₂ emisijų išskiria šio modelio / metų transporto priemonės?



Autoistorija.lt įžvalga:

Kiekvienai transporto priemonei priskiriama CO₂ emisijos klasė (nuo "A" iki "G") pagal tai, kokį emisijos kiekį ji išskiria.



Taršos mokestis 
0 €



CO₂ emisija g/km
59 g/km



CO₂ emisijos klasė
A



Kuro tipas
Benzinas / Elektra

CO₂ emisija (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija