

Audi Q7

VIN kodas

WAUZZZ4MXMD020279

Sugeneruota: 2025-04-11 11:29

Galioja: 52 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Audi Q7

 Kuro tipas
Dyzelinas / Elektra

 Pirmos registracijos metai
2021



Rida



Nerasta neatitikimų
ridos istorijoje



Vagystės



Įrašų nerasta



Nuotraukos



Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2021-01-12
Model	Q7 quat. TDI3.0 V6210 A8
Series	Q7
Type code	4MGCN2
Engine code	DPXA 6-cyl. turbo diesel engine 3.0 l/210 kW V6 TDI common rail base engine is T7V/T2P
Power	210
Fuel type	Diesel
Displacement	3.00
Drive type	AWD
Steering side	Left
Color	Orca black metallic
Interior	Black-Black/Black-Black/Black/ Moon Silver
Transmission	automatic
Transmission code	SUB

Automobilio komplektacija

(Originalo kalba)

P3S2	Black roof rails
PAV1	Driving on the right
PA51	Audi AG
PAQ0	Standard-production quality
PE0A	No special edition
PF0A	No special purpose vehicle, standard equipment
PKK3	Refrigerant R1234yf
PJ2D	Battery 380 A (68 Ah)
PVF0	Standard pedal cluster
P0YJ	Weight range 9 installation control only, no requirement forecast
P1D0	Without trailer hitch
P1S2	Tool kit
P1T2	Warning triangle
P0Y3	Cold zones
P1SA	Without additional front underbody guard
P3FA	Without roof insert (standard roof)
P4BI	Emission standard EU6 AP
P1Z6	Increase in initial standard fuel filling
P2WA	Without additional tires
P6A0	Without fire extinguisher
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P8Z5	Not hot country
P0FA	Standard manufacturing sequence
P2G5	Filler neck module 1 without insert
P5C0	Without special body measures
P6U0	Without additional seals outside
P6V1	Rear trim panel (ECE)
P6W6	Front license plate carrier
P0F3	Fuel system for diesel engine
P7A0	Without CD changer/CD player
P7G0	Without preparation for VTS (vehicle tracking system)
P8Y1	Two-tone horn
PA00	No self-collection
PC51	Operating permit, alteration
PGP1	Vehicles with special upgrade measures
PIX2	Diesel engine
PKS0	Without head-up display
PNT0	Transit coating (type 1)
PNY0	Standard battery/alternator capacity

PVH2	48-V electric system
P0RZ	Without ignition/starter switch locking system, without steering lock
P04H	S line
P0JL	Weight category front axle weight range 11
P1VH	Installation parts for six-cylinder engine
P3M3	Passenger car design
P4D0	Without seat ventilation/massage seat
P5L0	Without front spoiler
P9TA	Without additional warning lights
P8IY	LED headlamps with lens
PES0	Without vehicle inlet
P3CA	Without partition
PQT5	Without step
P0E2	Long wheelbase
P1Y6	Automatic slip-control differential
P7ZB	Vehicle class differentiation -4M0-
PDV8	6-cyl. turbo diesel engine 3.0 l/210 kW V6 TDI common rail base engine is T7V/T2P
PT2P	6-cylinder diesel engine 3.0 l unit 059.P
P0K4	Mild hybrid
P0M5	Fuel tank with increased volume
P0NB	S line logo, exterior
P0P0	Standard exhaust system
P0TD	Floor mats in front and rear
P1G8	Tire mobility system
P1P0	Without active roll stabilization
P20A	Without electric motor (hybrid)
P2C5	Safety steering column
P2D0	Without action
P2F0	Without locking and starting systems
P2K7	S line bumpers in full paint finish
P2KR	Labels in English and German
P2P2	Loading edge protection in stainless steel
P3G4	ISOFIX child seat anchors for front passenger seat
P3GD	Luggage compartment floor
P3U7	Electric luggage compartment cover
P4E7	Luggage compartment lid, electrically opening and closing
P4F2	Comfort key with sensor-controlled luggage compartment release with SAFELOCK
P4L6	Auto-dimming interior rearview mirror, frameless
P4UF	Driver and front passenger airbag with front passenger airbag deactivation

P5RU	Exterior mirror on the right (large field of view), convex
P5SL	Left exterior mirror, aspherical
P5XC	Sun visor on driver and front passenger side
P5ZF	Head restraints in front
P6F0	Without emblems
P6FA	Exterior mirror housings painted in body color
P6K8	Audi pre sense front
P6NQ	Headliner in Black fabric
P6SS	Luggage compartment floor mat
P6XL	Exterior mirrors, power-adjustable, heated and folding, auto-dimming on both sides, with memory feature
P6Y2	Cruise control system incl. speed limiter
P73A	Without grid connection cable for industrial plug, for the e-tron charging system
P7AL	Anti-theft alarm system
P7E0	Without heat accumulator/auxiliary heater
P7K1	Tire pressure monitoring system
P7L8	Start/stop system
P7P1	4-way lumbar support for the front seats
P7UG	MMI navigation plus with MMI touch response
P7W3	Audi pre sense rear
P7Y1	Lane change assistant with exit warning system and rear cross traffic alert
P8T5	Adaptive cruise control with speed limiter, efficiency assist, swerve assist and turn assist
P9AE	4-zone climate control system
P9B0	Without integrated toll system
P9G8	Belt-driven integrated starter alternator 48 V 110 - 250 A
P9P6	Seat belt reminder
P9PA	Standard wiper arms and blades
P9R0	Without night vision
P9WC	Without "Multimedia" in vehicle
PB0A	Part set without country-specific prescriptive standard
PEH0	Without vehicle charging cable
PEV0	Without grid connection cable for household plug, for the e-tron charging system
PFA0	Control of series production
PFK2	AdBlue tank with increased volume
PFM0	Basic equipment
PFZ1	N.N.N. Type 1
PG1G	tiptronic
PGA0	Without preconditioning
PGH1	quattro (with self-locking center differential)

PGJ0	Without combined lateral and longitudinal control
PGM0	Without acoustic vehicle alerting system
PGS5	Glossy Black operating buttons with haptic feedback and aluminum Look interior
PGZ2	Power latching for the doors
PIT3	Audi connect Navigation & Infotainment
PIU1	Audi smartphone interface
PIW3	Audi connect Emergency Call & Service with Audi connect Remote & Control
PL0L	Left-hand drive
PN5A	Cricket leather
PNJ0	Without wall bracket
PQ1A	Standard seats in front
PQK1	With multifunction camera
PQQ2	Ambient Lighting package plus
PQZ7	Electromechanical power steering
PU5A	Instrument housing assembly, indication in km/h
PUH2	Hold assist
PV0A	Tires without specification of tire brand
PVC0	Without garage door opener
PVT5	Scuff plates with aluminum inserts in front and rear, illuminated, with "S" logo in front
P4A3	Seat heaters in front
P4X3	Side airbags in front and curtain airbag system
P5K5	Adhesive film
P5J3	Roof spoiler
P4KC	Heat-insulating glass
PFQ1	Audi Sport/quattro GmbH wheels
P1XW	Leather-wrapped steering wheel, 3-spoke, with multi-function Plus
P7X2	Parking aid Plus
PKA2	Rear view camera system
P1BK	adaptive air suspension
P3Y0	Without roll-up sunshade
P8K1	Separate daytime running light
P9JA	Non-smoker's package
P9S8	Audi virtual cockpit
PK4H	Box
P0N1	Without all-wheel steering
P2H9	Audi drive select
P3L4	Power front seats with memory feature for the driver seat
P4GF	Windshield with heat-insulating glass
P76A	Without Mode 3 charging cable for public charging

P9ZE	Audi phone box
PFT0	Without parking assistance/garage parking assist
PVL1	Extended pedestrian protection
P3B5	ISOFIX child seat anchors and top tether
P2V5	Without air quality package
P8VM	LED rear combination lamps with dynamic turn signal
PA8Y	S line
P5KL	3rd row of seats
P7HA	Without leather wrapping
P8G4	Matrix LED headlamps with dynamic turn signal
PFY0	.
PUF8	Audi music interface in the rear seat area
P1PR	Anti-theft wheel bolts and loose wheel warning
P4ZD	Black Appearance package
P9VS	Bang & Olufsen premium sound system with 3D sound
P8X0	Without headlamp washer system
P1EX	Special identification label (EU)
PER1	Regional code " ECE " for radio
PQV3	Digital audio broadcasting
PGB1	LTE support for Audi phone box
P6I6	Adaptive cruise assist with emergency assist
PFP1	Preparation for features on demand
PJE3	Data module for Europe
PPCC	Tour assistance package
PQL5	Privacy glass (dark-tinted windows)
PQR9	Camera-based traffic sign recognition
PPV3	Power seats in front including memory feature for the driver seat
P6E6	Comfort center armrest in front
P7TM	Decorative inserts in Gray Oak
P2Z7	Without engine power/technology nameplate
PPXC	Matrix LED headlamps and LED rear combination lamps
PJX0	Without front cross traffic assist
P9M9	Parking heater and ventilation
P1KQ	Disc brakes in rear, 18-inch (ECE)
P1LN	Disc brakes in front, 18-inch (ECE)
PPG3	Comfort key in combination with anti-theft alarm system
PPCH	Lane change warning incl. Audi pre sense rear, exit warning system and rear cross traffic assist
PPE1	3rd row of seats

PVI1	Service indicator 30 000 km or 1 year (variable)
PX7Y	Equipment options subset for export (others)
PH7M	Tires 285/40 R21 109Y xl low rolling resistance
PB72	Type approval country Lithuania
PPK6	Parking heater/ventilation
PV34	Alloy wheels, 10-spoke star style, Anthrac. Black, diam.-turn., 9.5J x 21, 285/40 R21 tires, Audi Sport GmbH
PWC8	Connectivity package for the Baltic States
PWCK	Equipment package for the Baltic States
PWDA	Comfort package for the Baltic States
PI4M	With special labels safety certificates for Lithuania
P0XR	Manual in Lithuanian

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2021



Aptarnavimas

2021-02 |  Lietuva | 10 km

Atlikti darbai:

Serviso patikrinimas



Aptarnavimas

2022-02 |  Lietuva | 13 004 km

Atlikti darbai:

Tepalų servisas



Aptarnavimas

2023-02 |  Lietuva | 29 165 km

Atlikti darbai:

Serviso patikrinimas

Filtrai

Stabžių aptarnavimas

nežinoma paslauga



Aptarnavimas

2023-06 |  Lietuva | 35 643 km

Atlikti darbai:

Tepalų servisas



Techninė apžiūra

2024-02 |  Lietuva | 48 415 km

Apžiūros galiojimas iki: 2026-02

Atlikta techninė apžiūra - pirminė apžiūra:

Be trūkumų.



Aptarnavimas

2024-03 |  Lietuva | 50 488 km

Atlikti darbai:

Tepalų servisas



Aptarnavimas

2024-08 |  Lietuva | 60 221 km

Atlikti darbai:

Serviso patikrinimas

Filtrai

Stabžių aptarnavimas

nežinoma paslauga


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija