

Mercedes-Benz C 43 AMG

VIN kodas

WDD2053641F859532

Sugeneruota: 2026-02-04 09:58

Galioja: 351 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Mercedes-Benz C 43 AMG

 Kuro tipas
Benzinas

 Pavarų dėžė
Automatinė



Rida

 Nerasta neatitikimų
ridos istorijoje



Vagystės

 Įrašų nerasta



Žalų / remontų vertinimas

 Rasta informacijos apie
automobilio pažeidimus



Nuotraukos

 Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2019-01-04
Model	Mercedes-AMG C 43 4MATIC Coupe
Series	C
Generation	205
Body type	COUPE
Type code	205
Engine code	V6 SPARK-IGNITION ENGINE M276
Fuel type	Petrol
Displacement	3.00
Steering side	Left

Color	Black - standard finish
Interior	Fabric / imitation leather / microfiber - Black / anth.
Transmission	automatic

Automobilio komplektacija (Originalo kalba)

16U	APPLE CARPLAY SMARTPHONE INTEGRATION
17U	ANDROID AUTO SMARTPHONE INTEGRATION
235	ACTIVE PARKING ASSIST
249	AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS
294	KNEEBAG
351	ECALL EMERGENCY CALL SYSTEM
362	HERMES COMMUNICATIONS MODULE LTE
475	TIRE PRESSURE MONITOR (TPM)
500	ELECTRICALLY FOLDING EXTERIOR MIRRORS
531	COMAND APS NTG5/NTG5.5
543	SUN VISOR WITH ADDITIONAL FUNCTION
810	PREMIUM SOUND SYSTEM
889	KEYLESS-GO
893	KEYLESS-START
B09	REFRIGERANT COMPRESSOR WITH MAGNETIC CLUTCH
B59	DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
M276	V6 SPARK-IGNITION ENGINE M276
P44	PARKING PACKAGE
P49	MIRROR PACKAGE
VL	LEFT FRONT AXLE HALF
VR	RIGHT FRONT AXLE HALF
274	TELEPHONE ANTENNA
287	THROUGH-LOADING FEATURE
345	RAIN SENSOR
51U	HEADLINER, BLACK FABRIC
5P6	CONTROL CODE FOR SALES
611	AMBIENT LIGHTING
772	AMG STYLING - FRONT SPOILER, SIDE SKIRTS
875	HEATED WINDSCREEN WASHER SYSTEM
916	FUEL TANK WITH LARGE CAPACITY - VOLUME 1
F205	MODEL SERIES 205

FC	COUPE
JVO	PLANT CONTROL CODE
M005	VEHICLES WITH 4MATIC/ALL-WHEEL DRIVE
R01	SUMMER TYRES
U02	BELT FEEDER
U26	FLOOR MATS - AMG
08U	Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)
09U	Mercedes-Benz Connect - Vehicle Monitoring (HERMES)
15U	Pre-installation for MB-Link smartphone integration
218	Rear view camera
233	Adaptive cruise control Plus (DISTRONIC PLUS)
273	Exit warning assistant
30P	Stowage facility package
421	9-speed automatic transmission
546	Automatic speed control
8U6	Assistance system steering wheel control changeover
K27	Software control for unpowered in position "D"
K32	Active Lane Change Assist
K34	Route-based speed adaptation
255B	MB-Mobilo with DSB and GGD
2U8	Alternative refrigerant
927	Exhaust treatment, Euro 6 technology
K13	Control code for service interval 25000 km
PZB	Control code for Sales
U60	Pedestrian protection - Active hood
040U	Black - standard finish
99B	ACTIVE ADJUSTMENT DAMPING "NORMALLY OPEN"
M002	ENGINES WITH TURBOCHARGER WITH CHARGE AIR COOLING
M30	DISPLACEMENT 3.0 LITER
8U8	I-SIZE MARKING (ISOFIX SUCCESSOR)
B51	TIREFIT
K31	NOISE REGULATIONS AS PER ECE R51-03
K33	EXTENDED RESTART IN STOP-AND-GO TRAFFIC
P65	ERGONOMICS PACKAGE
776	WIDER WHEEL ARCH FOR AMG WHEELS
229L	GERMANY
2XXL	FEDERAL REPUBLIC OF GERMANY
02U	MERCEDES-BENZ CONNECT - SERVICE FOR OFFICE AND COMMUNICATION
332B	LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN

70B	SAFETY VEST - DRIVER
899	FRONT WIRELESS TELEPHONE CHARGING AND ANTENNA
M016	UPRATED ENGINE
U17	OMISSION OF COLORED SEAT BELT
598	GASOLINE PARTICULATE FILTER (OPF) WITH SENSOR SYSTEM
L6K	NAPPA LEATHER/MICROFIBER AMG STEERING WHEEL
1P6	CONTROL CODE FOR SALES
U21	SPORTABGASANLAGE
610A	FABRIC/IMITATION LEATHER/MICROFIBER
JVH	PLANT CONTROL CODE
H84	TRIM ELEMENTS - SILVER GLASS FIBER
JWB	PLANT CONTROL CODE
260	Model badge on trunk lid - Omission
270	GPS aerial
299	PRE-SAFE®
580	Air-conditioning system
GA7	AUTOMATIC TRANSMISSION
K11	Adaptive brake light, flashing
859	Central display size M
309	CUP HOLDER
14U	Smartphone integration package
464	Instrument cluster display M
513	Road sign recognition system
U10	Front passenger seat with weight sensor
23P	DRIVING PACKAGE
246	Analogue clock
642	Dynamic LED headlamps, right-hand traffic
448	TOUCHPAD WITH ROTARY PUSHBUTTON
873	Seat heaters for driver and front passenger
537	DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)
651	Winter tyres fitted
367	Pre-installation for Live Traffic Information
U47	AMG spoiler lip
876	Interior lighting package
488	Steel/air suspension system
U01	Rear seat belt status indicator
L	LEFT-HAND DRIVE
266	DISTRONIC PLUS transverse support (DTR+Q)
641A	Fabric / imitation leather / microfiber - Black / anth.

RSV	AMG - double-spoke wheels 19" "mixed tires"
059	YoM X8/2
431	Steering wheel gearshift buttons/steering wheel shift paddles - Electroplated
P29	Interior AMG Line / interior AMG sport package
01U	Mercedes-Benz Connect - Services for navigation
809	YoM X8/1
998	Control code for conversion to WLTP with RDE
P31	Exterior AMG Line / exterior AMG sport package
U09	Leather-clad instrument panel and beltline (embossed imit.)
628	Automatic high beam control plus (IHC+)
3U1	Head unit for Europe/CIS states/Mongolia
502	Multi-year free map updates
02B	Operating instructions and service booklet-German
969	Euro 6 technology COC document - with motor vehicle registration certificate, part 2
12U	Mercedes-Benz Connect - Services for Mercedes me Concierge Service (HERMES)
56V	Speed/load index 93Y XL + 96Y XL
8R1	Winter wheel and tire assembly - AMG double-spoke design 18"
6P5	Control code for Sales
79B	Pre-installation for digital radio standard DAB/DMB
U22	Front lumbar support adjustment

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2019



Aptarnavimas

2019-12 |  Vokietija | 14 991 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas



Aptarnavimas

2021-02 |  Vokietija | 22 453 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Stabdžių skysčio keitimas

Salono filtro keitimas



Aptarnavimas

2022-02 |  Vokietija | 37 512 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Pakeistas oro filtro elementas

Spark plugs replaced



Aptarnavimas

2023-01 |  Lietuva | 44 370 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Stabdžių skysčio keitimas

Salono filtro keitimas



Aptarnavimas

2024-02 |  Lietuva | 54 098 km



Žalos / remonto vertinimas

2024-06 |  Lietuva



Aptarnavimas

2025-04 |  Lietuva | 61 114 km


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalias ar transporto priemonės defektus



Svarbu prieš vertinant žalą:

Ne visi ataskaitoje esantys įrašai reiškia realią žalos ar eismo įvykio pasekmę.


Kai kurie įrašai gali atsirasti ne dėl pačios žalos, o dėl žalos vertinimo, likutinės vertės apskaičiavimo, draudimo bendrovių procesų, brangesnių remonto darbų, apžiūrų, diagnostikos, vertinimų prieš pardavimą ar kitų formalių procedūrų.

[Skaityti daugiau »](#)

Aptikome **1** su šia transporto priemone susijusius įrašus:



Žalos / remonto vertinimas



Data

2024-06

Fiksavimo šalis:



Lietuva

Preliminari remonto kaina

€500 - €750

CO₂ emisija

Kiek CO₂ emisijų išskiria šio modelio / metų transporto priemonės?



Autoistorija.lt įžvalga:

Kiekvienai transporto priemonei priskiriama CO₂ emisijos klasė (nuo "A" iki "G") pagal tai, kokį emisijos kiekį ji išskiria.



Taršos mokestis 
195 €



CO₂ emisija g/km
216 g/km



CO₂ emisijos klasė
F



Kuro tipas
Benzinas

CO₂ emisija (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija



JAV