



## Lexus

VIN kods

**JTHAABBH102002388**

Sugeneruota: 2025-04-02 17:37

Galioja: 21 d.

# Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis  
**Lexus**

 Pavarų dėžė  
**Automatinė**

 Pirmos registracijos metai  
**2021**

 Kuro tipas  
**Elektra**



## Skelbimas

 Rasta įrašų apie automobilio pardavimą



## Rida

 Nerasta neatitikimų ridos istorijoje



## Vagystės

 Įrašų nerasta



## Žalų / remontų vertinimas

 Rasta informacijos apie automobilio pažeidimus



## Nuotraukos

 Rastos istorinės automobilio nuotraukos

## Automobilio techninė informacija

(Originalo kalba)

Model	UX300e
Body type	Wagon
Type code	KMA10
Engine code	4KM
Transmission	Automatic

## Automobilio komplektacija

(Originalo kalba)

LPUG19	Luxury grade package
PFPWTT40	Protection film paint protection wax/film

FRRA17	Fr & rr stabilizer
WSCHT24	With active sound control
WBLHE26	With emergency brake lights
LTSLFN25	Led front turn signal lamp
DNRVMNH41	Day & night (auto) inside rear view mirror
TRKTEP25	Tire repair kit spare tyre
WDHN21	With windshield deicer
PUGVY20	Privacy uv back glass
WACHL29	With hill assist control (hac)
PUSGVY25	Privacy uv rear side glass
WRHO14	With roof rails
WRHB25	With (dab) satellite radio
WHS7	With abs
WPBMOSHL37	With (only p) air bag manual on-off sw
AUCERM1U50	Acm14-1 usa, can, eu, russia anti-corosion measures
WRACHL35	With (full range acc) cruise control
WALHN37	With (dynamic auto) headlamp levelling
LKAVL29	Lta+vib lane keep assist (lka)
NIGOI24	Nanoe minus ion generator
EWBHBWH32	Epb with brake hold parking brake
WDMHL30	With (color) roof drip moulding
TLS2S25	Tss 2/ lss +2 safety sense
PTTCEI38	Power tilt & telescopic steering column
WSRHA28	With traffic sign recognition
ETMCI23	Electric twin trip meter
EMFFAL29	Ethanol min. fill washer fluid
WCHR20	With wireless charger
ESDNM40	Eco/normal/sport integrated sport driving
UJ2X21	Usb*2+aux*1 audio jack
WARHO18	With front arm rest
NSMF16	Normal front seat
SLMOL27	Smooth leather seat material
WUDHA19	With head up display
ZCPPC25	Zippo 2 + card 1 key plate
WGHT20	With (with gps) clock
WCOSRLSHT57	With (without cut off switch) daytime running light system
AGGUI35	Acoustic green (uv) windshield glass
PMBK15	Pvm back monitor
WWWHA21	With rear window wiper

RTAIRSEE51	Rr tether anchor*2, iso-fix*2 child restraint system
WTHO17	With footrest type
WTTTCHC37	With package tray trim & tonneau cover
SSSOR26	Std (over sea) rear spoiler
ASSOI24	Auto + shitudo sensor a/c
WSBAHA37	With (d,p) adjustable seat belt anchor
RSIF29	Radio + sfin (tel/gps) antenna
WPHT23	With anti-chipping paint
PBDECDEA51	Power back door (w/handfree) auto & easy closer door
AMBRA29	Ahb-r brake m/cylind & booster
WCBHE32	With (kneepad, cover) console box
WHH221	With (fr:2) cup holder
WECMHA36	With e-call data communication module
BAREO18	Bynel door arm rest
WBMHO22	With door belt moulding
WCLHD32	With (led,fr2) door courtesy lamp
LIHUO23	Lexus door inside handle
MTLO14	Mould door trim
TTODR21	Tpo door trim ornament
WANSHV29	With emv and navigation system
WBHD21	With (std) floor board
WMHO13	With floor mat
WFCFLHD34	With (led fog) + cl front fog lamps
PHSE22	Passive front headrests
MVPLLP40	Maplamp(led) + vanity front personal lamp
PPSAEP38	Power (d & p 8-way) front seat adjuster
PTSBLF27	P/t+f/l, t/r front seat belt
DWBDC32	16.5" disc (hi) front wheel brake
WKLBHY23	With key, lamp glove box
WBLHD24	With (led) glove box lamp
WCHA31	With (w/washer) headlamp cleaner
WDCCHI38	With (hairline deco) i/p center cluster
WFOESHO52	With (room, foot, outhandle) illuminated entry system
WFPHN39	With (synthetic) instrument finish panel
WDLABDRHT52	With (active door lock) luggage and back door release
FRDTLI33	Full-trim luggage room & deck trim
WRLHU23	With 2 luggage room lamp
SLDAUDLEO44	Speed lock & door auto unlock power door lock
SAWAU24	4 seat auto power windows

WSHS28	With (Iss+2) pre-crash system
WARHA17	With rear arm rest
WFLHD23	With (led) rear fog lamp
UDXHOX24	Up down x3 rear headrests
SDSA425	3 seat 6:4 divid rear seat
EFSB3T35	Elr*3+outside f/l+p/t rear seat belt
WWTWDHA43	With (heavy with timer) rear window defogger
WDLMH41	With (rocker) rocker & door lower moulding
MHHLHN25	Mld hdlnng roof head lining
LLRM12	Led room lamp
DLRRBWAR42	D,p: lamp + reminder + rr seat belt warning
WLSHE42	With (electrical, 2way) seat lumbar support
WTSLHD31	With (led) side turn signal lamp
CAMR19	Csa (m/i) srs airbag
BEMSE25	Brushless e motor steering
VTALWSCE43	Voice, tel, acc, lda steering wheel switches
WAIPWH457	With (434mhz) autolocation tyre inflation pressure warning
WHC7	With vsc
TWDW22	Tandem windshield wiper
WAPAH46	With (driver and passenger) seat airconditioner
ETPCI30	Electric type accelerator pedal
EL321	Emv(l2)/13sp(ml) audio
WPPTH32	With (ahb-r) pvc brake pedal type
SNR14	Standard bumper
ARAPNO23	A rank cold area package
NBPDB33	Nordic, baltic destination package
ASGUI24	Acoustic front side glass
FLMALM28	For lhd model headlamp aiming
LWA3H23	Led (3) w/ ahs headlamps
WSPHI35	With stitch (washi) instrument panel
BCALE21	Bsm lane change assist
FLRLH26	Fr (w/ light) + rr register
KSE15	Km/h speedometer
COHCTO36	Center ornament (lexus, hi) wheel cap
OSMRRMREL41	Outer slide moon roof sun roof & moon roof
UC1S46	12v*1pcs+rr usb*2pcs accessory connector (n0 1)
SSEH43	Siren+shinnyu+keisha+glass anti-theft system
ESCCEM32	Eu se 7.5m battery charging cable
ATDC6T45	Ac (6.6kw, type2) + dc (50kw, chademo) charger

PFWAFLP43	Pollen&pm2. 5 filter w/deod clean air filter
DRDLSM31	D,p:2st1m, rr:1st2m dl door lock
CPOHOW41	Colour (w/o protector) door outside handle
WSASPHR35	With (fr,rr) std al door scuff plate
TRDAA36	Total ratio 11.691 front differential
WPRHO25	With front performance rod
EMIG19	Ev (side) grade mark
DCSEL27	D+ece48 light control system
PBDBDSC36	Plastic back door luggage & back door
WRKTWTTHP42	With rep. kit & tool, w/o tire luggage tray
LHSCLWO40	Led (w/o hot stamp) rear combination lamp
WPRPRHM49	With (bumper performance rod) rear performance rod
DWEWBIW33	17" disc with epb rear wheel brake
WTHU27	With (touchpad) remote touch
WCHHR34	With (d+p+rear cushion) seat heater
DPSSWP32	D:power, p:power seat side shield
ESSLKEH40	Ev (leather, std, sbw) shift lever & knob
WRIDALSHV46	With rev inhibit, d-opn autop shift lock system
LHSWTR39	Leather (w/pd, heat, stv) steering wheel
SDW5129	225/50r18 sm tire & disc wheel
Q1A16	Q711 transmission
AWCON28	Auto windshield wiper control
WCHA20	With traction control
WTIDHF30	With (7 tft) multi info display
SBNR19	Standard rear bumper
PFSAAF43	Pksa (o+v/ fr4rr4) parking support alt/brake
WIGHI33	With (hairline) door inner garnish
AHEARBPRVMOE54	Auto, ht, ec, as, rr, bsm, pvm outside rear view mirror
DLSR41	4b:w/smart (d+p+bd)+pbd wireless door lock

# Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.

Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2021



Aptarnavimas

2021-12

**Atlikti darbai:**

nežinoma paslauga



Įkeltas / atnaujintas  
skelbimas

2022-05 | Estija | 12 500 km

Patalpintas skelbimas internete apie šio automobilio pardavimą.



Aptarnavimas

2022-05 | 12 559 km

**Atlikti darbai:**

Atliktas aptarnavimas  
remonto paslauga



Įkeltas / atnaujintas  
skelbimas

2022-06 | Estija | 13 000 km

Pakeista rida: 13 000 km



## Žalos / remonto vertinimas

2023-01



## Žalos / remonto vertinimas

2023-05



## Aptarnavimas

2023-08 | 24 295 km

### Atlikti darbai:

Atliktas aptarnavimas



## Aptarnavimas

2023-09

### Atlikti darbai:

Programinės įrangos aptarnavimas



## Techninė apžiūra

2024-06 | 30 441 km

Apžiūros galiojimas iki: 2026-06

Atlikta techninė apžiūra - pakartotinė apžiūra:

**Be trūkumų.**



## Techninė apžiūra

2024-06 | 30 441 km

Atlikta techninė apžiūra - pirminė apžiūra:

**Dideli trūkumai.**



## Aptarnavimas

2024-08 | 31 796 km

### Atlikti darbai:

Atliktas aptarnavimas


# Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



# Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalias ar transporto priemonės defektus



Svarbu prieš vertinant žalą:

Ne visi ataskaitoje esantys įrašai reiškia realią žalos ar eismo įvykio pasekmę.


Kai kurie įrašai gali atsirasti ne dėl pačios žalos, o dėl žalos vertinimo, likutinės vertės apskaičiavimo, draudimo bendrovių procesų, brangesnių remonto darbų, apžiūrų, diagnostikos, vertinimų prieš pardavimą ar kitų formalių procedūrų.

[Skaityti daugiau »](#)

Aptikome **2** su šia transporto priemone susijusius įrašus:



## Žalos / remonto vertinimas



Važiuklės pažeidimai

Data


2023-01

Preliminari remonto kaina

€0 - €500



## Žalos / remonto vertinimas



Data

2023-05

Preliminari remonto kaina

€0 - €500 

# Informacija apie pardavimą

Rasta informacija apie automobilio skelbimus internete. Pardavimo laikas, kainos kitimas, informacija apie pardavėją.

Aptikome **1** su šia transporto priemone susijusius įrašus:



## SKELBIMAS

Skelbimas neaktyvus

Skelbimas patalpintas:

Šalis

Rida

Pardavėjo tipas:

2022-05

Estija

**12 500 km**

2022-05-04



**13 000 km**

2022-06-05


verslas

2022-06-05



Nuotraukos (13)





# Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija