

## Mercedes-Benz E 300

VIN kodas

**W1K2132531A929986**

Sugeneruota: 2025-12-02 13:16

Galioja: 259 d.

# Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis  
**Mercedes-Benz E 300**

 Pavarų dėžė  
**Automatinė**

 Pirmos registracijos metai  
**2021**

 Kuro tipas  
**Benzinas / Elektra**



## Rida



Nerasta neatitikimų  
ridos istorijoje



## Vagystės



Įrašų nerasta



## Nuotraukos



Automobilio istorinės  
nuotraukos nerastos

## Automobilio techninė informacija

(Originalo kalba)

|                 |  |
|-----------------|--|
| Production date | 2021-01-14                                   |
| Model           | E 300 e Wagon                                |
| Series          | E  |
| Generation      | 213  |
| Body type       | CREWBUS                                      |
| Type code       | 213  |
| Engine code     | INLINE 4-CYLINDER SPARK IGNITION ENGINE M274 |
| Power           | 85   |
| Fuel type       | Petrol                                       |
| Displacement    | 2.00   |
| Steering side   | Left   |
| Color           | Obsidian black - metallic finish             |
| Interior        | FABRIC - BLACK / ANTHRACITE                  |
| Transmission    | automatic                                    |

## Automobilio komplektacija

(Originalo kalba)

|      |  |
|------|--|
| 16U  | APPLE CARPLAY SMARTPHONE INTEGRATION                         |
| 17U  | ANDROID AUTO SMARTPHONE INTEGRATION                          |
| 235  | ACTIVE PARKING ASSIST  |
| 249  | AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS |
| 294  | KNEEBAG  |
| 351  | ECALL EMERGENCY CALL SYSTEM                                  |
| 362  | HERMES COMMUNICATIONS MODULE LTE                             |
| 475  | TIRE PRESSURE MONITOR (TPM)                                  |
| 500  | ELECTRICALLY FOLDING EXTERIOR MIRRORS                        |
| B59  | DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)              |
| GA   | AUTOMATIC TRANSMISSION                                       |
| HA   | REAR AXLE  |
| P44  | PARKING PACKAGE  |
| P49  | MIRROR PACKAGE   |
| U12  | VELOUR FLOOR MATS  |
| VL   | LEFT FRONT AXLE HALF   |
| VR   | RIGHT FRONT AXLE HALF  |
| 287  | THROUGH-LOADING FEATURE                                      |
| 875  | HEATED WINDSCREEN WASHER SYSTEM                              |
| M20  | DISPLACEMENT 2.0 LITER                                       |
| M274 | INLINE 4-CYLINDER SPARK IGNITION ENGINE M274                 |
| R01  | SUMMER TYRES   |
| 218  | Rear view camera   |
| 30P  | Stowage facility package                                     |
| 421  | 9-speed automatic transmission                               |
| 8U6  | Assistance system steering wheel control changeover          |
| 255B | MB-Mobilo with DSB and GGD                                   |
| 2U8  | Alternative refrigerant                                      |
| 725  | Roof rails in chrome look                                    |
| 927  | Exhaust treatment, Euro 6 technology                         |
| K13  | Control code for service interval 25000 km                   |
| PZB  | Control code for Sales                                       |
| U60  | Pedestrian protection - Active hood                          |
| 2U1  | Radiator shutter   |
| 891  | PREMIUM AMBIANCE ILLUMINATION                                |
| 897  | FRONT WIRELESS TELEPHONE CHARGING                            |
| LS2  | BODY-IN-WHITE LOAD STAGE 2                                   |
| 20U  | KEYLESS RENTAL   |
| 365  | HARD DRIVE NAVIGATION  |

|      |  |
|------|--|
| 3U6  | HU COUNTRY SET FOR ECE/ROW   |
| 485  | COMFORT SUSPENSION   |
| 51B  | RATING, COUNTRY GROUP EURO-NCAP  |
| 8U8  | I-SIZE MARKING (ISOFIX SUCCESSOR)  |
| B51  | TIREFIT  |
| K31  | NOISE REGULATIONS AS PER ECE R51-03                                      |
| 549  | CONNECT 20 HIGH (NTG6)   |
| 8U7  | REAR PASSENGER COMPARTMENT SEAT BELT WITH BELT FORCE LIMITER AND SOFTST. |
| B53  | EXTERNAL NOISE SOUND GENERATOR FOR HYBRIDS AND EV                        |
| P65  | ERGONOMICS PACKAGE   |
| U19  | AUGMENTED REALITY VIDEO  |
| 229L | GERMANY  |
| 2XXL | FEDERAL REPUBLIC OF GERMANY  |
| 332B | LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN                               |
| 70B  | SAFETY VEST - DRIVER   |
| F213 | MODEL SERIES 213   |
| 728  | CENTER CONSOLE IN PMMA VERSION (9051)                                    |
| 300A | FABRIC   |
| 301A | FABRIC - BLACK / ANTHRACITE  |
| FS   | CREWBUS  |
| L2B  | LEATHER LUXURY STEERING WHEEL  |
| 469  | DIFFERENT TIRE INFLATION PRESSURE  |
| ME05 | HYBRID DRIVE 85 KW-94 KW VARIANT (INCL. PLUG-IN)                         |
| O16  | SOFTWARE FRESH-UP 3  |
| H41  | Trim elements - Aluminum Shine (2B51)                                    |
| K37  | Deactivation of locking feedback via horn                                |
| 88U  | Headliner, gray fabric   |
| 999  | Exhaust system with OPF, generation 3.0                                  |
| PVA  | Control code for Sales   |
| 085  | World manufacturer conversion to Mercedes-Benz AG                        |
| 0B3  | Vehicle production location Sindelfingen                                 |
| 1B3  | Communication module ECE version   |
| 270  | GPS aerial   |
| 299  | PRE-SAFE®  |
| 580  | Air-conditioning system  |
| 7B4  | WIPPS countries WEU+COC  |
| 868  | Central display size L   |
| 890  | Automatic rear-end door  |

|      |   |
|------|---|
| K11  | Adaptive brake light, flashing  |
| 309  | CUP HOLDER  |
| 14U  | Smartphone integration package  |
| 197U | Obsidian black - metallic finish  |
| 355  | Preinstallation for retrofitting navigation system                            |
| 414  | Electric sunroof, glass version   |
| 513  | Road sign recognition system  |
| U10  | Front passenger seat with weight sensor                                       |
| 642  | Dynamic LED headlamps, right-hand traffic                                     |
| GH   | HYBRID TRANSMISSION   |
| 76B  | AC charging function single-phase/multiphase Mid (6 kW-7.7 kW)                |
| 446  | Touchpad only   |
| 873  | Seat heaters for driver and front passenger                                   |
| 234  | Blind Spot Monitoring   |
| 537  | DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)                              |
| N2C  | Plant control code  |
| 367  | Pre-installation for Live Traffic Information                                 |
| 876  | Interior lighting package   |
| P35  | Light Package   |
| U01  | Rear seat belt status indicator   |
| PBF  | MBUX Navigation Plus  |
| L    | LEFT-HAND DRIVE   |
| 051  | YoM X0/2  |
| 13U  | Mercedes-Benz Connect - EV functions  |
| 38U  | Services for remote access and charging plus                                  |
| 63B  | Vehicle socket XEV Combo 2/Type 2   |
| B30  | Charging cable Schuko CEE 7/7 (Type E/F) 4M/5M                                |
| B33  | Charging cable 7-pin ICCA as per IEC 62196 16A 4M/5M                          |
| 431  | Steering wheel gearshift buttons/steering wheel shift paddles - Electroplated |
| B10  | Fuel tank packages for Euro-6D standard                                       |
| 01U  | Mercedes-Benz Connect - Services for navigation                               |
| 998  | Control code for conversion to WLTP with RDE                                  |
| 258  | Collision warning system with FCW-Stop active brake application               |
| 628  | Automatic high beam control plus (IHC+)                                       |
| 801  | YoM X0/1  |
| U35  | 12 V socket in load compartment   |
| R32  | Light-alloy wheel 5-spoke-design 18" "mixed tires"                            |
| 7U0  | Alternative hood  |
| 02J  | Invalid changeover of world manufacturer to Mercedes-Benz AG (ASF)            |

|     |  |
|-----|--|
| 22V | Speed/load index 100Y XL + 103Y XL   |
| 502 | Multi-year free map updates  |
| 02B | Operating instructions and service booklet-German                                    |
| 969 | Euro 6 technology COC document - with motor vehicle registration certificate, part 2 |
| P14 | Equipment line/package – AVANTGARDE – Interior                                       |
| P15 | Equipment line/package – AVANTGARDE – Exterior                                       |
| 6P5 | Control code for Sales   |
| 79B | Pre-installation for digital radio standard DAB/DMB                                  |
| U22 | Front lumbar support adjustment  |

# Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.

Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.

Žiūrėti originalo kalba



2021



## Aptarnavimas

2021-10 |  Vokietija | 24 107 km

### Atlikti darbai:

Salono filtro keitimas  
Variklio alyvos ir filtro keitimas



## Aptarnavimas

2022-10 |  Lietuva | 36 962 km

### Atlikti darbai:

Salono filtro keitimas  
Pakeistas oro filtro elementas  
Variklio alyvos ir filtro keitimas



## Aptarnavimas

2023-09 |  Lietuva | 46 552 km

### Atlikti darbai:

Salono filtro keitimas  
Variklio alyvos ir filtro keitimas  
Stabdžių skysčio keitimas



## Techninė apžiūra

2024-01 |  Lietuva | 48 162 km

Apžiūros galiojimas iki: 2026-01  
Atlikta techninė apžiūra - pirminė apžiūra:  
**Be trūkumų.**


# Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



# Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

# CO<sub>2</sub> emisija

Kiek CO<sub>2</sub> emisijų išskiria šio modelio / metų transporto priemonės?



Autoistorija.lt įžvalga:

Kiekvienai transporto priemonei priskiriama CO<sub>2</sub> emisijos klasė (nuo "A" iki "G") pagal tai, kokį emisijos kiekį ji išskiria.



Taršos mokestis   
0 €



CO<sub>2</sub> emisija g/km  
38 g/km



CO<sub>2</sub> emisijos klasė  
A



Kuro tipas  
Benzinas / Elektra

CO<sub>2</sub> emisija (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

# Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija