

Mercedes-Benz A 250

VIN kodas

W1K1771861J252323

Sugeneruota: 2026-02-03 15:35

Galioja: 350 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Mercedes-Benz A 250

 Kuro tipas
Benzinas / Elektra

 Pavarų dėžė
Automatinė



Rida



Nerasta neatitikimų
ridos istorijoje



Vagystės



Įrašų nerasta



Nuotraukos



Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2020-07-31
Model	A 250 e
Series	A
Generation	177
Body type	Long sedan
Type code	177
Engine code	INLINE 4-CYLINDER SPARK IGNITION ENGINE M282
Fuel type	Petrol
Displacement	1.40
Steering side	Left
Color	POLAR WHITE - STANDARD FINISH
Interior	Fabric/ imitation leather/ microfiber - Black/ anthracite
Transmission	automatic

Automobilio komplektacija

(Originalo kalba)

149U

POLAR WHITE - STANDARD FINISH

16U	APPLE CARPLAY SMARTPHONE INTEGRATION
17U	ANDROID AUTO SMARTPHONE INTEGRATION
235	ACTIVE PARKING ASSIST
294	KNEEBAG
351	ECALL EMERGENCY CALL SYSTEM
362	HERMES COMMUNICATIONS MODULE LTE
475	TIRE PRESSURE MONITOR (TPM)
543	SUN VISOR WITH ADDITIONAL FUNCTION
840	GLAS DUNKEL GETÖNT
B59	DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
VL	LEFT FRONT AXLE HALF
VR	RIGHT FRONT AXLE HALF
287	THROUGH-LOADING FEATURE
345	RAIN SENSOR
440	CRUISE CONTROL
51U	HEADLINER, BLACK FABRIC
772	AMG STYLING - FRONT SPOILER, SIDE SKIRTS
877	AMBIENT LIGHTING
U26	FLOOR MATS - AMG
08U	Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)
09U	Mercedes-Benz Connect - Vehicle Monitoring (HERMES)
218	Rear view camera
8U6	Assistance system steering wheel control changeover
255B	MB-Mobilo with DSB and GGD
2U8	Alternative refrigerant
650A	Fabric/imitation leather/microfiber
927	Exhaust treatment, Euro 6 technology
K13	Control code for service interval 25000 km
PXV	Control code for Sales
U60	Pedestrian protection - Active hood
2U1	Radiator shutter
310	DOUBLE CUP HOLDER
20U	KEYLESS RENTAL
243	ACTIVE LANE KEEPING ASSIST (CAMERA)
365	HARD DRIVE NAVIGATION
3U6	HU COUNTRY SET FOR ECE/ROW
485	COMFORT SUSPENSION

51B	RATING, COUNTRY GROUP EURO-NCAP
548	CONNECT 20 MID (NTG6)
8U8	I-SIZE MARKING (ISOFIX SUCCESSOR)
961	EXHAUST SYSTEM WITH OPF, GENERATION 2.0
98B	UPPER RADIATOR SHUTTERS
K31	NOISE REGULATIONS AS PER ECE R51-03
M14	DISPLACEMENT 1.4 LITER
M282	INLINE 4-CYLINDER SPARK IGNITION ENGINE M282
P55	NIGHT PACKAGE
0B2	Vehicle production location Rastatt
1U5	RUBBER-SPRUNG STEERING GEAR
F177	MODEL SERIES 177
U54	COMPOUND-LINK AXLE
B53	EXTERNAL NOISE SOUND GENERATOR FOR HYBRIDS AND EV
L5C	SUPERSPORT STEERING WHEEL - LEATHER DEEP-EMBOSSSED
229L	GERMANY
2XXL	FEDERAL REPUBLIC OF GERMANY
332B	LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN
70B	SAFETY VEST - DRIVER
426	AUTOMATIC DUAL-CLUTCH TRANSMISSION, 8-SPEED
B80	CHARGING CABLE SCHUKO CEE 7/7 (TYPE E/F) 8M
JGJ	PLANT CONTROL CODE
R7K	WHEEL SIZE 19" ALL-ROUND VARIANT 1
O16	SOFTWARE FRESH-UP 3
K37	Deactivation of locking feedback via horn
V76	Speed/load index 93H XI
085	World manufacturer conversion to Mercedes-Benz AG
1B3	Communication module ECE version
270	GPS aerial
580	Air-conditioning system
7B4	WIPPS countries WEU+COC
950	AMG line
U62	Exterior light and sight package
14U	Smartphone integration package
355	Preinstallation for retrofitting navigation system
513	Road sign recognition system
632	Headlamps, LED, static, right-side traffic
U10	Front passenger seat with weight sensor
446	Touchpad only

873	Seat heaters for driver and front passenger
413	Automatic panoramic sliding sunroof
U59	Seat comfort package
537	DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)
645	M+S winter tyres, set of 4
367	Pre-installation for Live Traffic Information
7U4	Seat model variant 4
U01	Rear seat belt status indicator
PBF	MBUX Navigation Plus
L	LEFT-HAND DRIVE
RVG	AMG multi-spoke wheels 19" "all-round"
ME08	Hybrid drive 75 kW-84 kW (90 kW-V213) var. (plug-in)
13U	Mercedes-Benz Connect - EV functions
63B	Vehicle socket XEV Combo 2/Type 2
431	Steering wheel gearshift buttons/steering wheel shift paddles - Electroplated
B10	Fuel tank packages for Euro-6D standard
01U	Mercedes-Benz Connect - Services for navigation
998	Control code for conversion to WLTP with RDE
258	Collision warning system with FCW-Stop active brake application
801	YoM X0/1
651A	Fabric/ imitation leather/ microfiber - Black/ anthracite
80B	Single-phase low AC charging function (3.2 kW-3.8 kW)
02J	Invalid changeover of world manufacturer to Mercedes-Benz AG (ASF)
286	Luggage nets to left and right driver seat backrests
502	Multi-year free map updates
02B	Operating instructions and service booklet-German
969	Euro 6 technology COC document - with motor vehicle registration certificate, part 2
FV	Long sedan
6P5	Control code for Sales
79B	Pre-installation for digital radio standard DAB/DMB

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2020



Aptarnavimas

2021-08 |  Suomija | 3 224 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas



Aptarnavimas

2022-08 |  Suomija | 9 492 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Stabdžių skysčio keitimas



Aptarnavimas

2023-08 |  Suomija | 14 944 km

Atlikti darbai:

Variklio alyvos ir filtro keitimas

Pakeistas oro filtro elementas

Spark plugs replaced



Aptarnavimas

2024-08 |  Suomija | 19 804 km



Aptarnavimas

2025-08 |  Suomija | 32 605 km


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

CO₂ emisija

Kiek CO₂ emisijų išskiria šio modelio / metų transporto priemonės?



Autoistorija.lt įžvalga:

Kiekvienai transporto priemonei priskiriama CO₂ emisijos klasė (nuo "A" iki "G") pagal tai, kokį emisijos kiekį ji išskiria.



Taršos mokestis 
0 €



CO₂ emisija g/km
20 g/km



CO₂ emisijos klasė
A



Kuro tipas
Benzinas / Elektra

CO₂ emisija (g/km)

0 - 120 **A**

120 - 140 **B**

140 - 155 **C**

155 - 170 **D**

170 - 190 **E**

190 - 225 **F**

225 + **G**

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija