

Volkswagen Arteon

VIN kodas

WVWZZZ3HZNE507213

Sugeneruota: 2025-06-04 13:30

Galioja: 74 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Volkswagen Arteon

 Kuro tipas
Benzinas

 Pirmos registracijos metai
2022



Rida



Nerasta neatitikimų
ridos istorijoje



Vagystės



Įrašų nerasta



Nuotraukos



Automobilio istorinės
nuotraukos nerastos

Automobilio techninė informacija

(Originalo kalba)

Production date	2022-03-17
Model	Arteon SB R-L GT140 D7F
Series	Arteon
Type code	3H94LZ
Engine code	DNNA 4-cylinder SI engine 2.0 I TSI, 140 kW
Power	140
Fuel type	Petrol
Displacement	2.00
Drive type	FWD
Steering side	Left
Color	Pyrite Silver Metallic
Interior	Titanium Black/Titanium Black/Titanium Black
Transmission	automatic
Transmission code	UES

Automobilio komplektacija

(Originalo kalba)

PE0A	No special edition
PGP1	Vehicles with special upgrade measures
P1T2	Warning triangle
P1D0	Without trailer hitch
P1SA	Without additional front underbody guard
P0Y3	Cold zones
PQQ0	Without add. lights (interior lighting)
PKK3	Refrigerant R1234yf
PKS0	Without head-up display
PFN7	Variant
P3FA	Without roof insert (standard roof)
P4D0	Without seat ventilation/massage seat
P5C0	Without special body measures
P7ZS	Vehicle class differentiation -3H0-
P8Z5	Not hot country
P8FA	Without second battery
PQH0	Without voice control
PJ0V	Battery 420 A (70 Ah)
PEF0	Without ECO function
PFC1	Customized installation
PF0A	No special purpose vehicle, standard equipment
PQA0	Without child seat
PIG0	Standard curb weight range
P0YE	Weight range 5 installation control only, no requirement forecast
P0FA	Standard manufacturing sequence
P5K7	Transport protection film (minimum protection) with additional transport protection measures
P1S1	Tool kit and jack
P2WA	Without additional tires
P7G0	Without preparation for VTS (vehicle tracking system)
P1Z0	Initial standard fuel filling
P8GV	Alternator 180 A
P3LF	Door and side trim panel in foam film, insert in leatherette
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P7QA	Without CD/DVD for navigation
P6A0	Without fire extinguisher
PL45	Suspension range 45 installation control only, no requirement forecast
P8Y1	Two-tone horn
P3CX	Net partition

PEV0	Without charging cable
PAV1	Driving on the right
P1Y0	Without differential lock
PNY0	Standard battery/alternator capacity
PES0	Without vehicle inlet
PFB0	Standard paint coating
P2A0	Without delivery equipment
P7U0	Standard engine starter
P9D0	Without preparation for two-way radio installation
P0P1	Rear side exhaust tailpipe
P1Q2	Mass damper for steering wheel, 36 Hz
PA60	Category 0
P4BI	Emission standard EU6 AP
PT2C	4-cylinder SI engine 2.0 l
P0M4	Fuel tank
PC21	Operating permit, alteration
PK8R	Sportsback
P0RF	With electronic steering column lock
P0B5	Wheelbase
P1JA	Rear shock absorption, basic version 1
P2H0	Without Adaptive Chassis Control
P4A3	Heated front seats
P4ZB	Chrome moldings on the side windows
P7Y0	Without lane change assist
P8RM	8 speakers
P9M0	Without auxiliary heater/parking heater
P9Z0	Operating voltage 12 V
PA8F	Sports equipment
PB0A	Part set without country-specific prescriptive standard
PEM1	Driver alert system
PG02	Shock absorption in front
PL0L	Left-hand drive
PQG1	LongLife Service Regime
PQI6	Service indicator 30 000 km or 2 years (variable)
P6Q2	Gearshift knob in leather
P7K1	Tire pressure monitoring system
P0IJ	Dual-clutch transmission DSG DQ381
P0K0	Without alternative drive system
P0NB	Elimination of nameplate for engine designation on luggage compartment lid

P0TD	Carpet mats in front and rear
P1PE	Wheel locks with extended theft protection
P1X0	Front-wheel drive
P1ZK	Disc brakes in front
P20A	Without electric motor (hybrid)
P2EI	Disc brakes in rear
P31K	License plate carrier in front and rear (ECE)
P3H0	Non-folding front passenger seat backrest
P3QT	3-point seat belts in front with height adjustment and seat belt pretensioners
P3T2	3 head restraints in rear
P3ZU	3-point seat belts with seat belt pretensioners for the outer rear seats
P4L6	Auto-dimming interior rearview mirror
P4X3	Curtain airbag system for front and rear passengers incl. side airbags in front
P5RQ	Right exterior mirror, convex
P5SL	Aspherical exterior mirror on driver side
P5XJ	Illuminated vanity mirrors in sun visors
P6K4	Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)
P7L6	Start-stop system with regenerative braking
P8AR	Radio
P8N6	Rain sensor
P8T8	Adaptive Cruise Control ACC stop & go incl. speed limiter
P8X0	Without headlamp washer system
P9P9	Warning signal and warning lamp for front and rear seat belts not fastened
P9S0	Multi-color Digital Cockpit "Pro" selection of different info profiles possible
P9T1	Automatically-heated washer nozzles in front
P9WJ	App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto
PG1C	7-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF
PGM1	Electronic engine sound
PQ4H	Premium comfort seats in front
PQK1	Multifunction camera
PQR8	Without dynamic road sign display
PQV3	Digital radio reception DAB+
PUH2	Electromechanical parking brake with Auto Hold function
P0SC	Labels in English
P1N7	Progressive steering
P3D3	Decorative inserts "Piano Black" for center console
P3GA	Luggage compartment floor

P3KB	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest and load-through hatch
P3U1	Luggage compartment cover
P3W4	Acoustics package "Standard"
P3Y0	Without roll-up sunshade
P4B4	Lower side trims in chrome
P4UN	Driver and front passenger airbag with front passenger airbag deactivation, including knee airbag on driver side
P4V0	Without front passenger seat control
P6SE	Textile luggage compartment trim
P7B6	12-V outlet in center console in rear
P7E0	Without heat accumulator/auxiliary heater
P7M1	Scuff plates w/ stainless steel inserts
P9TJ	LED entry/warning lights in front doors
PQJ3	Chrome elements on door pulls, on the rotary light switch and on the front vents
PUG6	Hill Start Assist
PVC0	Without garage door opener
PVF1	Pedals in brushed stainless steel
PVL4	Pedestrian monitoring and re-active hood
P5ZF	Safety-optimized front head restraints
PKA2	Rear view camera system
P7P7	Lumbar supports in front, power-adjustable on driver side
PSA0	Model update, week 45
PV0A	Tires without specification of tire brand
P7W2	Proactive passenger protection system in combination with Front Assist
P7X2	Park Distance Control - warning signals for obstacles in the front and rear
P8Q3	Dynamic headlight range control
P1A5	Fuel system for fuel-injected SI engine
P1G6	Space- and weight-saving spare wheel
PU5A	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
P1AQ	Electronic Stability Control and electromechanical brake booster
P2F0	Without locking and starting systems
P6T1	LED light unit in front footwell
P9JA	Non-smoker's package: 12-V outlet in front
P6Y8	Electronic restriction of top speed
P8TL	Rear fog light on one side, back-up light on both sides
P8IT	LED headlamps with LED separate daytime running light
P9B0	Without integrated toll system
PQ48	AirStop® tires 245/40 R19

P8WA	Without front fog lamps
P2PT	Leather-wrapped multi-function sports steering wheel, heated, with touch control and shifting paddles
P5I3	Easy Open & Close - sensor controlled luggage compartment opening and closing with remote unlocking
P5TH	Decorative inserts in aluminum "Silver Rise" for dashboard and door trim panels
P8S6	Interior lights with switch-off delay and dimmer, 2 LED reading lights in front and 2 in rear
P8VP	3D LED rear combination lamps with dynamic turn signal
P4F2	Keyless locking and starting system Keyless Access with SAFELOCK
P7AL	Anti-theft alarm system with interior monitoring, backup horn, and towing protection
P1EX	Special identification label for EC for M1 passenger vehicles
PER1	Regional code " ECE " for radio
P4KF	Privacy glass for rear side windows and rear window
P6NW	Titanium Black headliner
P3PW	Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment
P8ZQ	Diversity antenna for FM reception
P6XI	Ext. mirror w/ surround lighting a. fr. passenger ext. mirror lowering funct., folding/heated, auto-dimming on dr. side
PPGW	Heated (without wires) and infrared-reflecting windshield
P8G1	High-beam control Light Assist
PEL5	Online service, with OCU, with head unit coding, without engine immobilizer interconnection
PNZ4	Emergency call service; no registration required, service is activated upon delivery
PYOR	Preparation for We Connect and We Connect Plus
P1E5	Activated carbon canister (Evaporative Emission Control System (EVAP))
P45T	4 alloy wheels "Montevideo" 8J x 19, black, diamond-turned surface
P6E3	Front center armrest with storage compartment, 2 rear vents
PPJW	Montevideo 8J x 19, Black, diamond-turned surface, Volkswagen R, AirStop® tires 245/40 R19
PU9B	USB-C interface
PW12	VE: NCAP package
PWD5	Anti-theft alarm system
P6I6	Comfort drive Travel Assist, lane keeping system Lane Assist and Emergency Assist
PPEL	Easy Open & Close package with SAFELOCK
P7UJ	Preparation for subsequent activation: Navigation feature "Discover Media" incl. Streaming & Internet
PRBB	Radio "Ready 2 Discover" incl. "Streaming & Internet"
PX3M	Equipment options subset for the Baltic States
PDQ6	4-cylinder SI engine 2.0 I TSI, 140 kW
PWFA	Lights & Vision package incl. high-beam control Light Assist

P4GW	Laminated safety glass windshield, heated (w/o wires), infrared-reflecting windshield, sound-insulating
P9IP	Mobile phone interface "Comfort" with inductive charging feature
PB72	Type approval country Lithuania
P3A0	ISOFIX anchorage points for mounting of 2 child seats on rear bench seat, also for i-Size child seats
PKH0	Air Care Climatronic 3 zone automatic climate control with enhanced air filterwith activated carbon
P9I5	Separate daytime running light with automatic headlight control and automat. Coming and Leaving Home feature
P2JX	Front bumpers in "R" style, trapezoidal trim panels in chrome in rear bumper
PN4J	Inserts of front seats and outer rear seats in ArtVelours microfleece
P0XR	Manual in Lithuanian

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.



Žiūrėti originalo kalba



2022



Aptarnavimas

2022-04 |  Lietuva | 11 km

Atlikti darbai:

Serviso patikrinimas



Techninė apžiūra

2022-04 |  Lietuva | 7 km

Apžiūros galiojimas iki: 2025-04

Atlikta techninė apžiūra - naujam automobiliui:

Be trūkumų.



Aptarnavimas

2023-04 |  Lietuva | 17 766 km

Atlikti darbai:

Tepalų servisas



Aptarnavimas

2023-04 |  Lietuva | 17 766 km

Atlikti darbai:

nežinoma paslauga



Aptarnavimas

2023-11 |  Lietuva | 29 863 km

Atlikti darbai:

Tepalų servisas
Filtrai



Aptarnavimas

2024-08 |  Lietuva | 45 773 km

Atlikti darbai:

Tepalų servisas
Stabžių aptarnavimas



Techninė apžiūra

2025-04 |  Lietuva | 58 325 km

Apžiūros galiojimas iki: 2027-04

Atlikta techninė apžiūra - pirminė apžiūra:

Be trūkumų.


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija