



Mercedes-Benz G 350

VIN kodas

WDB4633491X315064

Sugeneruota: 2025-08-22 15:04

Galioja: 206 d.

Informacija

Pateikiami pagrindiniai tikrinamo automobilio duomenys bei atliktų patikrinimų santrauka.

 Markė, modelis
Mercedes-Benz G 350

 Pavarų dėžė
Automatinė

 Pirmos registracijos metai
2019

 Kuro tipas
Dyzelinas



Skelbimas

✓ Rasta įrašų apie automobilio pardavimą



Rida

✓ Nerasta neatitikimų ridos istorijoje



Vagystės

✓ Įrašų nerasta



Nuotraukos

✓ Rastos istorinės automobilio nuotraukos

Automobilio techninė informacija

(Originalo kalba)

Production date	2019-02-12
Model	G 350 d
Series	G
Generation	463
Body type	STATION WAGON WIDE
Type code	463
Engine code	INLINE 6-CYLINDER DIESEL ENGINE, OM656
Fuel type	Diesel
Displacement	2.90
Steering side	Left
Color	Obsidian black metallic

Interior	LEATHER - BLACK / ANTHRACITE
Transmission	automatic

Automobilio komplektacija (Originalo kalba)

989	IDENTIFICATION LABEL UNDER WINDSHIELD
GA	AUTOMATIC TRANSMISSION
K14	CONTROL CODE FOR SERVICE INTERVAL 20000 KM
08U	Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)
09U	Mercedes-Benz Connect - Vehicle Monitoring (HERMES)
15U	Pre-installation for MB-Link smartphone integration
M013	Derated engine
M29	DISPLACEMENT 2.9 LITER
M656	INLINE 6-CYLINDER DIESEL ENGINE, OM656
8U8	I-SIZE MARKING (ISOFIX SUCCESSOR)
229L	GERMANY
2XXL	FEDERAL REPUBLIC OF GERMANY
332B	LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN
A53	ACTIVE LANE KEEPING ASSIST
BS4	BRAKE CALIPER WITH LETTERING
C59	DOOR SILLS AT FRONT IN STAINLESS STEEL
EA2	BLIND SPOT MONITORING
EK0	MERCEDES-BENZ EMERGENCY CALL SYSTEM
EK1	HERMES COMMUNICATIONS MODULE LTE
EU4	COMAND ONLINE
EV1	SMARTPHONE INTEGRATION
EV4	GOOGLE AUTOMOTIVE LINK SMARTPHONE INTEGRATION
EZ9	ACTIVE DISTANCE ASSIST DISTRONIC
F463	MODEL SERIES 463 - OFF-ROAD VEHICLE
FB	STATION WAGON WIDE
FD7	CONTROL CODE FOR REPOSITIONED OUTSIDE MIRRORS
JA6	COLLISION PREVENTION ASSIST
JA9	TRAFFIC SIGN ASSIST
JW8	ATTENTION ASSIST
M92	EXHAUST TREATMENT, EURO 6 TECHNOLOGY
P40	WIDER WHEEL ARCH FOR AMG WHEELS
RY6	TYRE PRESSURE MONITORING SYSTEM
S83	LOOP-DESIGN
W72	HEAT-INSULATING, DARK-TINTED GLASS

Y50	LOADING SILL PROTECTOR AT REAR IN STAINLESS STEEL
EO2	HEADUNIT EUROPE/CIS-STATES/MONOGLEI
PA2	RUBBER FLOOR MATS
X14	ECE COUNTRIES SELECTION CODE, EXTENDED
CK3	RADIATOR GRILLE PAINTED BLACK
EX6	6 YEARS' FREE MAP DATA UPDATES
X13	EU MEMBER STATES SELECTION CODE
X99	CONTROL CODE FOR USE OF M656
XN9	CONTROL CODE MODEL YEAR 9
EF6	Digital radio
E79	TELEPHONE ANTENNA
OT1	Control code for release bundle
B24	REMOTE CONTROL FOR AUXILIARY HEATER
200A	LEATHER
BB3	ELECTRONIC STABILITY PROGRAM (ESP)
201A	LEATHER - BLACK / ANTHRACITE
197U	Obsidian black metallic
EZ8	PARKTRONIC Park Assist
J25	Instrument cluster - FULL DIGITAL DISPLAY
MJ7	ECO start/stop function
250B	Mobilo
Y65	Alternative refrigerant
H12	Auxiliary heater
V57	LOAD COMPARTMENT COVER
VL4	RUBBER MAT FOR LOAD COMPARTMENT
PA8	PARKING PACKAGE
V43	FLOOR MATS - AMG
L57	IHC LIGHT
G43	AUTOMATIC TRANSMISSION 9G-TRONIC
JP0	PRE-SAFE SYSTEM
EM4	DRIVER ASSISTANCE PACKAGE PLUS
L5B	Leather Supersport steering wheel
RB4	SPARE WHEEL COVER PAINTED IN BLACK
U01	Rear seat belt status indicator
FZ8	ATA w. tow-away protection and interior monitoring
Y78	Scratch resistant clear coat
L	LEFT-HAND DRIVE
EU8	Burmester® 3D surround sound system
F15	Electric sunroof, glass version

RG6	50.8 cm (20") AMG light alloy wheels black
T84	Stainless Steel Side Running Boards
A20	Adjustable damping
Q55	Trailer coupl.,reinforced, ball head, low,
FB1	Cargo net
K81	Fuel tank with larger capacity
SH1	Sidebags in the rear bench seat
X92	*I* omission - Colored seat belt
998	Control code for conversion to WLTP with RDE
VA1	Open-pore black flamed ash-wood trim elements
EM0	Live Traffic capability (HERMES)
PA3	*I* exterior stainless steel package
NP1	*I* Night Package
PL1	*I* AMG LINE
X91	*I* omission - Colored topstitching
C90	Exterior protective strip - black pinstripe insert
FR1	*I* ambient lighting
MR8	Engine OM656 LA 29
IM5	Tires 275/50 R20 All-Season
CK1	Invalid outside mirror housing in black
EV3	Smartphone integration, CarPlay™
02B	Operating instructions and service booklet-German
969	Euro 6 technology COC document - with motor vehicle registration certificate, part 2
12U	Invalid Mercedes-Benz Connect - services for Mercedes me Concierge Service (HERMES)
JS1	360° camera (360° viewing system, Surround View)
PBG	Invalid Connectivity Package Premium
XZ8	Invalid change year 2018 (model year 2019)
TG2	Etg - E1*2007/46*1830*01 Model 463 Fb

Istorija

Rasti įvairių tipų automobilio istorijos įrašai laiko juostoje.



2019



Laikotarpyje nuo 2019-01 iki 2022-02 duomenų neradome



Techninė apžiūra

2022-02 |  Lietuva | 36 468 km

Apžiūros galiojimas iki: 2024-02

Atlikta techninė apžiūra - pirminė apžiūra:

Be trūkumų.



Įkeltas / atnaujintas skelbimas

2022-07 |  Lietuva | 38 000 km

Patalpintas skelbimas internete apie šio automobilio pardavimą.



[Daugiau informacijos »](#)



Įkeltas / atnaujintas skelbimas

2023-10 |  Lietuva | 67 070 km

Patalpintas skelbimas internete apie šio automobilio pardavimą.



[Daugiau informacijos »](#)



Techninė apžiūra

2023-10 |  Lietuva | 67 120 km

Apžiūros galiojimas iki: 2025-10

Atlikta techninė apžiūra - pirminė apžiūra:

Nedideli trūkumai.


Rida

Iš įvairių šaltinių surinkti duomenys apie fiksuotą automobilio ridą, jos kitimas.



Autoistorija.lt įžvalga:

Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Iš įvairių šaltinių surinkti duomenys apie fiksuotus eismo įvykius, žalas ar transporto priemonės defektus

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.



Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazines. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

Informacija apie pardavimą

Rasta informacija apie automobilio skelbimus internete. Pardavimo laikas, kainos kitimas, informacija apie pardavėją.

Aptikome 2 su šia transporto priemone susijusius įrašus:



SKELBIMAS

Skelbimas neaktyvus

Skelbimas patalpintas

Šalis

Rida

Pardavėjo tipas

Pardavėjo tapatybė

2022-07

 Lietuva

38 000 km

2022-07-15

Privatus asmuo

Nepatvirtinta

2022-07-15 |  Nuotraukos (9)





SKELBIMAS

Skelbimas neaktyvus

Skelbimas patalpintas

Šalis

Rida

Pardavėjo tipas

Pardavėjo tapatybė

2023-10

Lietuva

67 070 km



2023-10-06







Verslas

Nepatvirtinta

2023-10-06

Nuotraukos (28)





Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.



Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:



Lietuva



Slovėnija



Slovakija



Čekija



Vengrija



Italija



Rumunija



Vokietija