

Skoda Superb

Вин-номер

TMBCE7NP7H7513035

Отчет создан: 2025-05-16 16:46

Действительно: 64 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.



Марка, модель

Skoda Superb



Коробка передач

Автомат



Год первой регистрации

2016



Тип топлива

Бензин



Пробег



В истории пробега не обнаружены несоответствия



Кражи



Записей не найдено



Фотографии



Исторических фотографий автомобиля не найдено.

Технические данные

(Язык оригинала)

Production date	2016-11-21
Model	SUPERB GrtAMB TS206/2.0A6A
Series	SUPERB
Type code	3V33UX
Engine code	CJXA 4-cylinder SI engine 2.0 l/206 kW TFSI, homogeneous base engine is TT6/TA2
Power	206
Fuel type	Petrol
Displacement	2.00
Steering side	Left
Color	Corrida Red
Interior	Black Alcantara
Transmission	automatic
Transmission code	SGA

Оборудование

PKA0	Without camera systems/accident sensors
PKK3	Refrigerant R1234yf
PAV1	Driving on the right
PEV0	Without charging cable
PF0A	No special purpose vehicle, standard equipment
P2WA	Without additional tires
P3ZU	3-point seat belts, outer rear with ECE label
P0Y3	Cold zones
P3CA	Without partition
P6A0	Without fire extinguisher
P0FA	Standard manufacturing sequence
P1PA	Standard wheel bolts
P0VN	Information kit in Finnish
P7W0	Without extended safety system
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P8N6	Windshield wiper intermittent control with light/rain sensor
P8WH	Front fog lamp and cornering lamp
PIA1	With bracket
P0YE	Weight range 5 installation control only, no requirement forecast
P3H0	Without backrest release for front seats
P3S0	Without roof rails/roof load rack
P8Y1	Two-tone horn
PJ2D	Battery 380 A (68 Ah)
PQH1	Voice control
PUG1	Hill hold control
PQN2	Drawer under right front seat
PVL1	Extended pedestrian protection measures
P2G7	Filler neck module 1 with insert
P3C7	3-point seat belt for center rear seat
P2JV	Body-colored bumpers
P1SA	Without additional front underbody guard
P3W6	Additional interior noise suppression
P1E1	Activated carbon canister
P2B1	Additional exterior noise suppression
P8FA	Without second battery
P6FM	Components with special surface appearance
P9HA	Without additional malfunction display

PL18	Suspension range 18 installation control only, no requirement forecast
PE2G	Sports package
PK8B	Notchback
P0P0	Rear exhaust tailpipe (standard)
P1Q0	Without mass damper for steering wheel
PDF5	4-cylinder SI engine 2.0 l/206 KW TFSI, homogeneous base engine is TT6/TA2
PVF1	Pedal cluster
P1Z2	Increase in initial standard fuel filling
P2A0	Without delivery equipment
P1S3	Tool kit
P5C0	Without special body measures
PNS3	With umbrella
PEF1	ECO function
PFB0	Standard paint coating
PFM0	Basic equipment variant
P5MR	Decorative inserts
P7UG	Navigation system - High
P3D2	Center console
P6KC	Radiator grille
P8GV	Alternator 180 A
PA65	Category 5
PQQ9	Interior ambient lighting, type 2
PI8H	High radio (Gen2)
PTT6	4-cylinder SI engine 2.0 l unit 06K.C
PES0	Without vehicle inlet
PUH2	Parking brake
P9D0	Without preparation for two-way radio installation
P77G	Data storage device for EU, integrated
P9M9	Parking heater with radio remote control
PKS0	Without head-up display
P4D0	Without seat ventilation/massage seat
P4GW	Heat insulating windshield
P7B3	12-volt socket(s)
P5J8	Rear spoiler (type 3)
PQA0	Without child seat
PHI9	Tires 235/40 R19 96W
PUP1	Digital clock
P0M4	Fuel tank
P0B5	Wheelbase

P1VG	Installation parts for four-cylinder engine
P0G7	Tiptronic
P3LC	Door and side trim panel in foam film and woven fabric
PC41	Operating permit, alteration
P7U0	Standard engine starter
PB0G	Component parts set, complying with vehicle type for Finland, various parts
PWX3	Winter package
P1EX	Special identification label for EC for M1 passenger vehicles
P1NL	Trims for alloy wheels
P4X3	Side airbag in front with curtain airbag
P5K5	Transport protection film with additional transport protection measures
P5RQ	Right exterior mirror, convex
P6N0	Without mud flap
P7AA	Electronic immobilizer
PL0L	Left-hand drive
PQ4H	Sports comfort seats in front
PQG1	LongLife Service Regime
PQV0	Without TV reception/digital radio reception
PV0A	Tires without specification of tire brand
P3U1	Folding trunk cover
P7E0	Without heat accumulator/auxiliary heater
PA8C	Comfort equipment
PG02	Shock absorption in front
P3QT	3-point seat belts in front, with tensioner and height adjustment
P8S5	2 reading lights in front
P3B4	Child seat anchors for child seat system ISOFIX
P3X0	Without load-through hatch
P0K0	Without alternative drive system
P0TD	Textile floor mats
P1X1	Four-wheel drive
P20A	Without electric motor (hybrid)
P3NU	Unsplit rear seat bench, split folding backrest, with center armrest
P3T2	Three rear head restraints
P5SJ	Left exterior mirror, convex
P6Q2	Gearshift knob/handle in leather
P7K1	Tire pressure monitoring system
P7MM	Emission standard EU6
P8TB	Rear fog lamp
P8ZH	Antenna for AM/FM reception, "diversity"

PGM1	Standard electronic engine sound
PQI6	Service indicator 30 000 km or 2 years (variable)
PU5A	Instrument cluster, km/h speedometer
P0SC	Labels in English
P4L6	Breakaway interior rearview mirror, auto-dimming
P6XT	Exterior mirrors with memory feature, auto-dimming, power-folding/adjustable, separately heated
P8Q5	Dynamic headlight range control, with cornering light (AFS 1)
P8T8	Adaptive cruise control (with "follow-to-stop") and speed limiter
P9JA	Non-smoker's package
PER1	Regional code " ECE " for radio
PQJ1	Chrome package
PNZ0	Without call feature
P0ES	Installation differentiation for transmission DQ250 -- vehicle components --
P4A3	Heated front seats
P4I3	Central locking system Keyless Entry without SAFELOCK
P4V0	Without front passenger seat control
P6E3	Center armrest in front
P7L6	Start-stop system with regenerative braking
P7X5	Park assist
P8M0	Without rear window wiper and washer system
P9AK	Climatronic with impact pressure control, CFC-free
PG0R	6-speed automatic transmission for four-wheel drive
P1G8	Breakdown kit
P1Y3	Electronic differential lock XDS, dynamic traction support
P3N2	Storage box with cover in luggage compartment side panel (covers on both sides) plus cargoelement
P4E7	Electrically opening and closing tailgate/trunk lid (Tailgate/trunk lid electrically operated wo. Virtual pedal)
P4H5	Power-operated child safety lock
P6M3	Net program
P7M3	Decorative door sills front and rear
P7ZU	Vehicle class differentiation -3V0-
P8IP	Bi-Xenon headlights with AFS, with LED "DAY LIGHT" + with dynamic angle control
P8K3	"LIGHT ASSISTANT" ("COMMING HOME", "LEAVING HOME", "TUNNEL LIGHT", "DAY LIGHT")
P8SP	LED rear lights - top version
P8X1	Telescopic headlamps washers
P9IE	Mobile phone interface with W-LAN (BT interface)
P9P5	Passenger seat-belt warning light (for all passenger)

P9S6	Colour "MAXI DOT"
P9T1	Heated windscreen washer nozzles
P9TD	Warning lights in front doors and retro-reflectors in rear doors
P9VS	Sound package "branded"
PQK1	With multifunction camera
PUK3	Remote folding of rear backrest from luggage compartment
PVC0	Without garage door opener
P1A5	Fuel system for fuel-injected SI engine
P4KF	"Sunset"
P1JC	Rear shock absorption, sports version
P1LA	Disc brakes in front
P3J4	Head restraints for front seats
P2H5	"DRIVING MODE SELECT", without "DCC-DYNAMIC CHASSIS CONTROL"
P6K3	Forward collision warning incl. autonomous emergency braking, for adaptive cruise control "low"
PQR9	With dynamic road sign display
P1D4	Tow bar, swiveling
P3GA	Without variable boot floor
P4UP	Driver knee airbag with passenger airbag with switch-off
P5XH	Sun visor with make-up mirror and LED illumination and airbagschild
P6T5	Interior light in footwell in front and rear
P7Y9	"LANE ASSIST" and "BLIND SPOT DETECT"
P8G3	Advanced high-beam control
P9E3	Charging lamp in luggage compartment
P9Z3	230-V inverter and outlet for Europe
PEM1	"DRIVER ALERT" - driver alert system
P1AS	Electronic stability control (ESC)
P1KZ	Disc brakes in rear
P3G2	Preparation for child seats anchor with safety system "ISOFIX" on passenger seat
P8D5	Non-hot country plus auxiliary radiator
P9WT	"SMART LINK"
PEI9	"SMARTGATE" (AppGateway)
PPKL	"FOND PACKAGE"
PPNG	"SMART LIGHT ASSIST" with multifunction camera, "LANE ASSIST" and "BLIND SPOT DETECT"
P3PH	Power seat adjustment with memory feature for left seat, right seat manually height-adjustable
P7P7	Power-adjustable lumbar support for left front seat
P1XX	3 spoke multifunction leather steering wheel with gearbox DSG shifting (SPORTPAKET)
P3Y3	Mechanical roller sun visor for rear and side windows

P40S	Alloy wheels "VEGA" 8Jx19" anthracite polished
P4ZD	Black decorative trims
PN0X	Seat trim covers in part-leather "SportsGrain"
PUI2	External, AUX-IN jack, USB type A, 2x USB socket
P1N7	Progressive steering
P3FB	Sun roof with spoiler
PPH9	Electric sunroof PAD
PPJU	Alloy wheels "VEGA" 8Jx19" anthracite polished
PRAG	Infotainment Navigationssystem"COLUMBUS"with integrable Maps Evropa, Apple connectivity, voice control
PB05	Type approval country Finland
PX1B	Equipment options subset for Finland
PW16	SportLine Finland

История

Найденные различного типа записи истории автомобиля на временной шкале.

Обратите внимание: Информационные тексты, написанные на других языках, были переведены. Вы можете выбрать просмотр на языке оригинала.



Оригинал



2016



Сервис

2016-12 | Финляндия | 9 km

Выполненные работы:

Проверка сервиса



Сервис

2018-05 | Финляндия | 22 161 km

Выполненные работы:

Масляный сервис
неизвестная услуга



Сервис

2019-05 | Финляндия | 37 983 km

Выполненные работы:

Масляный сервис
Filters



Сервис

2020-05 | Финляндия | 52 605 km

Выполненные работы:

Масляный сервис
Filters
неизвестная услуга
Обслуживание свечей зажигания

Обслуживание тормозов
Проверка сервиса



Сервис

2020-07 |  Финляндия | 55 320 km

Выполненные работы:

неизвестная услуга



Сервис

2021-02 |  Финляндия | 62 070 km

Выполненные работы:

Масляный сервис
Filters
неизвестная услуга



Сервис

2021-07 |  Финляндия | 673 327 km

Выполненные работы:

Масляный сервис
Обслуживание тормозов



Сервис

2022-02 |  Финляндия | 76 400 km

Выполненные работы:

Проверка сервиса
Filters
неизвестная услуга
Масляный сервис



Мы не нашли никаких исторических событий с 2022-02 по 2025-04



Технический осмотр

2025-04 |  Литва | 140 206 km

Осмотр действителен до: 2026-12
Проведен технический осмотр - первичный осмотр:

без недостатков.

Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях




Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.

Ошибка ввода

2021-07

673 327 km



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.

Отлично! В данном отчете мы не обнаружили официальных записей о повреждениях или дорожно-транспортных происшествиях.

Часто это хороший знак, указывающий на то, что транспортное средство, вероятно, не участвовало в авариях или серьезных инцидентах и эксплуатировалось ответственно.



Тем не менее, важно отметить, что не все события всегда попадают в официальные базы данных. Некоторые инциденты могут быть не зафиксированы или недоступны в наших источниках информации. Данные предоставляются на основе информации от третьих лиц, поэтому их отсутствие в отчете не является гарантией того, что происшествий действительно не было.

Поэтому, как и в случае с любым подержанным автомобилем, мы рекомендуем дополнительно оценить состояние транспортного средства, поговорить с продавцом или проконсультироваться со специалистом.

Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия