

Mercedes-Benz CLA 220

Вин-номер

WDD1183441N009724

Отчет создан: 2026-02-04 13:11

Действительно: 351 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.



Марка, модель
Mercedes-Benz CLA 220



Год первой регистрации
2019



Коробка передач
Автомат



Тип топлива
Бензин



Пробег



В истории пробега не обнаружены несоответствия



Кражи



Записей не найдено



ДТП / повреждения



Найдена информация о повреждениях автомобиля



Фотографии



Исторических фотографий автомобиля не найдено.

Технические данные

(Язык оригинала)

Production date	2019-04-29
Model	CLA 220 Coupe
Series	CLA
Generation	118
Body type	COUPE
Type code	118
Engine code	INLINE 4-CYLINDER SPARK IGNITION ENGINE M260
Fuel type	Petrol

Displacement	2.00
Steering side	Left
Color	POLAR WHITE - STANDARD FINISH
Interior	Fabric/ imitation leather/ microfiber - Black/ anthracite
Transmission	automatic

Оборудование

(Язык оригинала)

149U	POLAR WHITE - STANDARD FINISH
16U	APPLE CARPLAY SMARTPHONE INTEGRATION
17U	ANDROID AUTO SMARTPHONE INTEGRATION
235	ACTIVE PARKING ASSIST
249	AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS
294	KNEEBAG
351	ECALL EMERGENCY CALL SYSTEM
362	HERMES COMMUNICATIONS MODULE LTE
475	TIRE PRESSURE MONITOR (TPM)
500	ELECTRICALLY FOLDING EXTERIOR MIRRORS
543	SUN VISOR WITH ADDITIONAL FUNCTION
810	PREMIUM SOUND SYSTEM
840	GLAS DUNKEL GETÖNT
889	KEYLESS-GO
B09	REFRIGERANT COMPRESSOR WITH MAGNETIC CLUTCH
B59	DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)
GA	AUTOMATIC TRANSMISSION
HA	REAR AXLE
P44	PARKING PACKAGE
P49	MIRROR PACKAGE
VL	LEFT FRONT AXLE HALF
VR	RIGHT FRONT AXLE HALF
287	THROUGH-LOADING FEATURE
345	RAIN SENSOR
51U	HEADLINER, BLACK FABRIC
772	AMG STYLING - FRONT SPOILER, SIDE SKIRTS
875	HEATED WINDSCREEN WASHER SYSTEM
877	AMBIENT LIGHTING
916	FUEL TANK WITH LARGE CAPACITY - VOLUME 1
B63	ENGINE SOUND VIA SPEAKERS
FC	COUPE

M20	DISPLACEMENT 2.0 LITER
U25	ILLUMINATED DOOR SILL
U26	FLOOR MATS - AMG
08U	Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)
09U	Mercedes-Benz Connect - Vehicle Monitoring (HERMES)
15U	Pre-installation for MB-Link smartphone integration
218	Rear view camera
233	Adaptive cruise control Plus (DISTRONIC PLUS)
273	Exit warning assistant
546	Automatic speed control
8U6	Assistance system steering wheel control changeover
K32	Active Lane Change Assist
K34	Route-based speed adaptation
255B	MB-Mobilo with DSB and GGD
2U8	Alternative refrigerant
429	7-speed automatic dual-clutch transmission
650A	Fabric/imitation leather/microfiber
927	Exhaust treatment, Euro 6 technology
942	Load compartment/trunk package
K13	Control code for service interval 25000 km
M013	Derated engine
U60	Pedestrian protection - Active hood
2U1	Radiator shutter
310	DOUBLE CUP HOLDER
99B	ACTIVE ADJUSTMENT DAMPING "NORMALLY OPEN"
365	HARD DRIVE NAVIGATION
3U6	HU COUNTRY SET FOR ECE/ROW
51B	RATING, COUNTRY GROUP EURO-NCAP
73B	ROLLER BLIND COMPARTMENT CLOSED
8U8	I-SIZE MARKING (ISOFIX SUCCESSOR)
98B	UPPER RADIATOR SHUTTERS
B51	TIREFIT
K31	NOISE REGULATIONS AS PER ECE R51-03
P55	NIGHT PACKAGE
U55	MULTI-LINK AXLE
1U5	RUBBER-SPRUNG STEERING GEAR
549	CONNECT 20 HIGH (NTG6)
K33	EXTENDED RESTART IN STOP-AND-GO TRAFFIC
L5C	SUPERSPORT STEERING WHEEL - LEATHER DEEP-EMBOSSSED

U19	AUGMENTED REALITY VIDEO
229L	GERMANY
2XXL	FEDERAL REPUBLIC OF GERMANY
332B	LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN
70B	SAFETY VEST - DRIVER
7U3	SEAT MODEL VARIANT 3
F118	MODEL SERIES 118
M260	INLINE 4-CYLINDER SPARK IGNITION ENGINE M260
PAC	VALUE PACKAGE
H44	TRIM ELEMENTS - LONGITUDINAL GRAIN ALUMINUM (2B45)
598	GASOLINE PARTICULATE FILTER (OPF) WITH SENSOR SYSTEM
586	LOGO PROJECTION VIA DOOR ILLUMINATION
002	CONTROL CODE FOR CHANGEOVER OF OPF FROM CORNING
JXS	PLANT CONTROL CODE
O16	SOFTWARE FRESH-UP 3
PAD	Engineering package
V76	Speed/load index 93H XI
260	Model badge on trunk lid - Omission
270	GPS aerial
299	PRE-SAFE®
580	Air-conditioning system
458	Instrument cluster display S
859	Central display size M
950	AMG line
U62	Exterior light and sight package
14U	Smartphone integration package
355	Preinstallation for retrofitting navigation system
513	Road sign recognition system
U10	Front passenger seat with weight sensor
23P	DRIVING PACKAGE
642	Dynamic LED headlamps, right-hand traffic
446	Touchpad only
873	Seat heaters for driver and front passenger
413	Automatic panoramic sliding sunroof
U59	Seat comfort package
645	M+S winter tyres, set of 4
367	Pre-installation for Live Traffic Information
459	Steel suspension with adjustable damping
U29	SPORT BRAKE SYSTEM

U01	Rear seat belt status indicator
PBF	MBUX Navigation Plus
L	LEFT-HAND DRIVE
266	DISTRONIC PLUS transverse support (DTR+Q)
RVG	AMG multi-spoke wheels 19" "all-round"
AA5	Standard power variant
059	YoM X8/2
431	Steering wheel gearshift buttons/steering wheel shift paddles - Electroplated
B10	Fuel tank packages for Euro-6D standard
01U	Mercedes-Benz Connect - Services for navigation
809	YoM X8/1
998	Control code for conversion to WLTP with RDE
628	Automatic high beam control plus (IHC+)
213	Speed-sensitive power steering / Vario steering
U35	12 V socket in load compartment
651A	Fabric/ imitation leather/ microfiber - Black/ anthracite
286	Luggage nets to left and right driver seat backrests
502	Multi-year free map updates
02B	Operating instructions and service booklet-German
969	Euro 6 technology COC document - with motor vehicle registration certificate, part 2
6P5	Control code for Sales
79B	Pre-installation for digital radio standard DAB/DMB
U22	Front lumbar support adjustment
B18	On-board xEV charging socket, NACS

История

Найденные различного типа записи истории автомобиля на временной шкале.



Обратите внимание: Информационные тексты, написанные на других языках, были переведены. Вы можете выбрать просмотр на языке оригинала.



Оригинал



2019



Сервис

2020-08 |  Германия | 12 868 km

Выполненные работы:

Замена моторного масла и фильтра



Сервис

2021-09 |  Германия | 31 511 km

Выполненные работы:

Замена моторного масла и фильтра

Замена тормозной жидкости



Сервис

2022-10 |  Литва | 43 773 km

Выполненные работы:

Замена моторного масла и фильтра

Заменен элемент воздушного фильтра

Spark plugs replaced



Несчастный случай

2023-10 |  Литва

Поврежденные компоненты:

Внешние части кузова


Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях



Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.



Важно перед оценкой ущерба:

Не все записи в отчёте означают реальный ущерб или последствия дорожно-транспортного происшествия.


Некоторые записи могут появляться не из-за самого ущерба, а вследствие оценки ущерба, расчета остаточной стоимости, процессов страховых компаний, дорогостоящих ремонтных работ, осмотров, диагностики, предпродажной оценки или других формальных процедур.

[Читать далее »](#)

Мы обнаружили **1** записей, связанных с этим транспортным средством:



Зарегистрирован ущерб



Дата

2023-10

Страна:



Литва

Прелиминарная цена ремонта

€ 501 - € 1500 

Поврежденные компоненты:

Внешние части кузова

Незначительные повреждения обычно не влияют на безопасность транспортного средства и не вызывают структурных повреждений.

Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия