



Volkswagen Transporter

Вин-номер

WV2ZZZ7HZKH145669

Отчет создан: 2025-10-27 16:59

Действительно: 272 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.



Марка, модель

Volkswagen Transporter



Коробка передач

Механическая



Год первой регистрации

2019



Тип топлива

Дизель



Объявление



Найдены записи о
продаже автомобиля



Пробег



В истории пробега не
обнаружены
несоответствия



Кражи



Записей не найдено



ДТП / повреждения



Найдена информация
о повреждениях
автомобиля



Фотографии



Найдены исторические
фотографии
автомобиля

Технические данные

(Язык оригинала)

Production date

2019-06-04

Model

Transporter WiVansw110 TDI6-s

Series

Transporter

Type code

SGB1F1

Engine code

CXFA 4-cyl. turbo diesel 2.0l/110kW(4V) TDI com.rail;b.engine
T37/T3Y/TS1/T4P/T98
TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I/T3C

Power

110

Fuel type

Diesel

Displacement	2.00
Steering side	Left
Color	Sunny Yellow/<-- special colour
Interior	Titanium Black/Titanium Black-Moon Rock Gray/Black
Transmission	manual
Transmission code	SAY

Оборудование

(Язык оригинала)

PE0A	No special edition
P4R1	Power windows
P3S0	Without roof rails/roof load rack
P1MM	Steering wheel
PEL0	Without online service
PKK3	Refrigerant R1234yf
PFM0	Basic equipment variant
P1T9	First aid kit with warning triangle and safety vest
PG0K	6-speed manual transmission
P0Y1	Standard climatic zones
P3W6	Additional interior noise suppression
P5C0	Without special body measures
P8Z5	Not hot country
P8FA	Without second battery
P8G0	Without light assistant
PQH0	Without voice control
PJ0V	Battery 420 A (70 Ah)
P0TA	Without floor mats
PF0A	No special purpose vehicle, standard equipment
PQA0	Without child seat
PIG1	Curb weight range 1
P0YD	Weight range 4 installation control only, no requirement forecast
P0FA	Standard manufacturing sequence
P3U0	Without luggage compartment cover
P2WA	Without additional tires
P1Z0	Initial standard fuel filling
P8GV	Alternator 180 A
P3CA	Without partition
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P7B0	Without socket

P0JE	Weight category front axle weight range 5
P1S2	Tool kit
P2V1	Dust and pollen filter
P0VC	Information kit in German
P8N1	Windshield wiper intermittent control
P8Y1	Two-tone horn
P9M5	Auxiliary heater
PAV1	Driving on the right
PIN0	Rear axle weight, standard
P6L0	Without C-rails
PGY0	Without power latching for tailgate
P0E1	Short wheelbase
PQL3	Heat-insulating glass (green)
P3HA	Without leather parts scope
P1L0	Standard air cleaner
P5G0	Without curtains
P1HZ	Labels without country group
P5AC	Rubber floor covering in cab
P5R2	Sliding door right in load/passenger compartment
P9NA	Without tachograph
PIM0	Front axle weight, standard
PIS0	Without interface for external use
P2Q0	Without modular seat mounting
P2QA	Nameplate set Transporter
P3LN	Unpainted door trim panel
P6CA	Without rear heating/ventilation duct
P9KA	Without identification lights
PAF0	Without stowage compartment
PNF0	Without awning
P3M9	Passenger car version with up to 9 seats
PA80	Category 19
PT13	4-cylinder diesel engine 2.0 l unit 04L.F
PZM8	9-seater package = 3-3-3
PC57	Operating permit, alteration
PZA8	Comfort package Plus
P9Z0	Operating voltage 12 V
PL0L	Left-hand drive
PQG1	LongLife Service Regime
PQV0	Without TV reception/digital radio reception

P7K1	Tire pressure monitoring system
P0SA	Without special labels
P5RQ	Right exterior mirror, convex
P7L6	Start-stop system with regenerative braking
P8TB	Rear fog lamp
P8X0	Without headlamp washer system
P1G8	Tire Mobility Set: 12-volt compressor and tire sealant
P3Y0	Without roll-up sunshade
P9ZX	Mobile phone interface
PDN4	4-cyl. turbo diesel 2.0l/110kW(4V) TDI com.rail;b.engine T37/T3Y/TS1/T4P/T98 TR1/T0P/T0N/T13/T29/TM4/TD1/TI9/T1I/T3C
PV0A	Tires without specification of tire brand
P8Q1	Headlight range control
PUG1	Hill start assist
PNZ0	Without call feature
PEM0	Without driver alert system
P1NE	Hub cap
P8WA	Without front fog lamps
P5SJ	Left exterior mirror, convex
PQI8	Service indicator 40 000 km or 2 years (variable)
P9H0	Without roof turn signals
P9LA	Without rotating beacon
P1CP	Vehicle class differentiation -7E0-
P1PA	Wheel bolts without wheel locks
P2E3	16-inch chassis with 16-inch brake system
P3R0	Standard roof (with mounting points for roof rack systems: 8 for short wheelbase, 10 for long wheelbase)
P3RC	Tailgate with window aperture
P4Y0	Without roof luggage net and lockable storage compartment
P5FA	Without additional tray areas in cab
P5V3	Hinges for rear gates/tailgate in standard design
P6B1	Lashing rings for load restraint system
P6N0	Without mud flap
P7Q0	Without navigation system
P9CU	Standard interior lights in passenger/ load compartment
P9P1	Warning buzzer and light for driver seatbelt not fastened
PNR0	Without emblems (interior)
PQJ0	Without chrome package
PX10	Equipment options subset for Central Europe

P1D1	Rigid trailer hitch (incl. trailer stabilization)
P1N1	Power steering and height and longitudinally adjustable safety steering column
P4I2	Central locking system with radio remotecontrol and interior release mechanism
P7QA	Without SD card for navigation
P4GF	Heat-insulating windshield made of laminated glass
P4H2	Child safety lock on the sliding doors in the passenger compartment
PB01	Type approval country Germany
P7H0	Without speed limiter
P1BA	Standard suspension and shock absorption
P2JB	Gray bumpers
P4L2	Dimming breakaway interior rearview mirror
P6XN	Exterior mirrors, power-adjustable and heated
P7AA	Immobilizer (electronic)
P7X1	Park Distance Control in rear
PU5A	Instrument cluster (km/h); display of speed, total/trip mileage, rpm, fuel gage and time
PK4B	Window Van
P0KT	With special decal
P1EX	Identification plate for M1 passenger car with EC type approval, with weight data, with COC
P1U0	Without table (for Multivan CL and HL w/2 sliding doors: guide rails for table available in the floor)
P1W0	Without cooling/warming box and without glove compartment cooling system
P1Y0	Without mechanical rear axle differential lock
P2A0	Transport mode activated
P2G0	Fuel tank with a volume of 70 l
P3JA	Without tilting and sliding glass sunroof in cab
P3TH	Left seat, in 1st row of seats
P3WA	Without seats, in 4th row of seats
P4A1	Seat heater for left cab seat, controllable
P4FH	Side windows, front and rear, in load/ passenger compartment, left
P4HS	Rear window made of heat-insulating glass, heated, and rear window wiper and washer system
P4JH	Side window in passenger/load compartment, right
P4UF	Driver and front passenger airbags, front passenger airbag deactivation, seat belt pretensioners for outer seats
P5K0	Transport protection measures without surface protection film
P5Q0	Without left sliding door in load/passenger compartment (closed side panel)
P5TC	Without decorative strip and decorative insert
P6K0	Without Forward Collision Warning Front Assist and without Autonomous Emergency Braking

P7V0	Dimmable dashboard illumination
P7Y0	Without lane change system Side Assist
P9WC	Without multimedia in vehicle
PGX0	Without power latching, right
PGZ0	Without power latching, left
PII0	Without cupboard
PNY0	Battery/alternator
P0WQ	Gross vehicle weight rating: 3 000 kg
P1AS	Electronic Stability Control, ABS, ASR (with deactivation button), el. diff. lock, Hill Start A., brake assist system
P2P1	Interior loading edge protection in plastic
P5XR	Sun visors with mirror and airbag label on front passenger sun visor
P8RE	4 speakers: 2 tweeters, 2 woofers
PA8B	Transporter
PN2Q	Seat trim covers in leatherette "Mesh"
PQE1	1 waste bin in door storage compartment of the cab
P5DB	Hardboard side trim panels in passenger/load compartment (medium height for vehicles w/ window apertures)
P6FA	Black exterior mirror housings and door handles
PC1G	4 steel wheels 6.5J x 16 in 20-hole style
PEU0	Without socket in front
PUI5	USB interface (also iPod/iPhone/iPad- capable)
P3J6	Height-adjustable front and rear head restraints
P4X0	Without side airbags, in front
P5CL	Comfort headliner in cab, hardboard rooftrim in passenger/load compartment
P6U0	Without additional dust seals on outside
P6X4	Grab handle as entry aid on A-pillar, ondriver and front passenger side
P8SA	Standard rear combination lamps
P9JA	Non-smoker's package (12-V outlet in dashboard)
P4E0	Tailgate latch without unlocking function from inside
P0G4	Manual transmission
P3L1	Height adjustment for left single seat in cab
P3SJ	2-seater front passenger bench, right, in 1st row of seats
P4N2	Dashboard with narrow center console and 2 beverage holders
P5N3	Folding grab handles and storage compartments on cab seats, reading light
P6KL	Radiator grille, unpainted, with 1 chrome trim
P7P5	Lumbar support for left single seat in the 1st row of seats (manually adjustable)
PZE8	Electrical package I: power windows and electrically adjustable and heated exterior mirrors
P2N3	Additional sound deadening measures in cab and passenger compartment

P9N1	step illumination in passenger/load compartment
P4S0	Without armrests on seats in the cab
P8K1	Separate daytime running light (permanently switched on during driving)
P8QL	2 remote control folding keys, 1 rigid key
P8T0	Without cruise control system
PI6V	Radio "Composition Colour" with 5-inch touch screen
PQ30	Tires 205/65 R16 C107/105T, with low rolling resistance
PB0X	Part set, complying with vehicle type for Germany, various parts
PWF2	Germany
P3VF	3-seater bench, folding and tipping, in 3rd row of seats (cannot be used in 4th row for modular seat fastening systems)
P8IA	H4 halogen headlamp
P3B5	Child seat anchor ISOFIX and top tether for Transporter/Caravelle in 2nd and 3rd row of seats
P3UE	2-seater bench on left and single seat with Easy Entry feature on right, in the 2nd row of seats
P5BC	Rubber floor covering in passenger/load compartment, with loading edge protection, in rear
PKH1	Air conditioning system Climatic in cab, 2nd heating system in passenger compartment
P9Q0	W/o multi-function display and w/o trip computer
PZU2	Rubber floor covering in passenger and load compartment
PZI4	Radio "Composition Colour"
P7CS	Emission standard Euro 6d-Temp-EVAP
PY9Z	WLTP type approval
LH1Q/	Sunny Yellow/<-- special colour

История

Найденные различного типа записи истории автомобиля на временной шкале.



2019



Несчастный случай

2020-09 |  Германия



Мы не нашли никаких исторических событий с 2020-09 по 2024-01



Технический осмотр

2024-01 |  Литва

Осмотр действителен до: 2024-07

Проведен технический осмотр - первичный осмотр:
без недостатков.



Технический осмотр

2024-01 |  Литва | 104 025 km

Осмотр действителен до: 2026-01

Проведен технический осмотр - первичный осмотр:
без недостатков.



Продажа или аукцион

2024-02 |  Литва | 104 100 km

В сети было размещено объявление о продаже данного автомобиля.



[Больше информации »](#)



Технический осмотр

2025-10 |  Литва | 106 388 km

Осмотр действителен до: 2027-10

Проведен технический осмотр - первичный осмотр:
без недостатков.


Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях



Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.



Важно перед оценкой ущерба:

Не все записи в отчёте означают реальный ущерб или последствия дорожно-транспортного происшествия.

Некоторые записи могут появляться не из-за самого ущерба, а вследствие оценки ущерба, расчета остаточной стоимости, процессов страховых компаний, дорогостоящих ремонтных работ, осмотров, диагностики, предпродажной оценки или других формальных процедур.


[Читать далее »](#)

Мы обнаружили **1** записей, связанных с этим транспортным средством:



Зарегистрирован ущерб

? МЕСТО ПОВРЕЖДЕНИЯ НЕИЗВЕСТНО



Дата

2020-09

Страна:



Германия

Пrelиминарная цена ремонта

€ 501 - € 1500 



Об этой записи:

Эта запись содержит недостаточно подробной информации для точного определения ее происхождения, однако мы предоставляем все имеющиеся данные для вашего анализа. Важно понимать, что это зафиксированная финансовая оценка, которая может означать:

- **Ремонт или модификации:** смету, составленную сервисом для плановых работ, косметического ремонта кузова или установки дополнительного оборудования (например, дисков);
- **Пропорциональную стоимость:** цены на запчасти для новых или люксовых автомобилей высоки, поэтому даже незначительный ремонт может отображаться как большая сумма;
- **Запись об ущербе:** расчет, произведенный страховой компанией после возможного дорожно-транспортного происшествия.

Мы предоставляем эту информацию как дополнительный показатель, помогающий покупателю и продавцу конструктивно обсудить прошлое автомобиля и более целенаправленно провести физический осмотр в сервисе.

Информация о продаже

Найдена информация об объявлениях автомобиля в интернете. Время продажи, изменение цены, информация о продавце.

Мы нашли **1** объявления, относящиеся к этому автомобилю:



ОБЪЯВЛЕНИЕ

Объявление неактивно

Объявление размещено

2024-02

Страна

 Литва

Пробег

104 100 km

2024-02-13



Тип продавца



Бизнес

Личность продавца

Не подтверждена

2024-02-13 |  Фотографии (21)





Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия