



Lexus

Вин-номер

JTHAABVH102002388

Отчет создан: 2025-04-02 17:37

Действительно: 21 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.

 Марка, модель
Lexus

 Коробка передач
Автомат

 Год первой регистрации
2021

 Тип топлива
Электрический



Объявление

 Найдены записи о продаже автомобиля



Пробег

 В истории пробега не обнаружены несоответствия



Кражи

 Записей не найдено



ДТП / повреждения

 Найдена информация о повреждениях автомобиля



Фотографии

 Найдены исторические фотографии автомобиля

Технические данные (Язык оригинала)

Model	UX300e
Body type	Wagon
Type code	KMA10
Engine code	4KM
Transmission	Automatic

Оборудование (Язык оригинала)

LPUG19	Luxury grade package
PFPWTT40	Protection film paint protection wax/film
FRRA17	Fr & rr stabilizer
WSCHT24	With active sound control
WBLHE26	With emergency brake lights
LTSLFN25	Led front turn signal lamp
DNRVMNH41	Day & night (auto) inside rear view mirror
TRKTEP25	Tire repair kit spare tyre
WDHN21	With windshield deicer
PUGVY20	Privacy uv back glass
WACHL29	With hill assist control (hac)
PUSGVY25	Privacy uv rear side glass
WRHO14	With roof rails
WRHB25	With (dab) satellite radio
WHS7	With abs
WPBMOSHL37	With (only p) air bag manual on-off sw
AUCERM1U50	Acm14-1 usa, can, eu, russia anti-corosion measures
WRACHL35	With (full range acc) cruise control
WALHN37	With (dynamic auto) headlamp levelling
LKAVL29	Lta+vib lane keep assist (lka)
NIGOI24	Nanoe minus ion generator
EWBHBWH32	Epb with brake hold parking brake
WDMHL30	With (color) roof drip moulding
TLS2S25	Tss 2/ lss +2 safety sense
PTTCEI38	Power tilt & telescopic steering column
WSRHA28	With traffic sign recognition
ETMCI23	Electric twin trip meter
EMFFAL29	Ethanol min. fill washer fluid
WCHR20	With wireless charger
ESDNM40	Eco/normal/sport integrated sport driving
UJ2X21	Usb*2+aux*1 audio jack
WARHO18	With front arm rest
NSMF16	Normal front seat
SLMOL27	Smooth leather seat material
WUDHA19	With head up display
ZCPPC25	Zippo 2 + card 1 key plate
WGHT20	With (with gps) clock
WCOSRLSHT57	With (without cut off switch) daytime running light system
AGGUI35	Acoustic green (uv) windshield glass

PMBK15	Pvm back monitor
WWWHA21	With rear window wiper
RTAIRSEE51	Rr tether anchor*2, iso-fix*2 child restraint system
WTHO17	With footrest type
WTTTCHC37	With package tray trim & tonneau cover
SSSOR26	Std (over sea) rear spoiler
ASSOI24	Auto + shitudo sensor a/c
WSBAHA37	With (d,p) adjustable seat belt anchor
RSIF29	Radio + sfin (tel/gps) antenna
WPHT23	With anti-chipping paint
PBDECDEA51	Power back door (w/handfree) auto & easy closer door
AMBRA29	Ahb-r brake m/cylind & booster
WCBHE32	With (kneepad, cover) console box
WHH221	With (fr:2) cup holder
WECMHA36	With e-call data communication module
BAREO18	Bynel door arm rest
WBMHO22	With door belt moulding
WCLHD32	With (led,fr2) door courtesy lamp
LIHUO23	Lexus door inside handle
MTLO14	Mould door trim
TTODR21	Tpo door trim ornament
WANSHV29	With emv and navigation system
WBHD21	With (std) floor board
WMHO13	With floor mat
WFCFLHD34	With (led fog) + cl front fog lamps
PHSE22	Passive front headrests
MVPLLP40	Maplamp(led) + vanity front personal lamp
PPSAEP38	Power (d & p 8-way) front seat adjuster
PTSBLF27	P/t+f/l, t/r front seat belt
DWBDC32	16.5" disc (hi) front wheel brake
WKLBHY23	With key, lamp glove box
WBLHD24	With (led) glove box lamp
WCHA31	With (w/washer) headlamp cleaner
WDCCHI38	With (hairline deco) i/p center cluster
WFOESHO52	With (room, foot, outhandle) illuminated entry system
WFPHN39	With (synthetic) instrument finish panel
WDLABDRHT52	With (active door lock) luggage and back door release
FRDTLI33	Full-trim luggage room & deck trim
WRLHU23	With 2 luggage room lamp

SLDAUDLEO44	Speed lock & door auto unlock power door lock
SAWAU24	4 seat auto power windows
WSHS28	With (Iss+2) pre-crash system
WARHA17	With rear arm rest
WFLHD23	With (led) rear fog lamp
UDXHGX24	Up down x3 rear headrests
SDSA425	3 seat 6:4 divid rear seat
EFSB3T35	Elr*3+outside f/l+p/t rear seat belt
WWTWDHA43	With (heavy with timer) rear window defogger
WDLMH41	With (rocker) rocker & door lower moulding
MHHLHN25	Mld hdng roof head lining
LLRM12	Led room lamp
DLRRBWAR42	D,p: lamp + reminder + rr seat belt warning
WLSHE42	With (electrical, 2way) seat lumbar support
WTSLHD31	With (led) side turn signal lamp
CAMR19	Csa (m/i) srs airbag
BEMSE25	Brushless e motor steering
VTALWSCE43	Voice, tel, acc, lda steering wheel switches
WAIPWH457	With (434mhz) autolocation tyre inflation pressure warning
WHC7	With vsc
TWDW22	Tandem windshield wiper
WAPAH46	With (driver and passenger) seat airconditioner
ETPCI30	Electric type accelerator pedal
EL321	Emv(l2)/13sp(ml) audio
WPPTH32	With (ahb-r) pvc brake pedal type
SNR14	Standard bumper
ARAPNO23	A rank cold area package
NBPDB33	Nordic, baltic destination package
ASGUI24	Acoustic front side glass
FLMALM28	For lhd model headlamp aiming
LWA3H23	Led (3) w/ ahs headlamps
WSPHI35	With stitch (wash) instrument panel
BCALE21	Bsm lane change assist
FLRLH26	Fr (w/ light) + rr register
KSE15	Km/h speedometer
COHCTO36	Center ornament (lexus, hi) wheel cap
OSMRRMREL41	Outer slide moon roof sun roof & moon roof
UC1S46	12v*1pcs+rr usb*2pcs accessory connector (n0 1)
SSEH43	Siren+shinnyu+keisha+glass anti-theft system

ESCCEM32	Eu se 7.5m battery charging cable
ATDC6T45	Ac (6.6kw, type2) + dc (50kw, chademo) charger
PFWAFLP43	Pollen&pm2. 5 filter w/deod clean air filter
DRDLSM31	D,p:2st1m, rr:1st2m dl door lock
CPOHOW41	Colour (w/o protector) door outside handle
WSASPHR35	With (fr,rr) std al door scuff plate
TRDAA36	Total ratio 11.691 front differential
WPRHO25	With front performance rod
EMIG19	Ev (side) grade mark
DCSEL27	D+ece48 light control system
PBDBDSC36	Plastic back door luggage & back door
WRKTWTTHP42	With rep. kit & tool, w/o tire luggage tray
LHSCLWO40	Led (w/o hot stamp) rear combination lamp
WPRPRHM49	With (bumper performance rod) rear performance rod
DWEWBIW33	17" disc with epb rear wheel brake
WTHU27	With (touchpad) remote touch
WCHHR34	With (d+p+rear cushion) seat heater
DPSSWP32	D:power, p:power seat side shield
ESSLKEH40	Ev (leather, std, sbw) shift lever & knob
WRIDALSHV46	With rev inhibit, d-opn autop shift lock system
LHSWTR39	Leather (w/pd, heat, stv) steering wheel
SDW5129	225/50r18 sm tire & disc wheel
Q1A16	Q711 transmission
AWCON28	Auto windshield wiper control
WCHA20	With traction control
WTIDHF30	With (7 tft) multi info display
SBNR19	Standard rear bumper
PFSAAF43	Pksa (o+v/ fr4rr4) parking support alt/brake
WIGHI33	With (hairline) door inner garnish
AHEARBPRVMOE54	Auto, ht, ec, as, rr, bsm, pvm outside rear view mirror
DLSR41	4b:w/smart (d+p+bd)+pbd wireless door lock

История

Найденные различного типа записи истории автомобиля на временной шкале.

Обратите внимание: Информационные тексты, написанные на других языках, были переведены. Вы можете выбрать просмотр на языке оригинала.

Оригинал



2021



Сервис

2021-12

Выполненные работы:

неизвестная услуга



Продажа или аукцион

2022-05 | Эстония | 12 500 km

В сети было размещено объявление о продаже данного автомобиля.



Сервис

2022-05 | 12 559 km

Выполненные работы:

Обслуживание выполнено
услуга по ремонту



Продажа или аукцион

2022-06 | Эстония | 13 000 km

Измененный пробег: 13 000 km



Несчастный случай

2023-01



Несчастный случай

2023-05



Сервис

2023-08 | 24 295 km

Выполненные работы:

Обслуживание выполнено



Сервис

2023-09

Выполненные работы:

Обслуживание программного обеспечения



Технический осмотр

2024-06 | 30 441 km

Осмотр действителен до: 2026-06

Проведен технический осмотр - повторный осмотр:

без недостатков.



Технический осмотр

2024-06 | 30 441 km

Проведен технический осмотр - первичный осмотр:

основные недостатки.



Сервис

2024-08 | 31 796 km

Выполненные работы:

Обслуживание выполнено


Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях



Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.



Важно перед оценкой ущерба:

Не все записи в отчёте означают реальный ущерб или последствия дорожно-транспортного происшествия.


Некоторые записи могут появляться не из-за самого ущерба, а вследствие оценки ущерба, расчета остаточной стоимости, процессов страховых компаний, дорогостоящих ремонтных работ, осмотров, диагностики, предпродажной оценки или других формальных процедур.

[Читать далее »](#)

Мы обнаружили **2** записей, связанных с этим транспортным средством:



Зарегистрирован ущерб



undercarriage_damage

Дата


2023-01

Прелиминарная цена ремонта

€0 - €500



Зарегистрирован ущерб



Дата

2023-05

Прелиминарная цена ремонта

€0 - €500 

Информация о продаже

Найдена информация об объявлениях автомобиля в интернете. Время продажи, изменение цены, информация о продавце.

Мы нашли **1** объявления, относящиеся к этому автомобилю:



ОБЪЯВЛЕНИЕ

Объявление неактивно

Объявление размещено:

2022-05

Страна

 Эстония

Пробег

12 500 km

2022-05-04



13 000 km


2022-06-05

Тип продавца:

Бизнес

2022-06-05 |  Фотографии (13)





Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия