

Skoda Superb

Вин-номер

TMBJJ7NP9M7017750

Отчет создан: 2025-11-12 16:31

Действительно: 253 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.

 Марка, модель
Skoda Superb

 Коробка передач
Автомат

 Год первой регистрации
2020

 Тип топлива
Дизель



Пробег

 В истории пробега не обнаружены несоответствия



Кражи

 Записей не найдено



ДТП / повреждения

 Найдена информация о повреждениях автомобиля



Фотографии

 Исторических фотографий автомобиля не найдено.

Технические данные

(Язык оригинала)

Production date	2020-09-23
Model	SUP.COM SPO TD140/2,0A7F
Series	SUP.COM
Type code	3V5R8D
Engine code	DFHA 4-cyl. turbo dies. eng. 2.0 l/140 kW 4V TDI common rail base engine is TD1/TR1/T5S/T6F
Power	140
Fuel type	Diesel

Displacement	2.00
Drive type	FWD
Steering side	Left
Color	Black Magic Pearlescent/Black Magic Pearlescent
Interior	Black-ceiling in black
Transmission	automatic
Transmission code	URW

Оборудование

(Язык оригинала)

PGP1	Vehicles with special upgrade measures
PKK3	Refrigerant R1234yf
PAV1	Driving on the right
PEV0	Without charging cable
PF0A	No special purpose vehicle, standard equipment
P0Y1	Standard climatic zones
P5K7	Transport protection film (minimum protection) with additional transport protection measures
P2WA	Without additional tires
P3ZU	3-point seat belts, outer rear with ECE label
P3FA	Without roof insert (standard roof)
P6A0	Without fire extinguisher
P1N3	Speed-related variable steering assist (Servotronic)
P0FA	Standard manufacturing sequence
P7W0	Without extended safety system
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P8N6	Windshield wiper intermittent control with light/rain sensor
P8WH	Front fog lamp and cornering lamp
P8Z5	Not hot country
PIA1	With bracket
PL07	Suspension range 07 installation control only, no requirement forecast
P0YD	Weight range 4 installation control only, no requirement forecast
P3H0	Without backrest release for front seats
P8Y1	Two-tone horn
PQH1	Voice control
PUG1	Hill hold control
PG1C	7-speed automatic transmission
P1D0	Without trailer hitch
P0F5	Fuel system for diesel engine
P3C7	3-point seat belt for center rear seat

P1SA	Without additional front underbody guard
P3W6	Additional interior noise suppression
P1JP	Rear shock absorption
P8FA	Without second battery
P6FM	Components with special surface appearance
P6M0	Without tie down straps/net/pocket
P9HA	Without additional malfunction display
P8RM	8 speakers (passive)
P2JD	Sports bumpers
P0P0	Rear exhaust tailpipe (standard)
PJ0V	Battery 420 A (70 Ah)
P1Z0	Initial standard fuel filling
P2A0	Without delivery equipment
P1S3	Tool kit
P7QA	Without CD/DVD for navigation
P5C0	Without special body measures
P8ZQ	Antenna for FM reception only, diversity
PND0	Without adapter
PEF1	ECO function
PFB0	Standard paint coating
PFM0	Basic equipment variant
PVL3	Extended and proactive pedestrian protection
P0RF	With electronic steering column lock
P9IJ	Comfort telephony with LTE and wireless charging
P3S5	Black roof rails
P4BF	Emission standard EU6 DG
P7Y1	Side Assist
P6KC	Radiator grille
P8GV	Alternator 180 A
PQQ9	Interior ambient lighting, type 2
PTR1	4-cylinder diesel engine 2.0 L unit 04L.A
PES0	Without vehicle inlet
PUH2	Parking brake
P9D0	Without preparation for two-way radio installation
P3D6	Center console
PKS0	Without head-up display
P4D0	Without seat ventilation/massage seat
P4GW	Heat insulating windshield
P7B3	12-volt socket(s)

P9TB	Additional warning lights (door area)
P5J8	Rear spoiler (type 3)
PQA0	Without child seat
PS4V	Region
P0PI	Nameplate set
PHI9	Tires 235/40 R19 96W
PUP1	Digital clock
P0M4	Fuel tank
P0B5	Wheelbase
P3LC	Door and side trim panel in foam film and woven fabric
P1PF	Standard wheel bolts
P8G4	Matrix beam
P7U0	Standard engine starter
PIG1	Curb weight range 1
PSI1	Price support
PDE5	4-cyl. turbo dies. eng. 2.0 l/140 kW 4V TDI common rail base engine is TD1/TR1/T5S/T6F
P1EX	Special identification label for EC for M1 passenger vehicles
P1NL	Trims for alloy wheels
P3GA	Without luggage/load compartment floor
P4X3	Side airbag in front with curtain airbag
P5RQ	Right exterior mirror, convex
P6N0	Without mud flap
P7AA	Electronic immobilizer
P9M0	Without auxiliary heater/parking heater
PK8D	Wagon/Avant
PL0L	Left-hand drive
PQ4H	Sports comfort seats in front
PQG1	LongLife Service Regime
PV0A	Tires without specification of tire brand
P3QT	3-point seat belts in front, with tensioner and height adjustment
P8S5	2 reading lights in front
P1X0	Front-wheel drive
P3B4	Child seat anchors for child seat system ISOFIX
P3G0	Without child seat anchora in front (ISOFIX)
P3X0	Without load-through hatch
P3Y0	Without roll-up sunshade
P8M1	Rear window wiper "AERO"
PB01	Type approval country Germany

PX0A	Equipment options subset for Germany
P0K0	Without alternative drive system
P0TD	Textile floor mats
P1Q3	Mass damper for steering wheel, XX Hz
P20A	Without electric motor (hybrid)
P3NU	Unsplit rear seat bench, split folding backrest, with center armrest
P3T2	Three rear head restraints
P5SJ	Left exterior mirror, convex
P6Q2	Gearshift knob/handle in leather
P7E6	Additional el. heating
P7K1	Tire pressure monitoring system
P8TB	Rear fog lamp
PGM1	Standard electronic engine sound
PQI6	Service indicator 30 000 km or 2 years (variable)
PU5A	Instrument cluster, km/h speedometer
P2F0	Without locking and starting systems
P3PN	Power seat adjustment for both front seats with memory feature
P4L6	Breakaway interior rearview mirror, auto-dimming
P8Q5	Dynamic headlight range control, with cornering light (AFS 1)
P8T8	Adaptive cruise control (with "follow-to-stop") and speed limiter
P9JA	Non-smoker's package
PB0A	Part set without country-specific prescriptive standard
PEL5	Remote Access / Remote Access + Online Infotainment
PER1	Regional code " ECE " for radio
PNZ2	Emergency call system eCall
PQJ1	Chrome package
PQV3	DAB - Digital radio reception
P4V0	Without front passenger seat control
P7L6	Start-stop system with regenerative braking
P7P1	Power-adjustable lumbar support in frontseats
P9AK	Climatronic with impact pressure control, CFC-free
P4UP	Driver knee airbag
P1E9	Without activated carbon canister with SCR
P1G8	Breakdown kit
P0IJ	Installation differentiation for transmission DQ381 -- vehicle components --
P3N2	Storage box with cover in luggage compartment side panel (covers on both sides) plus cargoelement
P4A4	Heated front and rear seats

P4E7	Electrically opening and closing tailgate/trunk lid (Tailgate/trunk lid electrically operated wo. Virtual pedal)
P4H5	Power-operated child safety lock
P4I3	"KESSY FULL" without "SAFE" system
P6NA	Unsplit molded headliner
P7M3	Decorative door sills front and rear
P7ZU	Vehicle class differentiation -3V0-
P8K3	"LIGHT ASSISTANT" ("COMMING HOME", "LEAVING HOME", "TUNNEL LIGHT", "DAY LIGHT")
P8X1	Telescopic headlamps washers
P9P5	Passenger seat-belt warning light (for all passenger)
P9T1	Heated windscreen washer nozzles
PKA2	"REAR VIEW CAMERA MID"
PQK1	With multifunction camera
PUK3	Remote folding of rear backrest from luggage compartment
PVC0	Without garage door opener
P3J4	Head restraints for front seats
PC60	Betriebserlaubnis Nachtrag
PG04	Shock absorption in front
PQR9	With dynamic road sign display
P5XH	Sun visor with make-up mirror and LED illumination and airbagschild
P6E7	Center armrest in front
P6K4	Forward collision warning incl. autonomous emergency braking, for adaptive cruise control "high"
P6T5	Interior light in footwell in front and rear
P9Z3	230-V inverter and outlet for Europe
PEM1	"DRIVER ALERT" - driver alert system
PPLG	"FRONT ASSIST" - adaptive cruise control to 210km/hour
P9S0	"Virtual Cockpit"
P0VC	Manual in German
P2H4	"DRIVING MODE SELECT" and "DYNAMIC CHASSIS CONTROL"
PPKV	Heated windscreen
P0SB	Labels in German
P40S	Alloy wheels "VEGA" 8Jx19" anthracite polished
P4ZD	Black decorative trims
PN0X	Seat trim covers in part-leather "SportsGrain"
P1AQ	Brake control system for vehicles without electric drive (ESC and electromechanical brake booster)
P1ZK	Disc brakes in front
P8AR	Optional infotainment system (MIB3)

PVF1	Alloy pedals
P3CX	Partition net screen
PE2G	"SportLine"
P7UG	Navi Columbus + Web Radio
PA8C	Equipment level - Ambition
PVW5	Acoustics front side windows with SunSet
P3U7	Automatical unlocking roller blind with multifunction pocket
P2EM	Disc brakes in rear
P6I6	Lane Assist with adaptive lane guidance function + Emergency Assist
P6XT	Ext. mirrors with memory feature, auto- dimming on driver's side, el.folding/ adjustable, separately heated
P8IX	Full LED TOP headlamps with Matrix Beam function incl. Welcome Effect
P8VM	TOP LED taillights
P9WJ	"SMART LINK" (drathlos für Apple)
PYOZ	Remote Access + Infotainment Online 3 years
P8QG	3 keys
P7X2	PDC with "MANOEUVRE ASSIST" - parking sensors front & rear with aut. braking
PU9C	2x USB front + 2x USB rear
P2FK	3 spoke perforated multifunction leatherSport steering wheel, heated, with DSG shifting,black stitching(grau Sportline)
P5TT	Decor moulding Sportline with ambient lighting
PPWF	Side Assist + Lane Assist with adaptive lane guidance function +Emergency Assist
PWDL	Business Columbus
LF9R/	Black Magic Pearlescent/Black Magic Pearlescent

История

Найденные различного типа записи истории автомобиля на временной шкале.

Обратите внимание: Информационные тексты, написанные на других языках, были переведены. Вы можете выбрать просмотр на языке оригинала.

Оригинал



2020



Сервис

2020-10 |  Германия | 10 km

Выполненные работы:

Осмотр при передаче.



Сервис

2021-06 |  Германия | 30 832 km

Выполненные работы:

Проверка с заменой масла.



Сервис

2022-03 |  Германия | 61 463 km

Выполненные работы:

Проверка с заменой масла.

Салонный фильтр.



Сервис

2022-10 |  Германия | 90 728 km

Выполненные работы:

Осмотр с заменой масла.

Фильтр дизельного топлива.

Элемент воздушного фильтра.

Обслуживание тормозной жидкости.



Сервис

2023-05 |  Германия | 112 892 km



Сервис

2023-07 |  Германия | 121 490 km

Выполненные работы:

Осмотр с заменой масла.
Салонный фильтр.
Масло для коробки передач.



Несчастный случай

2023-12 |  Германия | 136 500 km

Поврежденные компоненты:

Внешние части кузова
Фары



Технический осмотр

2024-08 |  Литва | 136 846 km

Осмотр действителен до: 2026-08
Проведен технический осмотр - первичный осмотр:
без недостатков.



Сервис

2024-12 |  Литва | 152 658 km

Выполненные работы:

Осмотр с заменой масла.
Обслуживание тормозной жидкости.



Сервис

2025-04 |  Литва | 167 773 km

Выполненные работы:

Осмотр с заменой масла.
Салонный фильтр.



Сервис

2025-09 |  Литва | 183 234 km

Выполненные работы:

Осмотр с заменой масла.
Фильтр дизельного топлива.
Элемент воздушного фильтра.


Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях



Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.



Важно перед оценкой ущерба:

Не все записи в отчёте означают реальный ущерб или последствия дорожно-транспортного происшествия.


Некоторые записи могут появляться не из-за самого ущерба, а вследствие оценки ущерба, расчета остаточной стоимости, процессов страховых компаний, дорогостоящих ремонтных работ, осмотров, диагностики, предпродажной оценки или других формальных процедур.

[Читать далее »](#)

Мы обнаружили **1** записей, связанных с этим транспортным средством:



Зарегистрирован ущерб



Дата

2023-12

Пробег

(136 500 km)

Страна:



Германия

Прелиминарная цена ремонта

€ 3001 - € 5000 

Поврежденные компоненты:

Внешние части кузова

Фары

Незначительные повреждения обычно не влияют на безопасность транспортного средства и не вызывают структурных повреждений.

Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия