

Toyota Corolla

Вин-номер

NMTBZ3BE80R064811

Отчет создан: 2026-01-09 11:59

Действительно: 346 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.



Марка, модель
Toyota Corolla



Коробка передач
Автомат



Год первой регистрации
2020



Тип топлива
Бензин + Электрический



Пробег



В истории пробега не обнаружены несоответствия



Кражи



Записей не найдено



ДТП / повреждения



Найдена информация о повреждениях автомобиля



Фотографии



Исторических фотографий автомобиля не найдено.

Технические данные

(Язык оригинала)

Production date	2020-10-12
Model	Corolla
Body type	Sedan
Type code	ZWE211
Engine code	1.8L (HEV special) (2ZR-FXE)
Displacement	1.80
Color	6X1
Transmission	Automatic

Оборудование

(Язык оригинала)

ISOL28	Immobilizer anti-theft system
FRGRA19	Fr2, rr2 assist grip
ECVECBK32	Ebd brake cont valve- edb control
WRDHO20	With cooler rear duct
BBMCO23	Black door belt moulding
WBLHE26	With emergency brake lights
RALCAIN38	Rh aiming (for lhd car) headlamp aiming
WACHC36	With (hac3) hill assist control (hac)
WRLHG21	With luggage room lamp
WIDHU27	With (7") multi info display
WCHARHP28	With cup holder rear arm rest
WLCAB31	Wvta label regulation compliancy
WOBPHS37	With (passenger only) seat back pocket
WOMTSLHT38	With outer mirror side turn signal lamp
WAWHL21	With asl speed warning
FRRA17	Fr & rr stabilizer
EMFFAL29	Ethanol min. fill washer fluid
WFLWHS30	With washer fluid level warning
FSBSNA38	Front+back sonar clearance & back sonar
FRHRC19	Fr:2 rr:2 cup holder
HMNN13	Hv engine mark
EERCL1E30	E5, e10 reg. fuel caution label
SPRA23	Smart-master 2 key plate
WFLHA17	With rear fog lamp
WDLSHO33	With d (power) seat lumbar support
PFAFLF29	Pollen filter clean air filter
WHB15	With (ahb-r) vsc
CASAPDE31	Cold area spec cold area package
WTRLSHD43	With (led type) daytime running light system
NSMF16	Normal front seat
WBLHO18	With glove box lamp
EBPK16	Epb parking brake
WWTWDHA43	With (heavy with timer) rear window defogger
NPDCMDP37	Needle punch trunk & deck carpet & mat
ETPCI30	Electric type accelerator pedal

CWMEW24	Camera + w/h back monitor
WDOPHA36	With (rear door only) child protector
PIHTG25	Plating door inside handle
FPRO16	Fr&rr door pocket
VXHTA26	Vertical x2 front headrests
MLUH24	Manual headlamp levelling
EMRVMIO32	Ec mirror inside rear view mirror
WRWHT34	With (autocut) light remind warning
WDLHW19	With power door lock
PTLSA22	Personal type room lamp
WKTHT30	Without (repair kit) spare tyre
PSSHT32	Push (with smart) starting system
PMLVDI33	Pvc (d&p mirror + light) sun visor
AMOA19	Auto (dual mode) a/c
WHS7	With abs
CBCSE37	Console box accessory connector (n0 1)
PSWIBMOSAI45	P seat with indicator air bag manual on-off sw
TDD620	T1 (8") dab 6sp audio
AMIE18	Audio + meter clock
WHHA13	With coat hook
RBIO16	Resin console box
FARRD19	Fabric door arm rest
RSPTOIA39	Resin + satin plating door trim ornament
SWDTPDGW51	Single without diffuser exhaust tail pipe & diffuser
WPLHL30	With (bulb) front personal lamp
DMSSMP32	260mm d&p manual front seat slide
GSGE025	Green 70% front side glass
SPBCCIL43	Satin plating/piano black i/p center cluster
WMLESHO46	With (room + map lamp) illuminated entry system
SWSPTT38	Soft w/ stitch (p-pad) instrument panel
AFPCSF340	Alc + fmh 3 position light control system
FROTUHWARN43	Fr & rr 4 one touch up/down hi power windows
FWSWSPCBWT45	Fab w/o stitch w/ slide p-blk rear console box
SFSPT23	6:4 split fold rear seat
PSGVY26	Privacy 20% rear side glass
TS2F16	Tss2 safety sense
FRLBWRZ40	Fr & rr (buzzer + lamp) seat belt warning
WCBHHC36	With (d+p cushion & back) seat heater
FBMMRB25	Fabric b mid seat material

WSPPBHBHT48	With satin plating + p-blk bezel shift lever boot
WPIHT36	With (meter) shift position indicator
DSHCKANH40	D&p sngl hi+sd (fr) + csa + kn srs airbag
TTCTL32	Tilt & telescopic steering column
WOL36	3-spoke,leather,heater steering wheel
DTVAAALWSPE71	Disp (h) + tel + voice + audio + acc + asl + lda steering wheel switches
COACTO36	Centre ornament (for alumi) wheel cap
LGAGIT38	Laminated green 70% ac windshield glass
ESPE17	Eps power steering
CBCSE38	Console box1 accessory connector (n0 2)
RWSIO23	Rr window + sfin antenna
WUJBD16	W/ usb audio jack
L3H15	Ln1 36ah battery
RSIPSOIO38	Radiator sp + id plate + sash black out
AMBRA29	Ahb-r brake m/cylind & booster
PCOU15	Pp colour bumper
ITTRSZO42	Isze + top tether*2 child restraint system
WRACHL35	With (full range acc) cruise control
WECMHA36	With e-call data communication module
BDWKPOHYL45	Bodycolour d: w/ key p:w/o door outside handle
WSPHO20	With door scuff plate
FHWNFTRR33	Fr&rr: hard with nv felt door trim
PWFTG24	Plating door window frame
TDMGD22	Toggle dms 3 drive mode
WAMUCPHT58	With (without acoustic mat) engine under cover & protection
ETWOECOT44	Euro6d temp with obd exhaust emission control
FSRLIS35	Fr (with silencer) & rr fender liner
TFHMF227	Tex fm 520g hybrid floor mat
DHPFCAMOW48	Dilour (with heel pad) front floor carpet and mat
WMBSFLHD44	With (led + mat blk + silver) front fog lamps
DPFSBEP37	D,p: 3elr + pt + f/l*2 front seat belt
DMSVAAA42	D: 2way manual front seat vertical adjuster
DWBIB30	15" disc (b) front wheel brake
BTWLBTE26	Bin type w/o lock glove box
ADSCPOA37	Auto dual + satin heater control panel
WPUCHI26	With (d, p) i/p under cover
APMCSFPPIA66	Audio panel & meter cluster satin (plating) instrument finish panel
WBABDGHA46	With (plating) lower back and back door garnish
CELABDRLL46	Cable + elec lock luggage and back door release

SFRFRDTET55	Side (with felt) + rr + 1con fk luggage room & deck trim
WTHG16	With luggage tray
WMAHC25	With (ohc) mike & mike amp
EOA8	Euro ncap
WSSWHCHT50	With (with sos sw, without holder) overhead console
MOPK19	Mid package option 3
GFWFLTTTCSI57	Glass fiber with felt lo package tray trim & tonneau cover
WWTPWHA39	With wrap type paint protection wax/film
BPPGCA36	Black paint + plating radiator grille
MBLGEA35	Material black radiator lower grille
PPCBAT25	Pp paint color rear bumper
VFHTA34	Vertical*2 + fixed*1 rear headrests
SBRF33	3elr-pt-fl*2 3elr*1 rear seat belt
FRSRT22	Fr & rr: satin register
SWPTAH33	Straight w/o paddle switch tronics
ADW5131	205/55r16 al-1 tire & disc wheel
WCSRHM35	With camera traffic sign recognition
WDIPWH351	With (433mhz) direct tyre inflation pressure warning
SELDLRN34	Smart entry less wireless door lock
AFEHRVMOL47	Auto fold, elec, heater outside rear view mirror
PHHHT34	Ptc heater (600w) additional heater
ASWCOI42	Auto (rain sensor) windshield wiper control
PGVY21	Privacy 20% back glass
BPLAEE25	Bi pes led + ahb headlamps
WPMSLHD45	With (led/cabin), privacy high mount stop lamp
LMLCLSP55	Led (stop/turn) + multi led (tail) rear combination lamp
KRRI23	Km/h + resin speedometer
SURPC034	Spec 1 (20mm up) rough road package
WKAHA32	With (lta) lane keep assist (lka)
LLKTR31	Leather (cvt) shift lever & knob

История

Найденные различного типа записи истории автомобиля на временной шкале.



Обратите внимание: Информационные тексты, написанные на других языках, были переведены. Вы можете выбрать просмотр на языке оригинала.



Оригинал



2020



Несчастный случай

2020-12 |  Литва

Поврежденные компоненты:
Внешние части кузова



Сервис

2021-12 | 12 902 km

Выполненные работы:
ННС.



Несчастный случай

2022-01

Поврежденные компоненты:
Внешние части кузова



Сервис

2022-12 | 23 065 km

Выполненные работы:
ННС.



Сервис

2023-12 | 31 199 km

Выполненные работы:

ННС.



Несчастный случай

2024-06 |  Литва

Поврежденные компоненты:

Structural elements of the body

Внешние части кузова

Фары


Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях



Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.



Важно перед оценкой ущерба:

Не все записи в отчёте означают реальный ущерб или последствия дорожно-транспортного происшествия.


Некоторые записи могут появляться не из-за самого ущерба, а вследствие оценки ущерба, расчета остаточной стоимости, процессов страховых компаний, дорогостоящих ремонтных работ, осмотров, диагностики, предпродажной оценки или других формальных процедур.

[Читать далее »](#)

Мы обнаружили **3** записей, связанных с этим транспортным средством:



Зарегистрирован ущерб



Дата

2020-12

Страна:



Литва

Прелиминарная цена ремонта

€ 501 - € 1500 


Поврежденные компоненты:

Внешние части кузова

Незначительные повреждения обычно не влияют на безопасность транспортного средства и не вызывают структурных повреждений.



Зарегистрирован ущерб



Дата

2022-01

Пrelиминарная цена ремонта

€ 501 - € 1500 


Поврежденные компоненты:

Внешние части кузова

Незначительные повреждения обычно не влияют на безопасность транспортного средства и не вызывают структурных повреждений.



Зарегистрирован ущерб



Дата

2024-06

Страна:



Литва

Прелиминарная цена ремонта

€ 5001 - € 10000 [i](#)

Поврежденные компоненты:

Structural elements of the body

Внешние части кузова

Фары

Незначительные повреждения обычно не влияют на безопасность транспортного средства и не вызывают структурных повреждений.

Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия