

Volkswagen Arteon

Вин-номер

WVWZZZ3HZJE501783

Отчет создан: 2026-01-15 11:57

Действительно: 352 д.

Информация

Предоставляются основные данные проверяемого автомобиля и краткая информация о проведенных проверках.



Марка, модель
Volkswagen Arteon



Коробка передач
Автомат



Год первой регистрации
2017



Тип топлива
Дизель



Пробег



В истории пробега не обнаружены несоответствия



Кражи



Записей не найдено



Фотографии



Исторических фотографий автомобиля не найдено.

Технические данные (Язык оригинала)

Production date	2017-06-20
Model	Arteon RLine 176 TDID7A
Series	Arteon
Type code	3H749T
Engine code	CUAA 4-cylinder diesel engine 2.0 I TDI, 176 kW
Power	176
Fuel type	Diesel
Displacement	2.00
Steering side	Left
Color	Oryx White Mother-of-Pearl Effect/Oryx White Mother-of-Pearl Effect
Interior	Black-Titanium Black/Titanium Black/ Titanium Black
Transmission	automatic
Transmission code	RWU

Оборудование

PE0A	No special edition
P0F5	Fuel system for diesel engine
P1SA	Without additional front underbody guard
P0Y3	Cold zones
P2JX	Comfort bumpers
PKK3	Refrigerant R1234yf
P3LJ	Door and side trim panel in foam film, insert in leatherette
PKS0	Without head-up display
PFN7	Variant
P3FA	Without roof insert (standard roof)
P3W6	Additional interior noise suppression
P4D0	Without seat ventilation/massage seat
P5C0	Without special body measures
P7ZS	Vehicle class differentiation -3H0-
P7MM	Emission standard EU6 plus
P8FC	Installation of SLI battery in rear, without second battery
PQH0	Without voice control
PEF1	ECO function
PFC1	Customized installation
PF0A	No special purpose vehicle, standard equipment
PS0C	Introductory volume
PQA0	Without child seat
P0FA	Standard manufacturing sequence
P5K7	Transport protection film (minimum protection) with additional transport protection measures
P1S1	Tool kit and jack
P2WA	Without additional tires
P7G0	Without preparation for VTS (vehicle tracking system)
P8GV	Alternator 180 A
P3H0	Without backrest release for front seats
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
PL47	Suspension range 47 installation control only, no requirement forecast
P6A0	Without fire extinguisher
P0YG	Weight range 7 installation control only, no requirement forecast
P1JP	Rear shock absorption
P0VV	Information kit in Swedish
P0P0	Rear exhaust tailpipe (standard)
P8Y1	Two-tone horn

PC01	Operating permit, alteration
PEV0	Without charging cable
PAV1	Driving on the right
PSV3	Control (in-plant)
PNY0	Standard battery/alternator capacity
PES0	Without vehicle inlet
P1Z2	Increase in initial standard fuel filling
P2A0	Without delivery equipment
P7U0	Standard engine starter
P9D0	Without preparation for two-way radio installation
P1Q2	Mass damper for steering wheel, 36 Hz
PA62	Category 2
P0M4	Fuel tank
PPW9	Parking heater and ventilation with radio remote control and timer
P0B5	Wheelbase
PTS3	4-cylinder diesel engine 2.0 l
P1X1	Four-wheel drive
P4ZB	Chrome moldings on the side windows
P7L6	Start-stop system with generative braking
P8G0	Without light control
P8RM	8 speakers
P8X1	Headlamp washer system
PA8F	Sports equipment
PEM1	Driver alert system
PG1D	7-speed automatic or DSG for four-wheel drive note: family EDF
PL0L	Left-hand drive
PQG1	LongLife Service Regime
PQI6	Service indicator 30 000 km or 2 years (variable)
PQV0	Without TV reception/digital radio reception
P6Q2	Gearshift knob in leather
P7K1	Tire pressure monitoring system
P0K0	Without alternative drive system
P0NB	Elimination of nameplate for engine designation on luggage compartment lid
P1AT	Electronic Stability Control w/ driver steering recommendation, ABS, ASR, EDL, EDTC and trailer stabilization
P1E9	Without activated carbon canister with SCR
P1NL	Trims for alloy wheels
P1PE	Wheel locks with extended theft protection
P20A	Without electric motor (hybrid)

P31K	License plate carrier in front and rear (ECE)
P3QT	3-point seat belts in front with height adjustment and seat belt pretensioners
P3T2	3 head restraints in rear
P4A4	Heated front and outer rear seats
P4L6	Auto-dimming interior rearview mirror
P4X3	Curtain airbag system for front and rear passengers incl. side airbags in front
P5RQ	Right exterior mirror, convex
P5SL	Aspherical exterior mirror on driver side
P5XJ	Illuminated vanity mirrors in sun visors
P7X5	Park Assist with Park Distance Control
P8N6	Rain sensor
P8T8	Adaptive Cruise Control ACC stop & go incl. speed limiter
P8TB	Rear fog lamp
P9T1	Automatically-heated washer nozzles in front
PQK1	Multifunction camera
PUH2	Electromechanical parking brake with Auto Hold function
P0SC	Labels in English
P0TE	Carpet mats in front and rear with decorative stitching
P1G8	Tire Mobility Set: 12-volt compressor and tire sealant
P1N7	Progressive steering
P1Y3	Electronic differential lock XDS
P2I0	Adaptive Chassis Control DCC
P3D3	Decorative inserts "Piano Black" for center console
P3GA	Luggage compartment floor
P3KB	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest and load-through hatch
P3U1	Luggage compartment cover
P3Y0	Without roll-up sunshade
P4B4	Lower side trims in chrome
P4GF	Heat-insulating windshield
P4UN	Driver and front passenger airbag with front passenger airbag deactivation, including knee airbag on driver side
P4V0	Without front passenger seat control
P5I6	Easy Open - sensor controlled luggage compartment opening and delayed electric closing, with remote unlocking
P6SE	Textile luggage compartment trim
P6T1	2 LED light units in front footwell
P7B6	12-V outlet in center console in rear
P7E0	Without heat accumulator/auxiliary heater

P8IU	LED headlamps for low beam and high beam, with LED separate daytime running light and dynamic cornering light
P8K3	Aut. headlight control w/ separate daytime running light, Leaving Home and manual Coming Home feature
P8Q5	Dynamic headlight range control, with dynamic cornering light
P8S7	Interior lights with switch-off delay and dimmer, 2 LED reading lights each in front and rear
P8SH	LED rear combination lamps, with dynamic turn signal
P8WM	Cornering light and poor weather light
P9P9	Warning signal and warning light for front and rear seat belts not fastened
P9S8	Multi-color Active Info Display, selection of different info profiles possible
P9TJ	LED entry/warning lights in front doors
PGM1	Standard electronic engine sound
PGP0	Vehicles without special upgrade measures
PI8F	Radio "Composition Media"
PK8C	Coupe
PPA6	Ambient lighting
PQJ3	Chrome elements on door pulls, on the rotary light switch and on the front vents
PQQ9	Ambient lighting (three-color)
PUG6	Hill Start Assist
PUP0	Analog clock in dashboard
PVC0	Without garage door opener
PVF1	Pedals in brushed stainless steel
PVL4	Pedestrian monitoring and re-active hood
PWLH	LED headlamps
P5ZF	Safety-optimized front head restraints
PKA2	Rear view camera system
P7P7	Lumbar supports in front, power-adjustable on driver side
PV0A	Tires without specification of tire brand
P7W2	Proactive passenger protection system in combination with Front Assist
P7UF	Navigation system "Discover Media" with TFT touch screen
PUQ2	2 USB interfaces, also for iPod/iPhone, 1 USB charging socket and AUX-IN jack
PU5A	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
P0EX	Dual-clutch transmission DSG DQ500
P3ZU	3-point seat belts in rear incl. seat belt pretensioner for the outer seats
PQ4H	Top comfort seats, in front
PSX8	Model update, week 22
P9JA	Non-smoker's package: 12-V outlet in front
P3A0	ISOFIX anchorage points for mounting 2 child seats on rear seats, also for i-Size child seats

P9WX	App-Connect and "Volkswagen Media Control"
PJ0B	Battery 520 A (92 Ah)
PQ48	AirStop® tires 245/40 R19
PKH7	Air Care Climatronic 3 zone automatic climate control with allergen filter and controls in the rear
PG12	Shock absorption in front
P4F2	Keyless locking and starting system Keyless Access with SAFELOCK
P7AL	Anti-theft alarm system with interior monitoring, backup horn, and towing protection
P1EX	Special identification label for EC for M1 passenger vehicles
PER1	Regional code " ECE " for radio
P1T3	First aid kit and warning triangle
P1LA	Disc brakes in front
P2PK	R-Line leather-wrapped multi-function sports steering wheel, with shifting paddles
P1KZ	Disc brakes in rear
P5TE	Decorative inserts in aluminum "Silver Rise" for dashboard and door trim panels
P6NW	Titanium Black headliner
P6K4	Forward Collision Warning Front Assist Autonomous Emergency Braking (for Adapt.Cruise Control ACC up to 210 km/h)
P7RE	Navigation data for Western Europe on SD card
PPND	Navigation feature "Discover Media" (for "Composition Media")
P1M6	Folding trailer hitch, with electric release
P3PW	Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment
P8ZQ	Diversity antenna for FM reception
P9ZE	Mobile phone interface "Comfort"
P6XI	Ext. mirror w/ surround lighting a. fr. passenger ext. mirror lowering funct., folding/heated, auto-dimming on dr. side
PPEL	Easy Open package incl. SAFELOCK
PQR9	Dynamic Road Sign Display
PEL5	Online service, with OCU, with head unit coding, without engine immobilizer interconnection
P45T	4 alloy wheels "Montevideo" 8J x 19, black, diamond-turned surface
P6E3	Front center armrest with storage compartment, 2 rear vents
P7M9	Scuff plates w/ stainless steel inserts and "R-Line" logo
PPJW	Montevideo 8J x 19, Black, diamond-turned surface, Volkswagen R, AirStop® tires 245/40 R19
PW12	VE: NCAP package
PW17	VE: Lights & Vision package, LED High without high-beam control Light Assist
PWD5	Anti-theft alarm system
PWQ3	Dynamic Road Sign Display in combination with driver assistance package or "Business Premium" package

PNZ4	Emergency call service, contract dur. 10 years; no registration required, service is activated upon delivery
PPAP	Acoustics package
P9M9	Parking heater and ventilation with radio remote control and timer
PB07	Type approval country Sweden
PX1D	Equipment options subset for Sweden
P8D5	Non-hot country plus auxiliary radiator
P9Z3	230-V outlet in center console in rear
P79D	Emergency Assist, Traffic Jam Assist, Rear Traffic Alert, Side Assist Plus incl. Lane Assist
PN7N	Inserts in Alcantara, inner sides of bolsters in leather "Vienna"
PYOZ	Guide & Inform and Security & Service Plus, contr.dur.:3 years incl. Security & Service Basic,contr. dur. 10 years
PPTO	Mobile phone interface "Comfort"
PPW3	Winter package for leather package
PB0H	Part set, complying with vehicle type for Sweden, various parts
PDK9	4-cylinder diesel engine 2.0 l TDI, 176 kW
PVW5	Sound-insulating windows in laminated safety glass, 65% light-absorbing glass in rear window and rear side windows
PW50	SE: Load package forces 1M6, KA2
PW52	SE: Executive package Elegance forces WLH,WL6,PA6 2ZD,PEL,5MD R-Line forces WLH,PA6,PEL,5TE
L0K1/	Oryx White Mother-of-Pearl Effect/Oryx White Mother-of-Pearl Effect

История

Найденные различного типа записи истории автомобиля на временной шкале.



Обратите внимание: Информационные тексты, написанные на других языках, были переведены. Вы можете выбрать просмотр на языке оригинала.



Оригинал



2017



Предварительная
проверка регистрации

2017-08 |  Швеция



Смена владельца

2017-08 |  Швеция



Смена владельца

2017-09 |  Швеция



Первая регистрация

2017-09 |  Швеция



Смена владельца

2018-10 |  Швеция



Сервис

2019-01 |  Швеция | 24 942 km



Сервис

2019-01 |  Швеция | 27 454 km

Выполненные работы:

Проверка с заменой масла (гибкая).



Смена владельца

2019-05 |  Швеция



Сервис

2020-03 |  Швеция | 55 385 km



Технический осмотр

2020-08 |  Швеция | 63 997 km



Технический осмотр

2020-08 |  Швеция | 64 235 km



Технический осмотр

2022-06 |  Швеция | 95 994 km



Смена владельца

2022-12 |  Швеция



Смена владельца

2023-04 |  Швеция



Снятие с учета (временное или постоянное)

2023-08 |  Швеция



Сервис

2024-07 |  Литва | 134 620 km

Выполненные работы:

Проверка с заменой масла (гибкая).
Обслуживание тормозной жидкости.
Масло для коробки передач.
Фильтр дизельного топлива.
Салонный фильтр.
Элемент воздушного фильтра.
Масло для муфты полного привода.
Объем дополнительной проверки.


Пробег

Из различных источников собраны данные о фиксированном пробеге автомобиля и его изменениях



Инсайт Autoistorija.lt:

Наши данные поступают из различных официальных источников, но мы всё равно рекомендуем провести профессиональный осмотр автомобиля со специалистами.



ДТП/повреждения

Данные о зафиксированных ДТП/ущербах собраны из различных источников.

Отлично! В данном отчете мы не обнаружили официальных записей о повреждениях или дорожно-транспортных происшествиях.

Часто это хороший знак, указывающий на то, что транспортное средство, вероятно, не участвовало в авариях или серьезных инцидентах и эксплуатировалось ответственно.



Тем не менее, важно отметить, что не все события всегда попадают в официальные базы данных. Некоторые инциденты могут быть не зафиксированы или недоступны в наших источниках информации. Данные предоставляются на основе информации от третьих лиц, поэтому их отсутствие в отчете не является гарантией того, что происшествий действительно не было.

Поэтому, как и в случае с любым поддержанным автомобилем, мы рекомендуем дополнительно оценить состояние транспортного средства, поговорить с продавцом или проконсультироваться со специалистом.

Проверка угона

Информация из полицейских и других баз данных о том, находится ли машина в розыске.



Мы не нашли никаких записей о том, что транспортное средство числится в угоне.

Поиск записей о возможных угонах транспортного средства проводился в базах данных следующих стран:



Литва



Словения



Словакия



Чехия



Венгрия



Италия



Румыния



Германия